

AD-A054 693


ARINC RESEARCH CORP ANNAPOLIS MD
COST-EFFECTIVENESS COMPARISON OF SHIPBOARD TELEGRAPH TERMINAL E--ETC(U)
NOV 67 M Y RAWASIA, E B BELL, C W DUKE
553-01-1-849

F/G 17/2
N00024-67-C-1182
NL

UNCLASSIFIED

1 OF 2
ADA
054693





FOR FURTHER TRAN Publication 553 1-1-849

(4)

**COST-EFFECTIVENESS COMPARISON
OF SHIPBOARD TELEGRAPH TERMINAL EQUIPMENTS
AN/UCC-1C(V) AND AN/UCC-1(V)**

November 1967

Prepared for
NAVAL SHIP ENGINEERING CENTER
COMMAND AND SURVEILLANCE DIVISION
Code 6181
Under Contract N00024-67-C-1182

DDC
JUN 6 1978
F

AU NO. _____
DDC FILE COPY

AD A 054693

ARINC RESEARCH CORPORATION

This document has been approved
for public release and sale; its
distribution is unlimited.

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER 553-01-1-849✓	2. GOVT ACCESSION NO.	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) COST-EFFECTIVENESS COMPARISON OF SHIPBOARD TELEGRAPH TERMINAL EQUIPMENTS		5. TYPE OF REPORT & PERIOD COVERED
7. AUTHOR(s) M.Y. Rawasia E.B. Bell C.W. Duke		6. PERFORMING ORG. REPORT NUMBER 553-01-1-849
9. PERFORMING ORGANIZATION NAME AND ADDRESS ARINC Research Corporation ✓ 2551 Riva Road Annapolis, Maryland 21401		8. CONTRACT OR GRANT NUMBER(s) N00024-67-C-1182 ^{new}
11. CONTROLLING OFFICE NAME AND ADDRESS NAVAL SHIP ENGINEERING CENTER COMMAND AND SURVEILLANCE DIVISION		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office) NAVAL SHIP ENGINEERING CENTER COMMAND AND SURVEILLANCE DIVISION		12. REPORT DATE November 1967
		13. NUMBER OF PAGES 73
		15. SECURITY CLASS. (of this report) UNCLASSIFIED
16. DISTRIBUTION STATEMENT (of this Report) UNCLASSIFIED/UNLIMITED		15a. DECLASSIFICATION/DOWNGRADING SCHEDULE
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)		
18. SUPPLEMENTARY NOTES		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number)		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) A shipboard surveillance and an engineering analysis were performed by ARINC Research Corporation to compare the cost-effectiveness of the microelectronic AN/UCC-1C teletype-communication terminal equipment with that of the AN/UCC-1 transistorized terminal equipment. The data employed included those obtained from observations made aboard the USS Topeka (CLG-8) and the USS Cavalier (APA-37), data extracted from the Navy Maintenance Data Collection System (MDCS), and procurement-cost data. Insufficient data were available to identify any difference in effect-		

DD FORM 1 JAN 73 1473

EDITION OF 1 NOV 65 IS OBSOLETE

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE(When Data Entered)

iveness between the UCC-1C and the UCC-1 terminal equipments. However, there was a reduction in cost in the UCC-1C.

The report identifies reliability problems of the teletype- communication system and recommends actions to correct them.

NO0004-07-0-1188

M.Y. Ravasala
E.H. Bell
G.W. Duke

AMIC Research Corporation
2521 River Road
Annapolis, Maryland 21401

November 1967

NAVAL SHIP ENGINEERING CENTER
COMMAND AND SURVEILLANCE DIVISION

UNCLASSIFIED

NAVAL SHIP ENGINEERING CENTER
COMMAND AND SURVEILLANCE DIVISION

UNCLASSIFIED/RELEASABLE

A shipboard surveillance and an engineering analysis were performed by AMIC Research Corporation to compare the cost-effectiveness of the micro- electronic AN/UCC-1C teletype-communication terminal equipment with that of the AN/UCC-1 transistORIZED terminal equipment.
The data employed included those obtained from operations made aboard the USS Togo (CIC-8) and the USS Cavalier (APA-37), data extracted from the Navy Maintenance Data Collection System (MDCS), and procurement-cost data. Insufficient data were available to identify any difference in effect-

UNCLASSIFIED

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE(When Data Entered)


⑥ COST-EFFECTIVENESS COMPARISON
OF SHIPBOARD TELEGRAPH TERMINAL EQUIPMENTS.
AN/UCC-1C(V) AND AN/UCC-1(V) ④

⑪ Nov 67

⑫ 130p.

Prepared for
Naval Ship Engineering Center
Command and Surveillance Division
Code 6181
Under Contract N00024-67-C-1182

⑬ 111



⑩ By

M. Y. Rawasia,
E. B. Bell
C. W. Duke

ARINC Research Corporation
a Subsidiary of Aeronautical Radio, Inc.
2551 Riva Road
Annapolis, Maryland 21401
Publication 553-01-1-849

⑭
This document has been approved
for public release and sale; its
distribution is unlimited.

400 247

401

© 1967 ARINC Research Corporation

Prepared under Contract N00024-67-C-1182
which grants to the U.S. Government a license
to use any material in this publication for
Government purposes.

ABSTRACT

A shipboard surveillance and an engineering analysis were performed by ARINC Research Corporation to compare the cost-effectiveness of the microelectronic AN/UCC-1C teletype-communication terminal equipment with that of the AN/UCC-1 transistorized terminal equipment.

The data employed included those obtained from observations made aboard the USS Topeka (CLG-8) and the USS Cavalier (APA-37), data extracted from the Navy Maintenance Data Collection System (MDCS), and procurement-cost data.

Insufficient data were available to identify any difference in effectiveness between the UCC-1C and the UCC-1 terminal equipments. However, there was a reduction in cost in the UCC-1C.

The report identifies reliability problems of the teletype-communication system and recommends actions to correct them.

ACCESSION for	
NTIS	White Section <input checked="" type="checkbox"/>
DDC	Buff Section <input type="checkbox"/>
UNANNOUNCED	<input type="checkbox"/>
JUSTIFICATION	
BY	
DISTRIBUTION/AVAILABILITY CODES	
Dist.	INT. NAT. or SPECIAL
<input checked="" type="checkbox"/>	<input type="checkbox"/>

SUMMARY

The objective of this study was to compare the effectiveness of the AN/UCC-1C with that of a conventional transistorized telegraph terminal (AN/UCC-1). The study comprised four tasks:

- (1) Shipboard Surveillance
- (2) Data Collection
- (3) Cost-Effectiveness Analysis
- (4) System Analysis of Overall Communication Network

The major difference between the UCC-1C and the UCC-1 is that the UCC-1 employs transistors in the circuits, while the UCC-1C employs microelectronic integrated circuits. Table S-1 compares components used in the UCC-1C and UCC-1 terminal equipment. In the converters the number of active elements decreased from 35 (14 transistors and 21 diodes) in the UCC-1 to 29 (4 integrated circuits, 6 transistors, and 19 diodes) in the UCC-1C. The number of active elements in the keyers increased, but these elements were added deliberately to provide better frequency stability in the transmit function.

TABLE S-1						
COMPARISON OF QUANTITIES OF SEMICONDUCTORS USED IN AN/UCC-1C AND AN/UCC-1						
Number of Semiconductors Used						
AN/UCC-1			AN/UCC-1C			
Type of Module	Transistors	Diodes	Integrated Circuits		Transistors	Diodes
			Number of IE Circuits	Number of Active Transistors In IE Circuits		
Keyer	5	5	10	92	2	16
Converter	14	21	4	20	6	19
Control Attenuator	0	0	2	10	2	5
Test Set	7	8	10	102	4	73

Shipboard surveillance was conducted by ARINC Research monitors aboard the USS Topeka from 17 April through 11 August 1967 and aboard the USS Cavalier from 26 June through 18 September, 1967.

A total of 2800 operating hours were accumulated on the UCC-1C and UCC-1 equipments aboard the USS Topeka and a total of 1100 operating hours were accumulated on the UCC-1C equipment aboard the USS Cavalier. During the entire surveillance period only 2 malfunctions were observed, both of which occurred aboard the USS Topeka. Both malfunctions were similar, one occurring on the UCC-1C and the other on the UCC-1, and required minor adjustments to correct. Based on the maintenance actions (which required 45 minutes and 2 hours, 15 minutes to correct, respectively) the intrinsic availability for both equipments was computed as approximately 1.0.

An analysis of Maintenance Data Collection System (MDCS) operational reports was also conducted to substantiate the shipboard surveillance observations. The MDCS program used in the analysis covered the 15-month period between 1 April 1966 and 30 June 1967 and contained reported events from 75 ships. The results obtained from the analysis are shown in Tables S-2 and S-3. Table S-2 summarizes the maintenance events and corresponding man-hours, including the events and man-hours that could be associated with the installation of the terminal equipments. Since installation activity does not represent malfunctioning of the equipment, nor does it provide an indication of the operational reliability of the equipment, these events and man-hours were subtracted and the results tabulated in Table S-3.

TABLE S-2				
SUMMARY OF MDCS MAINTENANCE DATA				
Equipment Identification	Total Number Reports	Total Number Events	Total Man-Hours Expended	Number of Ships*
AN/UCC-1	193	110	2012.0	35
AN/UCC-1C	147	108	736.5	46
* Nine ships were identified as having both equipments.				

TABLE S-3					
SUMMARY OF MDCS MAINTENANCE DATA EXCLUDING INSTALLATION ACTIVITY					
Equipment Identification	Total Number Events	Total Man-Hours Expended	Average Man-Hours Per Event	Man-Hour Range	
				Maximum Per Event	Minimum Per Event
AN/UCC-1	106	546.6	5.2	116.8	0.1
AN/UCC-1C	105	545.0	5.2	34.0	0.2

The analysis of the MDCS shows no appreciable difference in the maintenance support required for the two terminal equipments. Also, in view of the length of the period (15 months) for which data were provided, the number of events reported, and the man-hours expended for a population of 75 ships, both equipments appear to be operationally satisfactory.

COST ANALYSIS

The results of the cost analysis showed that, with the exception of procurement costs, the costs of installation and ownership of both systems were the same. The acquisition cost data showed a significant reduction in the cost of procuring the UCC-1C.

Figure S-1 reveals that the cost of UCC-1C converters becomes fairly constant when 50 or more cabinets are bought and increases rapidly when fewer than 50 are purchased. The curve representing the UCC-1 converter costs follows a trend similar to that of the UCC-1C. It appears that the cost levels out when approximately 60 or more are bought. The costs increase rapidly when fewer than 60 cabinets are bought. In addition, UCC-1 converters cost more than UCC-1C converters. For example, there is approximately a \$1,000 difference in the price of




FIGURE S-1
PROCUREMENT COST OF AN/UCC-1C AND AN/UCC-1 CONVERTERS VS
NUMBER OF CABINETS BOUGHT

a cabinet of UCC-1C and UCC-1 converters when about 80 cabinets are bought. This cost difference is even more significant when it is considered that development costs were all lumped in the first purchase of UCC-1 equipment and were distributed in the purchases of UCC-1C equipment.

PROBLEM IDENTIFICATION

Five major operational problems were identified during the evaluation. These were generally inter-related and are described as follows:

(1) Improper Diversity Balance

The diversity balance of every channel of telegraph terminal equipment aboard the USS Topeka and the USS Cavalier was improperly adjusted. With the improper adjustment, the advantage of using the frequency-diversity/space-diversity or frequency-diversity/R-F-diversity is lost. In a four-converter system, when the diversity is not balanced -- that is, automatic gain-control voltage of one of the converters is set higher than the other three converters -- regardless of which converter receives the strongest input signal, the converter with the highest AGC setting will produce the output signal to key the telegraph d-c loops. The other three converters and one of the receivers in the system are ineffective. The system will operate as effectively with only one converter and one receiver.

(2) Utilization of Terminal Equipment in the Communication Network Not Optimized

Frequently, only a single receiver was used with either the UCC-1C or UCC-1 system. Two receivers were available, but only one was patched to the system, and the second receiver was placed on standby. Whenever the reception on the first receiver became poor, the standby receiver was patched to the system. The operators then adjusted the first receiver or changed the frequency until good reception was obtained and placed the first receiver on standby. This method was used more aboard the USS Cavalier than aboard the USS Topeka.

Many of the management and technical shipboard communication personnel did not understand the reason for using two receivers in the system. They also stated that experience had shown them that the results obtained with one receiver were as good as those obtained with two receivers. Their opinion is justified only if the diversity balance of the equipment is not adjusted properly.

(3) Lack of Visual Malfunction Indication

There is no convenient indication of improperly operating or malfunctioning keyers and converters. If one of the keyers on a two-keyer transmit system is not operating, or up to three converters on a four-converter receive system are not operating, the radio operator is unaware of it unless he tests each module. Such tests are not periodically required; therefore, the condition will remain undetected unless the equipment fails completely.

(4) Test and Checkout Procedures Are Not Clearly Understood

There were four different opinions as to how the UCC-1C and its peripheral equipment should be set up to check and adjust the diversity balance according to the NAVSHIP Technical Manual. Only one of the four methods is correct. The improper methods observed can be attributed to a lack of understanding of the function of the telegraph terminal equipment, to the fact that the Technical Manual does not present the test procedures in terms fully understandable by the technicians, and to the fact that the manual is written with the assumption that when he conducts a test, the technical will read parts of the manual other than the one that describes the test.

(5) Test-Equipment Difficulties

The test set is not a completely self-contained unit for checking the receive-only system. To perform the diversity-balance test on the converters of UCC-1C equipment, keyers are required along with the test set to generate a test signal to the receive system. The test also requires disconnecting keyers and converters from the system and reconnecting them to each other back-to-back. After the test is completed, the keyers and converters must be disconnected and reconnected to return the system to operation. Keyers are not normally available aboard the ships that have receive capabilities only. These ships must depend on external signal sources to obtain the test signal.

ANALYSIS OF SYSTEM OUTAGES

An analysis of the communication network system in terms of unsatisfactory communications (i.e., garbled messages) was made. The record of these system outages is presented in Table S-4. On both the UCC-1C and the UCC-1 systems, 30 percent of outages were reportedly attributed to the cryptographic equipment. Approximately 45 percent of the outages involved the receiver.

TABLE S-4 SUMMARY OF COMMUNICATION NETWORK SYSTEMS OUTAGES			
Deficient Equipment Identification	Total Number of Garbled Teletype Messages		
	USS Topeka		USS Cavalier
	UCC-1C System	UCC-1 System	UCC-1C System
Receiver	16	20	5
Terminal	1	1	0
Transmitter	-	3	-
Teletype	-	1	-
Cryptographic Equipment	17	17	5
Cryptographic Equipment/Receiver Combination	5	5	1
Other (Equipment un-identified - no adjustment performed)	8	5	7
Total	47	52	18
		(48 in the receive network)	

Using the hours at sea as a basis for computing MTBSO provides a better comparison of the reliability of the network system containing the UCC-1C equipment with that of the system containing the UCC-1 equipment. The following MTBSO values are obtained:

	UCC-1 Network USS Topeka	UCC-1C Network USS Topeka	UCC-1C Network USS Cavalier	UCC-1C Network Combined USS Topeka and USS Cavalier
Mean Time Between System Outages (MTBSO)	17.5 hours	16 hours	29.8 hours	20 hours

Statistical tests of significance for the differences in the MTBSO of the UCC-1 system aboard the USS Topeka, the UCC-1C system aboard the USS Topeka, and the UCC-1C aboard the USS Cavalier were performed with the F-distribution. The purpose of these tests was to determine whether the MTBSO of the UCC-1C system aboard the USS Topeka was significantly different from the UCC-1 system aboard the USS Topeka and to show quantitatively the effect of ship operations and duty at sea on the system's reliability.

From the analysis the following deductions can be drawn:

- The UCC-1C and UCC-1 system networks aboard the USS Topeka have the same MTBSO.
- The MTBSO of the UCC-1C system network aboard the USS Cavalier was higher than the one aboard the USS Topeka.
- Operational data for the systems do not indicate that the reliability of the UCC-1C system is significantly different from that of the UCC-1 system.
- The type of ship, the under-way activities aboard the ship, and the amount of communication traffic handled by the ship affect the reliability of the communication-network system.

When the ships are under way, communication activities are at maximum, and this affects the operation of the UCC-1C and UCC-1 systems. The environmental conditions -- shock, vibrations, temperature variations, ship movement, gun fire, and power interruptions -- during ship maneuvers also affect the operation of these systems.

Figure S-2 presents the nonparametric-reliability-function curves for the UCC-1C network systems and the UCC-1 network system obtained from the system-outage data.

The reliability value is plotted against the hours of system operation at sea. The graph shows the probability of no outage, i.e., the probability that the message printout on the teletype will be satisfactory for a given number of hours following a previous unsatisfactory printout.

RECOMMENDATIONS

The following recommendations resulted from the evaluation:

(1) Microelectronic Application

- A continuation study should be made with the equipment in proper configuration and properly adjusted to evaluate advantages attributable to microelectronic design.
- Microelectronic applications should be continued in future developments and modifications of the communication telegraph terminal equipment. It is recommended that a comparative review of manufacturer procedures or techniques be conducted to establish guidelines for future procurements.

(2) Technical Manual Instructions on the Method of Operation and Testing of Terminal Equipment

- An application manual, directed to supervisory personnel and describing the advantages and proper method of operation, should be prepared.
- Test and adjustment procedures should be clarified in the technical manual for telegraph-terminal equipments.




FIGURE S-2

NONPARAMETRIC RELIABILITY FUNCTIONS

- Each test procedure described in the technical manual should reference the test book or other appropriate instructions, if they have been previously discussed, or redescribe them. In general, the technical manual should be reviewed and revised so that each set of instructions is an entity and does not assume that the technician has read previous or following sections.

(3) Terminal Equipment Problems

- The feasibility of incorporating a visual indication of operation mode and malfunction should be studied. An indicator should be considered for future procurements as well as for modification to existing equipments.
- PMR cards for periodic testing and balancing should be initiated. This maintenance could be performed quarterly.

(4) Test Equipment

A completely self-contained unit should be obtained so that the receive-only system can be tested without separate keyer modules. It is

understood that the Naval Electronic Systems Command is currently investigating this problem.

(5) Reliability of the System

A detailed study should be conducted to evaluate and define communication problems caused by receivers and cryptograph and transmitting equipments. The evaluation should quantitatively measure the effects of these equipments on system reliability and maintainability and should result in specific recommendations for corrective actions. This study could be conducted in conjunction with the microelectronic performance evaluation.

(6) MDCS Data

Better instructions should be provided to the fleet personnel for completing the MDCS forms, particularly with regard to accurate identification of the specific malfunctioning parts.

CONTENTS

	<u>Page</u>
SUMMARY	v
1. INTRODUCTION	1
1.1 Background	1
1.2 Objective	1
1.3 Description of Terminal Equipment	1
1.3.1 Function	1
1.3.2 Physical Description	3
1.3.3 Differences Between AN/UCC-1C and AN/UCC-1	3
2. METHOD OF EVALUATION	5
2.1 Definition of Terms	5
2.2 Description of Monitored Terminal Equipments	6
2.3 Task 1: Shipboard Surveillance	7
2.3.1 Personnel Briefing	9
2.3.2 Monitoring Procedures	9
2.4 Task 2: Additional Data Collections	10
2.5 Task 3: Cost Analysis	10
2.6 System Analysis of Task 4: Communication Network	10
3. DISCUSSION OF DATA	13
3.1 Shipboard Data, USS Topeka	13
3.1.1 Equipment Failures	13
3.1.2 Terminal-Equipment Maintenance Actions	13
3.1.3 Diversity-Balance Test	13
3.1.4 Unsatisfactory Communications	14
3.1.5 Experience of USS Topeka Personnel	15
3.2 Shipboard Data, USS Cavalier	15
3.2.1 Equipment Failures	15
3.2.2 Terminal-Equipment Maintenance Actions	16
3.2.3 Diversity-Balance Test	16
3.2.4 Unsatisfactory-Communication	16
3.2.5 Experience of USS Cavalier Personnel	17
3.3 MDCS-Data Analysis	17

CONTENTS (continued)

	<u>Page</u>
3.4 Cost Data	20
3.4.1 Development and Procurement Costs	20
3.4.2 Installation Costs	22
4. ANALYSIS OF TERMINAL-EQUIPMENT PROBLEMS	27
4.1 Proper Method of Utilization	27
4.2 System Operation With One Receiver	27
4.3 Improper Diversity Balance	27
4.4 Test and Checkout Procedures	28
4.5 Test-Equipment Problem	28
4.6 Lack of Visual Malfunction Indication	28
5. COMPARATIVE COST AND EFFECTIVENESS ANALYSIS	31
5.1 Effectiveness Analysis	31
5.2 Cost Analysis	
6. COMMUNICATION-NETWORK SYSTEM-RELIABILITY ANALYSIS	33
6.1 Reliability of Communication Network	33
6.2 Analysis of System Outages	39
7. CONCLUSIONS AND RECOMMENDATIONS	41
7.1 Microelectronic Application	41
7.1.1 Conclusion	41
7.1.2 Recommendation	41
7.2 Technical Manual Instructions on the Method of Operation and Testing of Terminal Equipment	41
7.2.1 Conclusions	41
7.2.2 Recommendations	42
7.3 Terminal Equipment Problems	42
7.3.1 Conclusions	42
7.3.2 Recommendations	42
7.4 Test Equipment	42
7.4.1 Conclusion	42
7.4.2 Recommendation	42
7.5 Reliability of the System	43
7.5.1 Conclusions	43
7.5.2 Recommendation	43

CONTENTS (continued)

	<u>Page</u>
7.6 MDCS Data	43
7.6.1 Conclusion	43
7.6.2 Recommendation	43
APPENDIX A - IDENTIFICATION OF MONITORED AN/UCC-1C AND AN/UCC-1 EQUIPMENTS	A-1
APPENDIX B - SUMMARY OF EVENTS OCCURRING DURING SURVEILLANCE PERIOD	B-1
APPENDIX C - SURVEILLANCE PROCEDURES	C-1
APPENDIX D - INCIDENT REPORTS	D-1
APPENDIX E - MDCS COMPUTER OUTPUT	E-1
APPENDIX F - COMPUTER PRINTOUT OF STATISTICAL TESTS	F-1
APPENDIX G - INSTALLATION COST DATA	G-1

1. INTRODUCTION

1.1 Background

The AN/UCC-1C telegraph terminal equipment was designed to employ microelectronic integrated-circuit devices. The purpose of the microelectronic application was to achieve maximum performance, reliability, and maintainability at minimum equipment cost*. Since the AN/UCC-1C is one of the first applications of microelectronic circuitry in Fleet service, it is important to the Navy to evaluate the advantages it offers and problems associated with it early in its operational phase.

1.2 Objective

The objective of this study was to compare the costs and effectiveness of the AN/UCC-1C with those of a conventional transistorized telegraph terminal (AN/UCC-1). The study comprised four tasks:

- (1) Shipboard Surveillance
- (2) Data Collection
- (3) Cost-Effectiveness Analysis
- (4) System Analysis of Overall Communication Network

1.3 Description of Terminal Equipment

1.3.1 Function

The UCC-1C and the UCC-1 are functionally the same. They are multichannel voice-frequency-carrier telegraph terminal equipments employing a frequency-division multiplex system over single-sideband radio circuits, voice-frequency wire lines, and microwave circuits.

These terminal equipments provide up to 16 different narrowband voice-frequency tone channels, each channel passing a different band of frequencies.

Associated with each channel is an oscillator which, keyed by a telegraph loop, generates one frequency representing a mark and another representing a space. These two frequencies are symmetrical with respect to the center of the channel pass band. The output from any set of different channels can be combined on a single line for transmission over a single 3-kHz bandwidth communication link**.

*See Military Specification, Carrier Telegraph Terminal Equipment, AN/UCC-1C(V), MIL-C-2361B (Ships), November 1965.

**For a 32-channel operation, multiplexer-demultiplexer units are used for transmission over a 6-kHz bandwidth communication link. Most U.S. Naval Ships, including the ships that were used during shipboard surveillance, are on a 3-kHz bandwidth communication link which requires no multiplex-demultiplexer units. Therefore, the operation of a 6-kHz bandwidth link is not discussed here.

The UCC-1 and UCC-1C equipments consist of frequency-shift keyers, converters, and control attenuators. Each frequency-shift keyer provides one channel that accepts d-c telegraph signals from an external loop, supplying the appropriate voice-frequency mark-space frequency-tone signal. The keyers are used only in the transmitting operation. Each frequency-shift converter used in the receiving operation has one channel that accepts a particular frequency tone signal, and it produces a keying signal to operate a d-c telegraph loop. The control attenuator has switches and fuses for the line power to the converters and keyers. The unit also incorporates an amplifier that maintains the composite output power at a constant level when the tones are combined.

Figure 1 is a schematic of a terminal equipment as it should be configured to obtain frequency-diversity/space-diversity or frequency-diversity/r-f-diversity for the application of a four-converter module per channel. This application is common to most U.S. Naval ships. At the transmitting location, two keyer modules are assigned to accept one d-c telegraph signal. The keyers supply two different




FIGURE 1

SCHEMATIC OF AN/UCC-1 AND AN/UCC-1C TERMINAL EQUIPMENT

voice frequency tone signals for transmission. At the receiving location two pairs of converter modules are assigned to each channel. One pair of converter modules (for each channel) processes signals from one radio receiver (designated Radio Receiver A), and the other pair processes signals from another receiver (designated Radio Receiver B).

In this system, the converter module receiving the strongest signal produces the keying signal to operate the d-c telegraph loop when the converters are properly balanced.

1.3.2 Physical Description

Both the UCC-1C and the UCC-1 telegraph terminals are modular carrier-telegraph equipment. Each comprises a cabinet that houses one control-attenuator module and eight frequency-shift converter modules or eight frequency-shift keyer modules (or any combination of pairs totaling eight modules of the latter two components). These will be referred to as attenuators, converters, or keyers in the remainder of this report.

The control attenuator provides the power ON-OFF switch, fuses, and blown-fuse indicator for the equipment. The keyer and the converter each consist of two sub-modules, the front and the back. The keyer is a complete self-contained, single-channel, FSK (frequency-shift keying)-tone, telegraph-transmit unit. All active circuit components of the keyer are contained on a plug-in printed-circuit board in the front sub-module. The front sub-module is completely interchangeable with the front sub-modules of all other keyers regardless of the keyers' transmitting frequencies. The converter consists of a complete single-channel FSK-tone telegraph-receive unit. All active circuit components of the converter are contained on a plug-in printed-circuit board in the front sub-module. It is also completely interchangeable with the front sub-modules of all other converters regardless of the converters' receiving frequencies.

All frequency-determining elements of both the keyers and converters are contained in their respective back sub-modules. The back sub-modules are not interchangeable.

1.3.3 Differences Between AN/UCC-1C and AN/UCC-1

The major difference between the UCC-1C and the UCC-1 is that the UCC-1 employs transistors in the circuits, while the UCC-1C employs microelectronic integrated circuits. Table 1 compares components used in the UCC-1C and UCC-1 terminal equipment.

In the converters the number of active elements decreased from 35 (14 transistors + 21 diodes) in the UCC-1 to 29 (4 integrated circuits + 6 transistors + 19 diodes) in the UCC-1C. The number of active elements in the keyers increased, but these elements were added deliberately to provide better frequency stability in the transmit function.

TABLE 1						
COMPARISON OF QUANTITIES OF SEMICONDUCTORS USED IN AN/UCC-1C AND AN/UCC-1						
Number of Semiconductors Used						
AN/UCC-1			AN/UCC-1C			
Type of Module			Integrated Circuits			
			Number of IE Circuits	Number of Active Transistors In IE Circuits		
Keyer	5	5	10	92	2	16
Converter	14	21	4	20	6	19
Control Attenuator	0	0	2	10	2	5
Test Set	7	8	10	102	4	73

To increase the transmitting frequency stability, the UCC-1C keyers make use of a seven-stage-divider flip-flop circuit, which is not available in the UCC-1 keyers. The mark-space oscillators of UCC-1C keyers operate at frequencies that are 128 times the mark-space frequencies of the broadcast channel. The oscillator frequency is divided by 128 in the divider circuit to obtain the broadcast-channel frequency. This design dampens the variations in the tone-frequency signal and is an improvement over the UCC-1 equipment.

The UCC-1C control attenuator, in addition to the power ON-OFF switch and fuse, contains a constant-level amplifier and an amplifier blown-fuse indicator on the front panel. The addition of the amplifier increased the number of active elements in the UCC-1C attenuator.

On each of the UCC-1C converters, keyers, and control attenuators, a single multiple-contact connector on the front panel mates with the cable connector of the test set. The connector provides a means of connecting module test points to the test set quickly and easily. On each of the UCC-1 converters, keyers, and control attenuators, separate test points are provided on the front panel. Separate connections from the module test points to the test set must be made when tests are being performed on the modules.

2. METHOD OF EVALUATION

2.1 Definition of Terms

Terms used throughout this report are defined as follows:

Communication Network System - UCC-1C or UCC-1 system network containing the telegraph terminal equipment, the transmitter or receiver, the transmitting medium between the transmitting and receiving stations, cryptographic equipment, and the teletypewriters.

Failure - An unsatisfactory printing output -- i.e., no copy or garbled printing, caused by a verified deficiency in the terminal equipment itself.

System Outage - Production of an unsatisfactory message output -- i.e., no copy or garbled messages as observed by, and in the judgment of, monitoring engineers.

Maintenance Action - A specific maintenance event necessary to keep an item in, or restore it to, a specified operational condition by repair or adjustment, or both.

Patched - The condition in which an equipment is electrically connected into the communication network system.

Available Time - The time the equipment is available for operation aboard the ship.

Energization Time - The calendar hours during which power was applied to the communication system network.

Utilization Time - The portion of energized time during which the telegraph terminal equipment is patched into the communication system network and is available to receive or transmit messages.

In-Port Utilization Time - The portion of utilization time during which the ship is docked.

Sea Utilization - The portion of utilization time during which the ship is under way.

The following computations are obtained from the ratios of the previously defined time periods and incidents:

$$\text{Percent Utilization} = \frac{\text{Utilization time}}{\text{Available time}}$$

$$\frac{\text{Mean Time Between System Outages During Utilization}}{\text{System Outages During Utilization}} = \frac{\text{Total Utilization Time}}{\text{Total System-Outage Incidents}}$$

$$\frac{\text{Mean Time Between System Outages During Utilization at Sea}}{\text{System Outages During Utilization at Sea}} = \frac{\text{Total Utilization-At-Sea Time}}{\text{System-Outage Incidents at Sea}}$$

2.2 Description of Monitored Terminal Equipments

The USS Topeka and the USS Cavalier were assigned by the Naval Ship Systems Command to provide the facilities necessary for shipboard surveillance. During the surveillance period both ships were performing crew-training missions.

The USS Topeka, a CLG-class cruiser, had extensive communication traffic via ship-to-shore/ship-to-ship, multi-channel communication network, and voice communication systems. The training missions of the USS Topeka involved active maneuvers, gun firing, missile firing, and continuous movement at sea.

The USS Cavalier, an APA-class troop carrier, had one channel of ship-to-shore and a multi-channel communication network system. In its training missions, the USS Cavalier took on troops and, after being under way a short period, anchored not more than 20 miles from shore facilities for the disembarking and re-embarking of troops for training exercises. Upon completion of the troop training exercise, the ship would return to port.

UCC-1C equipment capable of receiving eight channels and UCC-1 equipment capable of transmitting and receiving four channels were installed aboard the USS Topeka. UCC-1C equipment capable of receiving six channels was installed aboard the USS Cavalier.

The UCC-1C system layout aboard the USS Topeka is presented in Figure 2. The UCC-1C equipment rack contained four cabinets, each cabinet holding 8 converters and one control attenuator. Thus each cabinet contained modules assigned to two communication channels. Only four channels were patched to the cryptographic equipment and the teletypewriters to receive messages. The other four channels were energized but not utilized.

The UCC-1C and UCC-1 modules, with associated equipments, for both ships are identified in Appendix A.




FIGURE 2
AN/UCC-1C RECEIVE SYSTEM
ABOARD THE USS TOPEKA

The UCC-1 system layout aboard the USS Topeka is shown in Figure 3. The UCC-1 equipment rack contained three cabinets. One cabinet contained 8 keyers and one control attenuator for transmitting signals on four channels. Eight converters and one control attenuator were placed in each of the other two cabinets for receiving four channels. This equipment was patched into the network system only as required during ship movements.

The UCC-1C system layout aboard the USS Cavalier is shown in Figure 4. The UCC-1C equipment rack contained three cabinets, each cabinet holding 8 converters and one control attenuator. Thus each cabinet contained modules assigned to two communication channels. Only two channels were patched to the cryptographic equipment and the teletypewriters for receiving messages.

2.3 Task 1: Shipboard Surveillance

Shipboard surveillance was conducted by ARINC Research monitors aboard the USS Topeka from 17 April through 11 August 1967 and aboard the USS Cavalier from 26 June through 18 September 1967.





FIGURE 3
AN/UCC-1 RECEIVE-AND-TRANSMIT SYSTEM
ABOARD THE USS TOPEKA



*Channels Not Utilized

FIGURE 4
AN/UCC-1C RECEIVE SYSTEM ABOARD THE USS CAVALIER

This task consisted of an initial briefing of ship personnel and the performance of the monitoring procedures and associated reporting.

2.3.1 Personnel Briefing

Before the surveillance was started, ARINC Research engineers explained the purpose of the study to the ship's communications officers and personnel and described the monitoring procedures to be conducted. The briefing helped to assure that the objectives of the evaluation program would be attained with a minimum of disruption to shipboard operations and was useful in obtaining the necessary cooperation from the communications personnel.

2.3.2 Monitoring Procedures

An ARINC Research engineer aboard each ship was stationed in the communication center, where the terminal equipment was in operation. During regular day watches or during maximum communication activity and special ship movements, the engineers obtained first-hand observations of the operation of, and maintenance performed on, major equipments in the telegraph communication network system.

If the ARINC Research monitors were absent from the location of equipment when an anomaly occurred, the monitors relied on the shipboard personnel to observe the incident and report the details. These reports were verified by discussions with the officer in charge and the Chief Petty Officers and by a review of the normal written reports maintained by the ship.

To accomplish their objectives, the monitors correlated data obtained from the ships personnel with their own observed data and recorded these data in the following reports:

Initial Report. Before the evaluation was started, assembly code numbers were assigned to all telegraph-terminal components and to the interfacing equipments, and embossed tags containing the numbers were attached to components and equipments. A list was made of the code numbers, and the information was tabulated and forwarded to ARINC Research, Annapolis, during the first week of the evaluation aboard each ship. The assigned codes are given in Appendix A.

Daily Log. Daily events and conditions that could affect the operation of the telegraph terminal equipment or interface equipments were recorded in a daily log. Copies of the daily logs were forwarded to ARINC Research, Annapolis, on a weekly basis. These logs are summarized in Appendix B.

Weekly Activities Report. Weekly activity reports summarizing significant events and conditions that occurred during the preceding week were also submitted. These reports contained

a summary of the daily log entries and an analysis of the effects of events that may not have been apparent when the daily entries were made.

Incident Report. Incident reports were used for the systematic tabulation of detail data on maintenance actions performed on telegraph terminal equipment.

Work Sheet. Work Sheets were used by the observers to record general information and draw sketches or diagrams to clarify comments made on the incident reports.

Examples of these reports, with an explanation of their content and the procedures for surveillance and preparation of report forms, are given in the appendixes.

2.4 Task 2: Additional Data Collections

Data from the 3M Maintenance Data Collection System (MDCS) was evaluated to analyze further the Fleet experience with the UCC-1C and UCC-1 communication terminal equipment. A computer run of the MDCS General Data Retrieval Program, Catalog Number MDCS-11-0-06304, was obtained. This program lists maintenance and parts-use data.

2.5 Task 3: Cost Analysis

A cost-of-ownership evaluation was performed to determine the differences in development, procurement, and installation costs of the UCC-1C and UCC-1. The development and procurement costs were obtained from the procurement contracts issued for the purchase of UCC-1C and UCC-1 equipments. Installation costs were obtained from the Long Beach Naval Shipyard in Long Beach, California.

2.6 Task 4: System Analysis of Communication Network

The objective of the system analysis was threefold: (1) to evaluate the effectiveness of the microelectronic UCC-1C equipment and compare it with the transistorized UCC-1 equipment, (2) to acquaint Navy management with the sources of communication network problems, (3) to provide a quantitative guide as to where future effort could be most profitably expended to improve the fleet communication system.

Unsatisfactory communications due directly to deficiencies in terminal equipment produce unsatisfactory printouts on the teletypewriter. These have been previously defined as system outages. Unsatisfactory printout also results from a deficiency in any of the interfacing equipments. The record of these system outages constituted the data used to perform the system analysis.

To determine any interactions between UCC-1C or UCC-1 equipment and the interfacing equipments in the system, it was necessary to evaluate the observed system outages in terms of the effectiveness of the communication network.

3. DISCUSSION OF DATA

3.1 Shipboard Data, USS Topeka

A total of 2800 operating hours was accumulated on the UCC-1C and UCC-1 equipments from the start of the evaluation on 17 April 1967 through the completion of surveillance on 11 August 1967.

3.1.1 Equipment Failures

There were no failures requiring repair or replacement of failed parts of UCC-1 equipment during the surveillance period. Therefore, no failed parts were collected for failure analyses.

3.1.2 Terminal-Equipment Maintenance Actions

A maintenance action consisting of adjustments to the UCC-1C converter was performed on 6 July 1967. Excessive garbling of channel 1 of the UCC-1C system was observed, and a teletype technician* who was familiar with the UCC-1C equipment was called to perform the maintenance. The loop-current output of converter CV-17 of the UCC-1C was checked with the telegraph distortion analyzer, and the output was found to have a distortion between 25 percent and 45 percent.

The maintenance action taken consisted of centering the delay-control screw and adjusting the bias control until the distortion was minimum. The total inoperative time of channel 1 was 45 minutes.

A similar problem on channel 3 of the UCC-1 system was observed on 7 August 1967, and a similar maintenance action was performed by the same technician. Total inoperative time of channel 3 was 2 hours, 15 minutes.

The incident report describing both of these maintenance actions is given in Appendix D.

3.1.3 Diversity-Balance Test

During a discussion on 15 June 1967 between ARINC Research engineers and Code 6621D, NAVSEC, NORDIV, the problem of improper adjustment of diversity balance of converters on most U.S. Naval ships was reported. The ARINC Research engineer aboard the USS Topeka then requested that a diversity-balance test be conducted so that he could identify the method of testing used by the technician and determine the condition of the diversity-balance setting on the terminal equipment. This test was conducted on 21 June 1967.

*The school-trained UCC-1 technician was attending the San Diego Naval Electronic School and was not available to perform the maintenance action.

The method of testing used by the technician is discussed in Section 4.3.4 of this report. The diversity balance of each UCC-1C channel was improperly adjusted. This was apparent because the adjustment screw on each converter was turned to the maximum clockwise setting and each had to be reset in an attempt to balance the equipment.

The technician attempted to balance the diversity; however, because of the method employed and the test equipment used, it is doubtful that the proper diversity balance was actually achieved.

Diversity-balance tests were not repeated during the remaining surveillance period. It should be noted, however, that it is possible under certain conditions to maintain communication traffic with improperly balanced equipment.

3.1.4 Unsatisfactory Communications

Incidents of unsatisfactory communications resulting in garbled messages are presented in Table 2 for the UCC-1C network system on board the USS Topeka and in Table 3 for the UCC-1 network system on board the USS Topeka. These tables identify the interfacing equipments associated with the system that were adjusted to correct the problem of unsatisfactory communications.

TABLE 2 OUTAGES OF COMMUNICATION NETWORK SYSTEM UTILIZING THE AN/UCC-1C TELEGRAPH TERMINAL ABOARD THE USS TOPEKA, 17 April to 11 August 1967						
Equipment* Identification	Number of Garbled Messages on Teletype					
	April	May	June	July	August	Total
Receiver	-	7	-	5	4	16
AN/UCC-1C Telegraph Terminal	-	-	-	1	-	1
Cryptographic Equipment	2	12	-	2	1	17
Cryptographic Equipment/ Receiver Combination	-	5	-	-	-	5
Other (Equipment unidentified - no adjustment per- formed)	-	6	1	-	1	8
Total	2	30	1	8	6	47
*Equipment involved in corrective action.						

<p align="center">TABLE 3</p> <p align="center">OUTAGES OF COMMUNICATION NETWORK SYSTEM UTILIZING THE AN/UCC-1 TELEGRAPH TERMINAL ABOARD THE USS TOPEKA, 17 April to 11 August 1967</p>						
Equipment*	Number of Garbled Messages on Teletype					
	April	May	June	July	August	Total
Receiver	2	10	1	1	6	20
AN/UCC-1 Telegraph Terminal					1	1
Transmitter (AN/UCC-1 Transmit System)	1	1		1		3
Cryptographic Equipment	7	8		1	1	17
Cryptographic Equipment/Receiver Combination		1			4	5
Other (Equipment unidentified - no adjustment performed)		1			4	5
Teletype (AN/UCC-1 Transmit System)		1				1
Total	10	22	1	3	16	52
*Equipment involved in corrective action.						

3.1.5 Experience of USS Topeka Personnel

The experience of maintenance technicians and radio operators who worked on the telegraph-terminal equipment aboard the USS Topeka is given in Table 4.

3.2 Shipboard Data, USS Cavalier

A total of 1100 operating hours was accumulated on the UCC-1C equipment from the start of the evaluation on 26 June 1967 through the completion of surveillance on 11 September 1967.

3.2.1 Equipment Failures

There were no failures requiring repairs or replacement of failed parts of UCC-1C equipment during the surveillance period. Therefore, no failed parts were collected for failure analysis.

TABLE 4 EXPERIENCE OF USS TOPEKA PERSONNEL			
Type of Personnel	Rate	Training	Years of Service in the Navy
Radio Operator	RM2	Radioman School, Class A	4
Radio Operator	RM3	Radioman School, Class A; Teletype Main- tenance School	5
Radio Operator	RM3	Radioman School, Class A	3
Maintenance Technician	ET2	Electronic Technician School, Class A & Class B; UCC-1 Main- tenance School	4
Maintenance Technician	ET2	Electronic Technician School (Transistor); UCC-1C Maintenance School	(4-1/2 years of Naval Reserve)
Maintenance Technician	ET2	Radar School; Crypto School	6

3.2.2 Terminal-Equipment Maintenance Actions

No maintenance action was performed on the UCC-1C equipment.

3.2.3 Diversity-Balance Test

A shipboard technician was requested by the ARINC Research engineers to conduct the diversity-balance test. Each of the diversity-balance adjustment screws was found turned to the maximum clockwise setting, indicating that the UCC-1C channels were improperly adjusted; each had to be reset in an attempt to balance the equipment.

The technician was not able to balance the diversity of UCC-1C channels because of the lack of proper test equipment. The USS Cavalier has receive capability only in its teletype communication network system, and no keyers were available for the test.

3.2.4 Unsatisfactory-Communication

Incidents of unsatisfactory communications resulting in garbled messages are presented in Table 5 for the UCC-1C network system on board the USS Cavalier. The table identifies the interfacing equipments associated with the system that were adjusted to correct the problem of unsatisfactory communications.

<p align="center">TABLE 5 OUTAGES OF COMMUNICATION NETWORK SYSTEM UTILIZING THE AN/UCC-1C TELEGRAPH TERMINAL ABOARD THE USS CAVALIER, 26 June to 11 September 1967</p>					
Equipment* Identification	Number of Garbled Messages on Teletype				
	June	July	August	September	Total
Receiver	1	1	2	1	5
Cryptographic Equipment	1	3	-	1	5
Cryptographic Equipment/ Receiver Combination	-	1	-	-	1
Other (Equipment unidentified - no adjustment per- formed)	-	-	2	5	7
Total	2	5	4	7	18
*Equipment involved in corrective action.					

3.2.5 Experience of USS Cavalier Personnel

The experience of the maintenance technicians and the radio operators* who worked on the telegraph-terminal equipment aboard the USS Cavalier is given in Table 6.

3.3 MDCS-Data Analysis

So that the history of Fleet experience with the UCC-1C and UCC-1 communication terminal equipments could be analyzed further, ARINC Research requested a 3M Maintenance Data Collection System (MDCS) computer run of maintenance events recorded by Navy personnel aboard ships using these equipments. The computer run requested was an MDCS General Data Retrieval Program, Catalog Number MDCS-11-0-06304. This program lists data elements concerning maintenance and parts use on equipments. To use the UCC-1 and UCC-1C data furnished in this program, several additional sources of information were necessary:

- Allowance Parts Lists
- Manufacturer's Procurement Contracts
- NAVSHIPS 0967-006-1003 and -0004 Active Fleet Compilation of Equipment Assignments
- ARINC Research Monitor's Daily Logs and Equipment Identification Reports

*All of the radio operators aboard the USS Cavalier were authorized to operate the UCC-1C system. The listing in Table 6 represents the operators who worked on the system most of the time during surveillance.

<p style="text-align: center;">TABLE 6 EXPERIENCE OF USS CAVALIER PERSONNEL</p>			
Type of Personnel	Rate	Training	Years of Service in the Navy
Radio Operator	RM1	Radioman School, Class A, Class B; Teletype Maintenance School; Crypto Maintenance School	7-1/2
Radio Operator	RM2	Radioman School, Class A; Teletype Maintenance School	4
Radio Operator	RM2	Radioman School, Class A	3-1/2
Radio Operator	RM2	Radioman School, Class A	3-1/2
Radio Operator	RM3	Radioman School, Class A	3
Radio Operator	RM3	Radioman School, Class A	2-1/2
Maintenance Technician	ET2	AN/UCC-1C Mainte- nance School; Crypto Maintenance School	4
Maintenance Technician	ET2	AN/UCC-1C Mainte- nance School; Crypto Maintenance School	2-1/2

These added sources were needed to identify specifically the UCC-1C maintenance events reported in the computer program and to separate them from UCC-1 events. The data furnished in the MDCS program did not provide this separation; the Equipment Identification Code (EIC) generally identified the equipment only as the UCC-1 series and did not differentiate between the -1 and the -1C designs. A reproduction of the computer-program output used for the analysis is provided in Appendix E.

The MDCS program used in the analysis covered the 15-month period between 1 April 1966 and 30 June 1967 and contained reported events from 75 ships. With a few exceptions, i.e., where it was not possible to delineate the reported event specifically as either -1 or -1C equipment, all maintenance-action data reported were utilized in the analysis. The usable data consisted of 340 maintenance reports with "HOW MALFUNCTION" codes and the corresponding maintenance man-hours reported by the ships. The 340 reports were analyzed and reduced to represent 217 maintenance events. The completion of each general maintenance

action was considered an event. For example, an initial maintenance action that involved a delay in maintenance activity due to lack of parts, a requirement for outside assistance, or ship operations was combined with the completing action to represent a single event. In addition, maintenance actions that represented the general testing and adjusting of a set of converters over a continuous time span were combined to represent a single event. However, individual maintenance actions occurring as a result of discoveries made during the course of a general maintenance action were counted as separate events.

The results obtained from the analysis are shown in Tables 7 and 8. Table 7 summarizes the maintenance events and corresponding man-hours, including the events and man-hours that could be associated with the installation of the terminal equipments. Since installation activity does not represent malfunctioning of the equipment, nor does it provide an indication of the operational reliability of the equipment, these events and man-hours were subtracted and the results tabulated in Table 8. The similarity in the results obtained indicates that the maintainability of the two designs, from the standpoint of maintenance man-hours expended, is essentially the same.

TABLE 7 SUMMARY OF MDCS MAINTENANCE DATA				
Equipment Identification	Total Number Reports	Total Number Events	Total Man-Hours Expended	Number of Ships*
AN/UCC-1	193	110	2012.0	35
AN/UCC-1C	147	108	736.5	46
*Nine ships were identified as having both equipments.				

TABLE 8 SUMMARY OF MDCS MAINTENANCE DATA EXCLUDING INSTALLATION ACTIVITY					
Equipment Identification	Total Number Events	Total Man-Hours Expended	Average Man-Hours Per Event	Man-Hour Range	
				Maximum Per Event	Minimum Per Event
AN/UCC-1	106	546.6	5.2	116.8	0.1
AN/UCC-1C	105	545.0	5.2	34.0	0.2

Table 9 lists the malfunction codes reported and the number of times each was used for both designs. The table reflects the similarity in the number of events reported for each malfunction descriptor. The following malfunction descriptors were recorded on more than 60 percent of the events reported on each equipment:

<u>Description</u>		<u>UCC-1C</u>	<u>UCC-1</u>
No malfunction	(000)	22.7%	10.0%
Inoperative	(068)	9.3%	10.9%
Output Incorrect	(161)	12.0%	15.5%
No Output	(255)	17.6%	15.5%
Open	(450)	1.8%	10.9%

It was determined from "When Discovered" and "Action Taken" codes that the first three descriptors were used during installation activity and preventive maintenance as well as in describing corrective-maintenance actions. Unfortunately, the cause of corrective-maintenance actions could not be specifically identified because of the vague identification or nonidentification of the replaced parts. (In more than 55 percent of the reported events, replacement parts were used.) If this information had been reported in greater detail, the data could have been used with a review of the equipment schematics to identify the location and function of the source of trouble and, possibly, areas for engineering corrective actions.

The analysis of the MDCS shows no appreciable difference in the maintenance support required for the two terminal equipments. Also, in view of the length of the period (15 months) for which data were provided, the number of events reported, and the man-hours expended for a population of 75 ships, both equipments appear to be operationally satisfactory.

3.4 Cost Data

3.4.1 Development and Procurement Costs

The development and procurement costs for the UCC-1C and UCC-1 were obtained from the procurement contracts for each equipment. Since the cost and number of units bought varied considerably for each purchase, a common base had to be established to compare the relative costs of the UCC-1C and UCC-1 equipments. This base was established by calculating the cost of UCC-1C and UCC-1 converters and keyers on a per-cabinet basis. For the purpose of this analysis, a cabinet contains eight converters or eight keyers, one power-control attenuator, one test set, one technical manual, and associated hardware such as cabling, etc.

TABLE 9
HOW-MALFUNCTIONED REPORTS

Code	How-Malfunctioned Code	Number of Events Reported	
	Description	AN/UCC-1	AN/UCC-1C
000	No Malfunction	11	24
004	Low GM or Emission	1	0
008	Noisy	0	1
021	Overloaded	0	2
054	Faulty Part	1	0
068	Inoperative	12	10
070	Broken	1	1
080	Burned Out	2	9
093	Missing Part	1	0
099	Other	0	7
117	Deteriorated	1	0
127	Adjustment Improper	5	4
160	Contact Connection Defective	0	1
161	Output Incorrect	17	13
196	Shorted	4	1
233	Erratic	1	0
242	Failed to Operate	6	2
255	No Output	17	19
276	Weak	0	1
346	Misaligned	7	3
360	Intermittent	1	0
428	Incorrect Reading	1	0
450	Open	12	2
458	Out of Balance	2	1
462	Output Too Low	0	1
472	Fuse Blown	1	0
700	Weak Electrically	3	0
750	Missing	1	1
819	Contact Not Operating Properly	1	0
884	Broken	0	1
900	Burned	1	4
Total		110	108

The cost of a fully equipped cabinet of UCC-1C converters and keyers was compared with the cost of a similar cabinet of UCC-1 converters and keyers.

Tables 10 through 13 give the procurement cost data for the UCC-1C and UCC-1 equipments. The number of cabinets of converters bought is shown, along with the cost per cabinet and the average cost per cabinet for each purchase.

3.4.2 Installation Costs

Table 14 lists the labor and material costs associated with the installation of UCC-1C and UCC-1 equipments. The installation costs of UCC-1C and UCC-1 equipments are identical. Appendix G details the installation cost data assembled from shipyard records, supplied through the office of the Chief Planner and Estimator of the Long Beach Naval Shipyard.

<p align="center">TABLE 10</p> <p align="center">PROCUREMENT COSTS OF AN/UCC-1C CONVERTERS</p> <p align="center">(IN DOLLARS)</p>				
Purchase Number	Number of Full Cabinets Bought	Cost Per Cabinet	Total Cost*	Average Cost Per Cabinet
1	702	1,952	1,370,304	
	17.5	1,824	31,920	
	18	1,802	32,442	
	12.5	1,867	23,335	
	44	1,781	78,364	
	10	1,867	18,668	
	2.5	1,867	4,667	
	20	4,203	84,060	
	6	4,075	24,447	2,004
2	3	1,821	5,464	
	7.5	1,887	14,154	
	16	1,801	28,812	
	3	1,821	5,464	1,827
3	48	2,378	114,132	
	28	2,859	80,052	
	13	2,224	28,912	
	10.5	2,357	24,752	
	4	1,318	5,272	2,446
4	12	2,555	30,666	
	16	2,233	35,720	
	10	2,233	22,330	
	6	2,650	15,900	
	3	2,240	6,720	
	1.5	2,368	3,552	2,369
5	0.5	5,858	2,929	5,858
6	1.5	5,858	8,787	5,858
7	2.5	5,858	14,645	
	2	4,321	8,642	
	2.5	5,010	12,525	
	6	5,379	32,274	5,237
*Development cost amortized over the production delivery schedule.				

TABLE 11 PROCUREMENT COSTS OF AN/UCC-1 CONVERTERS (IN DOLLARS)				
Purchase Number	Number of Full Cabinets Bought	Cost Per Cabinet	Total Cost*	Average Cost of Cabinet Per Purchase
1	4	7,557	30,228	7,557
2	2	5,464	10,928	
	5	5,557	27,784	5,530
3	24	5,040	120,960	
	8	4,924	39,392	5,000
4	44	3,265	143,660	
	16	3,190	51,036	3,245
5	20	3,956	79,105	
	16	3,509	56,140	
	52	3,190	165,867	3,420
*Development cost included in first purchase.				

TABLE 12 PROCUREMENT COSTS OF AN/UCC-1C KEYERS (IN DOLLARS)				
Purchase Number	Number of Full Cabinets Bought	Cost Per Cabinet	Total Cost	Average Cost of Cabinet Per Purchase
1	25	1,918	47,950	
	1	2,410	2,410	
	12	1,790	21,480	1,890

TABLE 13 PROCUREMENT COSTS OF AN/UCC-1 KEYERS (IN DOLLARS)				
Purchase Number	Number of Full Cabinets Bought	Cost Per Cabinet	Total Cost	Average Cost of Cabinet Per Purchase
1	12	3,299	39,588	
	4	3,299	13,194	3,300
2	22	2,439	53,658	
	8	2,289	18,308	2,400

TABLE 14
SUMMARY OF
INSTALLATION COSTS FOR AN/UCC-1C AND
AN/UCC-1 TERMINAL EQUIPMENT

1. Labor Costs (Civilian Personnel)		
Shop-test terminal equipment and prepare for installation	24 man-hours	
Fabricate and install foundation aboard ship		
or		
Fabricate mounting kits and install in 19" cabinet	38 man-hours	
Shipboard installation of terminal equipment		
Install cable, connect a cold-wire check and final-test, check-out installation (includes quality-assurance services)	81 man-hours	
Total Labor Costs @ 8.50 hour	143 man-hours	\$1,216
2. Material Costs		
Material used for equipment preparation and bonding (plugs - miscellaneous electrical material - bond mat).		\$ 116
Material used for equipment installation (cable - mounting hardware - insulation - rubber matting)		\$ 100
Material for foundations or mounting kit		\$ 30
Total material		\$ 246

4. ANALYSIS OF TERMINAL-EQUIPMENT PROBLEMS

Six problems associated with the performance and usage of both terminal equipments were identified and analyzed.

4.1 Proper Method of Utilization

For the UCC-1 or UCC-1C receiving system, most U. S. Naval ships are provided four converters per channel and two receivers to operate in a frequency-diversity/space-diversity mode or a frequency-diversity/r-f-diversity mode. In these modes maximum reception performance is obtained through redundancy when the equipments are adjusted and connected properly (see Figure 1).

4.2 System Operation With One Receiver

Aboard the USS Topeka and USS Cavalier, quite often a single receiver was used with the UCC-1C or UCC-1 system. Two receivers were available, but only one was patched to the system, and the second receiver was placed on standby. Whenever the reception on the first receiver became poor, the standby receiver was patched to the system. The operators then adjusted the first receiver or changed the frequency until good reception was obtained and placed the first receiver on standby. This method was used more aboard the USS Cavalier than aboard the USS Topeka.

Many of the management and technical shipboard communication personnel did not understand the reason for using two receivers in the system. They also stated that experience had shown them that the results obtained with one receiver were as good as those obtained with two receivers. Their opinion is justified only if the diversity balance of the equipment is not adjusted properly.

4.3 Improper Diversity Balance

The diversity balance of every channel of telegraph terminal equipment aboard the USS Topeka and the USS Cavalier was improperly adjusted. With the improper adjustment, the advantage of using the frequency-diversity/space-diversity or frequency-diversity/r-f-diversity is lost. In a four-converter system, when the diversity is not balanced -- that is, automatic gain-control voltage of one of the converters is set higher than the other three converters -- regardless of which converter receives the strongest input signal, the converter with the highest AGC setting will produce the output signal to key the telegraph d-c loop. The other three converters and one of the receivers in the system are ineffective. The system will operate as effectively with only one converter and one receiver.

4.4 Test and Checkout Procedures

ARINC Research engineers discussed the test and checkout procedures for setting the diversity balance on UCC-1C equipment with the U. S. Naval Shipyard technicians, the MOTU (Mobile Technical Unit) personnel, and the technicians aboard the USS Topeka and USS Cavalier.

There were different opinions as to how the UCC-1C and its peripheral equipment should be set up to check and adjust the diversity balance according to the paragraph 2 4a(4)(b) of Technical Manual NAVSHIP 0967-046-9010, for AN/UCC-1C(V) Telegraph Terminal.

The four different procedures used by different Navy personnel to conduct the test and set the diversity balance are presented in Table 15.

According to the AN/UCC-1C(V) Technical Manual, Procedure 4 is the only correct method for conducting the test and setting the diversity balance. The improper methods described in the first three procedures for testing can be attributed to (1) a lack of understanding of the function of the telegraph terminal equipment, (2) to the fact that the Technical Manual does not present the test procedures in terms fully understandable by the technicians, and (3) the fact that the manual is written with the assumption that when conducting a test, the technician will read parts of the manual other than the one that describes the test.

4.5 Test-Equipment Problem

The test set is not a completely self-contained unit for checking the receive-only system. To perform the diversity-balance test on the converters of UCC-1C equipment, keyers are required along with the test set to generate a test signal to the receive system.

The test also requires disconnecting keyers and converters from the system and reconnecting them to each other back-to-back. After the test is completed, the keyers and converters must be disconnected and reconnected to return the system to operation.

Keyers are not normally available aboard the ships that have receive capabilities only. These ships must depend on external signal sources to obtain the test signal.

4.6 Lack of Visual Malfunction Indication

There is no convenient indication of improperly operating or malfunctioning keyers and converters. If one of the keyers on a two keyer transmit system is not operating, or up to three converters on a four-converter receive system are not operating, the radio operator is unaware of it unless he tests each module. Such tests are not periodically required; therefore, the condition will remain undetected unless the equipment fails completely.

An investigation should be conducted to determine the feasibility of incorporating a visual indicator to show that the modules are operating.

TABLE 15
VARIATIONS IN UCC-1C CHECKOUT PROCEDURES

Procedure 1:

- (1) Entire system (Receiver, Crypto, UCC-1C equipment, and the Teletype) remains in service during the diversity-balance check.
- (2) Use test-set TS-2232 UCC-1C(V); plug in test-set connector/adaptor to any one of the UCC-1C converters.
- (3) Connect oscilloscope leads to the common and the AGC (Automatic Gain Control) pins of each converter being checked, and monitor the AGC output.
- (4) The following procedure, described in paragraph 2-4d(4) (b)6 of the AN/UCC-1C(V) Technical Manual, is then performed (the procedure is reproduced below exactly as it appears in the TM):

"For four-channel diversity operation, perform the diversity balance as follows:

a Monitor the AGC test point of the Converter noted as having the second highest output.

Note

If the separation of signal levels was not sufficient to permit identification of the Converter having the second highest output, turn the DIV BAL control on the Converter with the highest output slowly counterclockwise until the signal levels separate sufficiently to permit identification of the second highest output.

b Turn the DIV BAL control on the Converter with highest output slowly counterclockwise until the AGC voltage observed on the oscilloscope reaches maximum amplitude.

Note

Do not advance the control past the maximum amplitude point.

c Connect the oscilloscope to monitor the AGC test point of the Converter noted as having the third highest output.

d Turn the DIV BAL controls on the Converters with the highest output and second highest output slowly counterclockwise. Advance each control slowly until the output no longer increases when either control is turned.

Note

Do not advance either of the controls past the maximum amplitude point.

e Connect the oscilloscope to monitor the AGC test point of the Converter noted as having the lowest output.

f Turn the DIV BAL controls on the three Converters with higher output slowly counterclockwise until the AGC output being monitored no longer increases.

Note

Do not advance any of the DIV BAL controls past the maximum amplitude point.

g Compare the AGC amplitude of all Converters in the diversity combination. If they are not equal, repeat steps b through f and readjust slightly as required. When this step has been completed, all Converters in the diversity combination have the same gain."

Procedure 2:

- (1) Entire system (Receiver, Crypto, AN/UCC-1C and the teletype) remains in service (same as Item 1 of Procedure 1).
- (2) Do not use test set.
- (3) Connect oscilloscope leads to the common and the AGC pins of the converter being checked.
- (4) Same as Item 4 of Procedure 1.

Procedure 3:

- (1) Entire system may remain in service. However, better result is obtained if the receiver is taken out of the system.
- (2) Use the test-set TS-2232-UCC-1C(V); plug in test set connector/adaptor to the converter. Set the tone setting on the test set to the tone frequency of the converter being checked.
- (3) Connect oscilloscope leads to common and AGC output pins of the test set.
- (4) Same as Item 4 of Procedure 1.

(Continued)

TABLE 15 (Continued)

Procedure 4:

Method A: When keyers are available for testing (i.e., keyers are in the system).

- (1) Disconnect telegraph-terminals associated equipment from the UCC-1C System.
- (2) Connect keyers and converters back-to-back.
- (3) Plug in test set connector/adaptor to the keyer that corresponds to the converters being checked.
- (4) Generate dot cycle with the test set.
- (5) Connect oscilloscope to AGC and common pins of the converter being checked.
- (6) The procedure described in paragraph 2-4d(4) (b)6 of the AN/UCC-1C(V) Technical Manual is then performed.

Method B: When keyers are not available for testing

- (1) Entire UCC-1C system remains in service.
- (2) Contact a ship or communication station and request transmission of dot cycle test (per Technical Manual).
- (3) Connect oscilloscope to AGC and common pins of the converter being checked. (It is not necessary for the ship personnel performing the adjustments on the converter to use the test set when the dot cycle test is used.)
- (4) Same as Item 4 of Procedure 1.

5. COMPARATIVE COST AND EFFECTIVENESS ANALYSIS

5.1 Effectiveness Analysis

As described in Section 3.1.2, a single malfunction on each of the UCC-1C and the UCC-1 terminal equipments was observed during the surveillance period aboard the USS Topeka.

If it is assumed* that the distributions of times to failure of the terminal equipments are exponential, the following values are obtained from the observed maintenance-action data:

Value	AN/UCC-1C Terminal Equipment	AN/UCC-1 Terminal Equipment
Number of Observed Malfunctions	1	1
Total Active Repair Time (Hours)	0.75	2.25
Total Equipment Energization Time	2800 hrs.	2800 hrs.
MTBF Based on Energization Time	2800 hrs.	2800 hrs.
Total Equipment Utilization Time (hours)	2800	848
MTBF (Mean Time Between Failures) based on utilization time (hours)	2800**	848**
Intrinsic Availability	1	1
$\text{Intrinsic Availability}(A_j) = \frac{\text{Total Energized Time}}{\text{Total Energized Time} + \text{Total Active Repair Time}}$		
AN/UCC-1C	AN/UCC-1	
$A_j = \frac{2800}{2800 + 0.75} \cong 1$	$A_j = \frac{2800}{2800 + 2.25} \cong 1$	

*This assumption is based on the results of many studies that validate an exponential time to failure distribution for complex electronic equipments.

**Because of the single failure on each equipment the MTBF based on the utilization time is misleading. The different MTBF numbers are obtained because of the difference in the number of hours of utilization of the equipments during the surveillance period. With the available data it cannot be shown that there is a significant difference in MTBF between the two equipments when based on equal utilization times.

5.2 Cost Analysis

Figure 5 is a plot of the average cost per cabinet of converters as a function of the number of cabinets bought. This plot reveals that the cost of UCC-1C converters becomes fairly constant when 50 or more cabinets of them are bought and increases rapidly when less than 50 are purchased.

The curve representing the UCC-1 converter costs follows a trend similar to that of the UCC-1C. It appears that the cost levels out when approximately 60 or more are bought. The costs increases rapidly when fewer than 60 cabinets are bought.

Figure 5 shows that UCC-1 converters cost more than UCC-1C converters. For example, there is approximately a \$1,000 difference in the price of a cabinet of UCC-1C and UCC-1 converters when about 80 cabinets are bought. This cost difference is even more significant when it is considered that development costs were all lumped in the first purchase of UCC-1 equipment and were distributed in the purchases of UCC-1C equipment.

Tables 12 and 13 tabulate procurement costs for UCC-1C and UCC-1 keyers, respectively. These data were not plotted, since there were too few points to establish a meaningful trend. It can be seen from Tables 12 and 13 that the cost per cabinet of UCC-1C keyers is less than that of UCC-1 keyers.




FIGURE 5

PROCUREMENT COST OF AN/UCC-1C AND AN/UCC-1 CONVERTERS VS
NUMBER OF CABINETS BOUGHT

6. COMMUNICATION-NETWORK SYSTEM-RELIABILITY ANALYSIS

During the surveillance, only one malfunction was observed on each of the AN/UCC-1C and UCC-1 terminal equipments. The observed data were insufficient to determine whether there was a substantial difference in the effectiveness of the two equipments.

To make a more meaningful comparison of the operational performance of the UCC-1C and UCC-1 and to evaluate the effect of interfacing equipments on the system, communication-network system outages were analyzed.

System outages and their causes as reported by the shipboard personnel or observed by ARINC Research engineers are listed in Table 16.

6.1 Reliability of Communication Network System

Operational data for the systems do not indicate that the reliability of the UCC-1C system is significantly different from that of the UCC-1 system.

The mean time between system outages (MTBSO) for total utilization time of the network system containing the UCC-1C equipment is approximately two and one-half times greater than that of the network system containing the UCC-1 equipment; but this is a biased value. The total utilization time of the system containing the UCC-1C equipment was 2,368 hours, with 697 hours at sea and 1,671 hours in port. The total utilization time of the system containing the UCC-1 equipment was 848 hours, with 843 hours at sea and 5 hours in port. Since the rate of network system outages at sea is far greater than in port, the comparison of 1,671 in-port hours of the system utilizing the UCC-1C equipment with 5 in-port hours of the system utilizing the UCC-1 equipment will produce an unrealistic, or biased result.

Using the hours at sea as a basis of computing MTBSO provides a better comparison of the reliability of the network system containing the UCC-1C equipment with that of the system containing the UCC-1 equipment. The following MTBSO values are obtained:

	UCC-1 Network USS Topeka	UCC-1C Network USS Topeka	UCC-1C Network USS Cavalier	UCC-1C Network Combined USS Topeka and USS Cavalier
Mean Time Between System Outages	17.5 hours	16 hours	29.8 hours	20 hours

Communication-network system operational data and reliability computations are summarized in Table 17.

TABLE 16
REPORTED CAUSES OF SYSTEM OUTAGES*

Equipment	Anomaly Reported	Corrective Action Taken	Number of Outages
Receive Network System Utilizing UCC-1 Aboard USS Topeka			
Receiver R-1051	Frequency drift		10
	Poor propagation	Receiver adjusted	5
	Poor frequency reception		3
	Component failure	Receiver replaced	1
Receiver AN/SRR-19	Poor propagation condition	Receiver adjusted	1
Crypto KW-26	Crypto out of synchronization due to:	Crypto resynchronized and adjusted	
	Vibration by gun firing		6
	Power interruption		7
	Cause unknown		5
Receiver R-1051 and Crypto KW-26	Poor signal from receiver through crypto. Crypto out of synchronization	Receiver and crypto adjusted	5
Unknown	None	None	4
Receive Network System Utilizing AN/UCC-1C Aboard USS Topeka			
Receiver R-1051	Frequency drift	Receiver adjusted	
	Frequency drift/poor propagation condition combination		3
	Receiver tuned improperly		2
	Poor reception		1
Receiver AN/SRR-19	Frequency drift	Receiver adjusted	1
	Poor propagation condition		1
	Component failure		1
Crypto KG-14	Crypto out of synchronization due to:	Crypto resynchronized and adjusted	
	Power interruption		7
	Vibration by gun fire		1
	Cause unknown		10
Receiver R-1051 and Crypto KW-26	Poor signal from receiver through crypto. Crypto out of synchronization	Receiver and crypto both adjusted	5
Unknown	None	None	8
*Does not include terminal equipment malfunctions.			

TABLE 16 (Continued)

Equipment	Anamoly Reported	Corrective Action Taken	Number of Outages
Transmit Network System Utilizing AN/UCC-1 Aboard USS Topeka			
Transmitter AN/WRT-2	Unable to transmit messages due to component failure	Transmitter replaced	2
	Unable to transmit messages due to lack of power to transmitter	Power restored	1
Teletypewriter (Send)	Unable to send messages due to bad connection in teletype circuit	Connection repaired	1
Receive Network System Utilizing AN/UCC-1C Aboard USS Cavalier			
Receiver R-1051	Receiver out of adjustment	Receiver adjusted	1
	Receiver not tuned properly		1
	Frequency drift		1
Receiver AN/SRR-19	Lost broadcast on set frequency (Transmitting station discontinued broadcasting)	Receiver re-set to different broadcast frequency	2
Crypto KWR-37	Crypto out of synchronization due to:	Crypto resynchronized and adjusted	1
	Bad keying from transmitting station Cause unknown		3
Receiver R-1051 and Crypto KWR-37	Poor signal from receiver through crypto. Crypto out of synchronization	Receiver and crypto both adjusted	1
Unknown	None	None	8

TABLE 17
COMMUNICATION-NETWORK SYSTEM OPERATIONAL DATA
AND RELIABILITY COMPUTATIONS

Parameter	Receive Network System Utilizing UCC-1 Aboard USS Topeka	Receive Network System Utilizing UCC-1C Aboard USS Topeka	Receive Network System Utilizing UCC-1C Aboard USS Cavalier
Hours Equipment Available	2800	2800	1870
Hours Equipment Energized	2800	2800	1100
Hours Equipment Utilized	848	2368	720
Percent Utilization	30%	85%	40%
Hours Equipment Utilized at Sea	843	697	485
Hours Equipment Utilized at Port	5	1670	235
Total System Outages	48	47	18
System Outages at Sea	48	43	16
System Outages in Port	0	4	2
Mean Time Between System Outages During Total Utilization (Hours)	17.5	50	40
Mean Time Between System Outages at Sea (Hours)	17.5	15.95	29.83
Mean Time Between System Outages in Port (Hours)	-	417	117

Statistical tests of significance for the differences in the MTBSO of the UCC-1 system aboard the USS Topeka, the UCC-1C system aboard the USS Topeka, and the UCC-1C aboard the USS Cavalier were performed with the F-distribution. The purpose of these tests was to determine whether the MTBSO of the UCC-1C system aboard the USS Topeka was significantly different from the UCC-1 system aboard the USS Topeka and to show quantitatively the effect of ship operations and duty at sea on the system's reliability.

The test of significance with the F-distribution is based on fundamental statistical concepts established for data that are known, or assumed, to have an

exponential distribution.* Sample means computed from exponentially distributed data are distributed as chi-square (χ^2) with $2r + 2$ degrees of freedom, where r is the number of observations (in this case the number of system outages). Also, the ratio of two χ^2 variates is distributed as an F-distribution. By use of these basic statistical principles, tests were made for significant differences in MTBSO between systems aboard the USS Topeka and systems aboard the Cavalier.

The following calculations were made:

$$\theta_1 = \text{MTBSO of UCC-1 System aboard USS Topeka} = 17.54 \text{ hours}$$

$$\theta_2 = \text{MTBSO of UCC-1C System aboard USS Topeka} = 15.95 \text{ hours}$$

$$\theta_3 = \text{MTBSO of UCC-1C System aboard USS Cavalier} = 29.83 \text{ hours}$$

$$r_1 = \text{Number of outages of UCC-1 system aboard USS Topeka during utilization at sea} = 48$$

$$r_2 = \text{Number of outages of UCC-1C system aboard USS Topeka during utilization at sea} = 43$$

$$r_3 = \text{Number of outages of UCC-1C system aboard USS Cavalier during utilization at sea} = 16$$

The null hypothesis that $\theta_1 = \theta_2$ was tested against the alternate hypothesis that $\theta_1 \neq \theta_2$ at the 10-percent (α) level of significance as follows:

$$\frac{\theta_1}{\theta_2} \leq F(2r_1 + 2) (2r_2 + 2) (\alpha)$$

where

$$\frac{\theta_1}{\theta_2} = \frac{17.54}{15.95} = 1.1$$

and

$$F(2r_1 + 2) (2r_2 + 2) (\alpha) = F(98) (88) (0.10) = 1.3$$

Since 1.1 is less than 1.3, the null hypothesis of MTBSO equality between the UCC-1C and UCC-1 aboard the USS Topeka cannot be rejected.

The same statistical test was performed for the UCC-1C system outages aboard the USS Topeka and the USS Cavalier. In this test the null hypothesis is $\theta_3 = \theta_2$ and the alternate hypothesis is $\theta_3 \neq \theta_2$.

*Tests conducted to verify the hypothesis that the system outage data have an exponential distribution indicated that at the 20-percent level of significance the hypothesis cannot be rejected. For the computer printouts of the tests, see Appendix F.

The test was made again at the 10-percent (α) level of significance; it resulted in the following:

$$\frac{\theta_3}{\theta_2} \leq F_{(2r_3 + 2) (2r_2 + 2) (\alpha)}$$

where

$$\frac{\theta_3}{\theta_2} = \frac{29.83}{15.95} = 1.86$$

$$F_{(2r_3 + 2) (2r_2 + 2) (\alpha)} = R_{(34) (88) (0.10)} = 1.5$$

Since 1.86 is greater than 1.5, the null hypothesis is rejected.

This indicates that the MTBSO of the UCC-1C system aboard the USS Cavalier was not equal to the one aboard the USS Topeka (it was higher in this case).

From the analysis the following deductions can be drawn:

- The UCC-1C and UCC-1 system networks aboard the USS Topeka have the same MTBSO.
- The type of ship, the under-way activities aboard the ship, and the amount of communication traffic handled by the ship affect the reliability of the communication network system.

When the ships are under way, communication activities are at maximum, and this affects the operation of the UCC-1C and UCC-1 systems. The environmental conditions -- shock, vibrations, temperature variations, movement of ship, gun fire, power interruptions -- during ship maneuvers also affect the operation of these systems.

Figure 6 presents the nonparametric-reliability-function curves for the UCC-1C network systems and the UCC-1 network system obtained from the system-outage data.

The reliability value is plotted against the hours of system operation at sea. The graph shows the probability of no outage, i.e., the probability that the message printout on the teletype will be satisfactory for a given number of hours following a previous unsatisfactory printout. The method used to derive the nonparametric reliability function is presented in the ARINC Research Reliability Engineering Text*.

*Techniques Used in Computing Reliability Function", Reliability Engineering, pp. 143-149, ARINC Research Corporation, Prentice-Hall, Inc., 1965.




FIGURE 6
NONPARAMETRIC RELIABILITY FUNCTIONS

6.2 Analysis of System Outages

On both the UCC-1C and the UCC-1 systems, 30 percent of outages were reportedly attributed to the cryptographic equipment. Approximately 45 percent of the outages involved the receiver.

If the diversity balance on the terminal equipment were adjusted properly and the proper method of hookup (i.e., frequency-diversity/space-diversity or frequency-diversity/r-f diversity) were utilized, system outages attributable to the receiver could be reduced.

The following system outages resulting from receiver anomalies could be eliminated if the terminal equipment were correctly adjusted and balanced and a correct system configuration used:

<u>Receiver-Caused System Outages</u>	<u>Number of Observed Occurrences</u>	<u>Situation Causing Outages</u>
Frequency drift, poor propagation conditions, poor reception	41	Improper configuration
Crypto out of synchronization due to poor signal reception	11	Improper diversity balance

7. CONCLUSIONS AND RECOMMENDATIONS

Conclusions and recommendations resulting from the comparison of the UCC-1C and the UCC-1 are presented below.

7.1 Microelectronic Application

7.1.1 Conclusion

There was insufficient data and sample size to determine any quantifiable difference in the effectiveness between the observed UCC-1 and UCC-1C terminal equipments. Since neither equipment was properly used during the surveillance program, any inherent improvement in communication performance due to UCC-1C design may have been masked.

The analysis of the cost data shows that the UCC-1C provides a reduction of approximately 30 percent below the cost of the UCC-1 in converter equipment purchases in lots of 80 to 100 cabinets. A general cost reduction was observed in all UCC-1C equipment purchases.

Other military equipments have experienced operational problems with microelectronic designs (e.g., TACAN). In view of the apparent success of the application of microelectronics in the communication terminal equipment, it might be concluded that the manufacturer of this equipment has employed special design, procurement, and production procedures to ensure successful performance.

7.1.2 Recommendation

A continuation of the study should be made with the equipment in proper configuration and properly adjusted to evaluate performance advantages that can be attributed to the microelectronic design.

Microelectronic applications should be continued in future developments and modifications of the communication telegraph terminal equipment. It is recommended that a comparative review of manufacturer procedures or techniques be conducted to establish guidelines for future procurements.

7.2 Technical Manual Instructions on the Method of Operation and Testing of Terminal Equipments

7.2.1 Conclusions

Terminal equipments were not being utilized properly, because of poor understanding of the operation, advantages, and need for proper adjustment of multi-channel telegraph-terminal equipments. In addition, the method of conducting tests was not fully understood by the technicians. Also, the manual assumes technicians will read parts of the manual other than the one that describes the test being conducted.

7.2.2 Recommendations

An application manual, directed to supervisory personnel and describing the advantages and proper method of operation, should be prepared.

Test and adjustment procedures should be clarified in the technical manual for telegraph terminal equipments.

Each test procedure described in the technical manual should reference the test book or other appropriate instructions, if they have been previously discussed, or redescribe them. In general, the technical manual should be reviewed and revised so that each set of instructions is an entity and does not assume that the technician has read previous or following sections.

7.3 Terminal Equipment Problems

7.3.1 Conclusions

No convenient indicator is provided on the terminal modules for monitoring the mode of operation or determining the existence of a malfunction in the equipment.

Periodic testing of the terminal equipments to determine performance status is not currently required.

7.3.2 Recommendations

The feasibility of incorporating a visual indication of operation mode and malfunction should be studied. An indicator should be considered for future procurements as well as for modification to existing equipments.

PMR cards for periodic testing and balancing should be initiated. This maintenance could be performed quarterly.

7.4 Test Equipment

7.4.1 Conclusion

The test equipment provided for test and checkout of terminal equipments is incomplete. Currently, keyer modules must be available for performance of the test.

7.4.2 Recommendation

A completely self-contained unit should be obtained so that the receive-only system can be tested without separate keyer modules. It is understood that the Naval Electronic Systems Command is currently investigating this problem.

7.5 Reliability of the System

7.5.1 Conclusions

The reliability of the communication network system utilizing UCC-1C or UCC-1 terminal equipments depends on the reliability of the interfacing equipments. More unsatisfactory outputs on teletype were attributed to the interfacing equipment than to the terminal equipment.

7.5.2 Recommendation

A detailed study should be conducted to evaluate and define communication problems caused by receivers and cryptograph and transmitting equipments. The evaluation should quantitatively measure the effects of these equipments on system reliability and maintainability and should result in specific recommendations for corrective actions. This study could be conducted in conjunction with the microelectronic operational performance evaluation.

7.6 MDCS Data

7.6.1 Conclusion

Although a procedure exists for reporting maintenance events through the MDCS, several additional sources of information (see Section 3.3) are required to analyze the maintenance data. Better utilization of MDCS data can be achieved from more efficient reporting.

7.6.2 Recommendation

Better instructions should be provided to the Fleet personnel for completing the MDCS forms, particularly with regard to accurate identification of the specific part name and part number of the malfunctioning parts.

APPENDIX A
IDENTIFICATION OF MONITORED AN/UCC-1C AND AN/UCC-1 EQUIPMENTS

TABLE A-1
IDENTIFICATION OF THE AN/UCC MODULES AND ASSOCIATED
COMMUNICATION EQUIPMENTS ABOARD THE USS TOPEKA

AN/UCC-1C Modules					
ARINC Research Code Number	Equipment Identification	Part Number	Serial Number	Assignments	
				Communication Channel	Frequency
CY-4	Cabinet	CY-4639/UCC-1C(V)	A-1505	1	1785
CV-17			A-1350	1	1785
CV-18			A-1463	1	425
CV-19			A-1468	1	425
CV-20	Converter	CV-1920(P) UCC-1C(V)	A-1392	2	1955
CV-21			A-1498	2	1955
CV-22			A-1384	2	595
CV-23			A-1546	2	595
CV-24					
CA-4	Control Attenuator	C-6554/UCC-1C(V)	A-114		
CY-5	Cabinet	CY-4639/UCC-1C(V)	A-1451	3	2125
CV-25			A-1470	3	2125
CV-26			A-209	3	765
CV-27			A-1318	3	765
CV-28	Converter	CV-1920(P) UCC-1C(V)	A-1433	4	2295
CV-29			A-1420	4	2295
CV-30			A-1483	4	935
CV-31			A-1547	4	935
CV-32			A-118	4	
CA-5	Control Attenuator	C-6554/UCC-1C(V)			
CY-6	Cabinet	CY-4639/UCC-1C(V)	A-1544	5	2465
CV-33			A-1432	5	2465
CV-34			A-1270	5	1105
CV-35			A-1444	5	1105
CV-36	Converter	CV-1920(P) UCC-1C(V)	A-1558	6	2635
CV-37			A-1306	6	2635
CV-38			A-1466	6	1275
CV-39			A-1590	6	1275
CV-40			A-151		
CA-6	Control Attenuator	C-6554/UCC-1C(V)			
CY-7	Cabinet	CY-4639-UCC-1C(V)	A-1521	7	2805
CV-41			A-1449	7	2805
CV-42			A-1512	7	1445
CV-43			A-1402	7	1445
CV-44	Converter	CV-1920(P) UCC-1C(V)	A-1472	8	2975
CV-45			A-1443	8	2975
CV-46			A-1453	8	1615
CV-47			A-1469	8	1615
CV-48					
CA-7	Control Attenuator	C-6554/UCC-1C(V)			
TS-1	Test Set	TS-2232 UCC-1C(V)			
AN/UCC-1 Associated Communication Equipment					
R-3	Receiver	R-1051/URR	B-1466		
R-4	Receiver	R-1051/URR	B-1488		
R-5	Receiver	AN/SRR-19A	28		
KR-9			153		
KR-10			154		
KR-11	Crypto	KG-14/TSEC	152		
KR-12			180		
KR-13			155		
KR-14			135		
KR-15	Crypto	KWR37	2883		

(continued)

TABLE A-1 (Continued)

AN/UCC-1 Modules					
ARINC Research Code Number	Equipment Identification	Part Number	Serial Number	Assignments	
				Communication Channel	Frequency
CY-1	Cabinet	CY-3956/UCC-1(V)	154	1	1785
KY-1			85	1	425
KY-2			75	2	1955
KY-3			140	2	595
KY-4			171	3	2125
KY-5	Keyer	KY-490(P)-UCC-(V)	231	3	765
KY-6			204	4	2295
KY-7			112	4	935
KY-8			56		
CA-1	Control Attenuator	C-4702/UCC-1(V)			
CY-2	Cabinet	CY-3956/UCC-1(V)	173	1	1785
CV-1			306	1	1785
CV-2			472	1	425
CV-3			478	1	425
CV-4	Converter	CV-1522(P) UCC-1(V)	461	2	1955
CV-5			440	2	1955
CV-6			444	2	595
CV-7			479	2	595
CV-8					
CA-2	Control Attenuator	C-4702/UCC-1(V)			
CY-3	Cabinet	CY-3956/UCC-1(V)	230	3	2125
CV-9			219	3	2125
CV-10			388	3	765
CV-11			387	3	765
CV-12	Converter	CV-1522(P) UCC-1(V)	297	4	2295
CV-13			330	4	2295
CV-14			382	4	935
CV-15			448	4	935
CV-16					
CA-3	Control Attenuator	C-4702/UCC-1(V)			
TS-2	Test Set	1920A/UCC-1C(V)			
AN/UCC-1C Associated Communication Equipment					
R-1	Receiver	R-1051/URR	B-1500		
R-2	Receiver	R-1051/URR	B-1447		
KR-1		KW-26(R)	1848		
KR-2		KW-26(S)	1716		
KR-3		KW-26(R)	23347		
KR-4	Crypto	KW-26(S)	23389		
KR-5		KW-26(R)	23337		
KR-6		KW-26(S)	23388		
TR-1			111		
TR-2			221		
TR-3			268		
TR-4			222		
TR-5	Transmitter	AN/WRT-2	200		
TR-6			235		
TR-7			237		
TR-8			236		

TABLE A-2
IDENTIFICATION OF THE AN/UCC-1C MODULES AND ASSOCIATED
COMMUNICATION EQUIPMENTS ABOARD THE USS CAVALIER

AN/UCC-1C Modules					
ARINC Research Code Number	Equipment Identification	Part Number (Honeywell Inc.)	Serial Number	Assignments	
				Communication Channel	Frequency
CY-1A	Cabinet	CY4639-UCC-1 UCC-1C(V)			
CV-1A			A-674	1	1785
CV-2A			A-320	1	1785
CV-2A			A-489	1	425
CV-3A			A-1023	1	425
CV-4A			A-666	2	1955
CV-5A	Converter	CV-1920P UCC-1C(V)	A-992	2	1955
CV-6A			A-667	2	595
CV-7A			A-398	2	595
CV-8A			A-170		
CA-1A	Control Attenuator	C-6554/UCC-1C(V)			
CY-2A	Cabinet	CY-4639/UCC-1C(V)			
CV-9A			A-711	3	2125
CV-10A			A-1006	3	2125
CV-11A			A-462	3	765
CV-12A			A-999	3	765
CV-13A	Converter	CV-1920(P) UCC-1C(V)	A-557	4	2295
CV-14A			A-352	4	2295
CV-15A			A-469	4	935
CV-16A			A-558	4	935
CA-2A	Control Attenuator	C-6554/UCC-1C(V)	A-199		
CY-3A	Cabinet	CY-4630-UCC-1C(V)			
CV-17A			A-4001	5	2805
CV-18A			A-3946	5	2805
CV-19A			A-4029	5	1445
CV-20A			A-4222	5	1445
CV-21A	Converter	CV-1920(P) UCC-1C(V)	A-7705	6	2975
CV-22A			A-6599	6	2975
CV-23A			A-4408	6	1615
CV-24A			A-8988	6	1615
CA-3A	Control Attenuator	C-6554/UCC-1C(V)	A-415		
TS-1A	Test Set	TS-2232/UCC-1C(V)			
AN/UCC-1C Associated Communication Equipment					
R-1A	Receiver	R-1051/URR	E-776		
R-3A	Receiver	R-1051/URR	B-832		
R-7A	Receiver	AN/SSR-19A	A-25		
KR-1A	Crypto	TSEC/KG-14	408		
KR-2A	Crypto	TSEC/KG-14	1149		
KR-3A	Crypto	TSEC/KW-37	334		
KR-4A	Crypto	TSEC/KW-37	337		

APPENDIX B
SUMMARY OF EVENTS OCCURRING
DURING SURVEILLANCE PERIOD

<p align="center">TABLE B-1</p> <p align="center">SUMMARY OF EVENTS DURING SURVEILLANCE</p> <p align="center">PERIOD ABOARD USS TOPEKA</p>					
Equipment Identification	Date/Time of Incident	Cause of Incident	Type of Incident	Corrective Action Taken	Remarks
Crypto KW-26 (AN/UCC-1)	4/25/2243	1	1	1	1
Crypto KW-26 (AN/UCC-1)	4/26/1415	1	1	1	1
Transmitter WRT-2 (AN/UCC-1)	4/27/67	WRT-2 will not lock on frequency setting	Unable to Transmit Messages	Transmitter Taken Off Line	
Receiver R1051/URR (AN/UCC-1)	4/27/1930	Frequency Drifting	Messages Garbled	Adjusted and Aligned	
Crypto KW-26 (AN/UCC-1)	4/27/2132	Crypto Out of Synchronization		Adjusted	2
Crypto KW-26 (AN/UCC-1)	4/27/2145	Crypto Out of Synchronization		Adjusted	2
Crypto KW-26 (AN/UCC-1)	4/27/2155	Crypto Out of Synchronization		Adjusted	2
Crypto KW-26 (AN/UCC-1)	4/27/2210	Crypto Out of Synchronization		Adjusted	
Crypto KW-26 (AN/UCC-1)	4/27/2220	Crypto Out of Synchronization		Secured Equipment Until Cease Fire	
Crypto KG-14 (AN/UCC-1C)	4/28/2015	Crypto Out of Synchronization	Messages Garbled	Adjusted	
R1051 Receiver (AN/UCC-1C)	4/28/2138	Poor Frequency Propagation	Garbled Messages	Adjustments	3
Crypto KG-14 (AN/UCC-1C)	4/30/0200	Crypto Out of Synchronization	Messages Garbles	Adjusted	

TABLE B-1 (continued)					
Equipment Identification	Date/Time of Incident	Cause of Incident	Type of Incident	Corrective Action Taken	Remarks
R1051 Receiver (AN/UCC-1C)	5/1/1525	Poor Frequency Propagation	Garbled Messages	None	4
R1051 Receiver (AN/UCC-1/1C)	5/1/1700	Poor Frequency Propagation	Garbled Messages	None	5
AN/UCC-1C System	5/2/0530	Unknown	Messages Garbled	None	6
AN/UCC-1C System	5/2/0640	Unknown	Messages Garbled	None	7
Crypto KW-26 (AN/UCC-1)	5/2/1815	Crypto Out of Synchronization	Messages Garbled	Adjustment	8
Crypto KG-14 (AN/UCC-1C)	5/3/1430	Crypto Out of Synchronization	Messages Garbled	Adjustment	
Receiver R1051/URR(AN/UCC-1)	5/3/1550	Frequency Drift	Messages Garbled	Tuning & Adjustment	9
Receiver R1051/URR(AN/UCC-1)	5/4/1630	Poor Frequency Propagation	Messages Garbled	Tuning & Adjustment	
Receiver R1051/URR(AN/UCC-1)	5/11/1745	Frequency Drift	Messages Garbled	Tuning & Adjustment	
Teletype (AN/UCC-1)	5/5/1530	Bad Connection on Teletype	Unable To Send Messages Via UCC-1 System	Repair Connection on Teletype	
R1051/Receiver (AN/UCC-1)	5/5/1930	Frequency Drift	Messages Garbled	Tuning & Adjustment	
R1051/Receiver	5/5/2155	RF Gain	Messages Garbled	Adjustment	
AN/UCC-1C System	5/9/1510	Unknown	Unable to Receive Messages	None	10
AN/UCC-1C System	5/10/2010	Unknown	Messages Garbled	None	11

TABLE B-1 (continued)					
Equipment Identification	Date/Time of Incident	Cause of Incident	Type of Incident	Corrective Action Taken	Remarks
R1051/Receiver (AN/UCC-1)	5/10/2020	Poor Frequency Propagation and Drift in Frequency	Messages Garbled	Adjustment	12
Crypto KG-14 (AN/UCC-1C)	5/11/2305	Switch on Crypto on Wrong Position	Messages Garbled	Receiver R1051 Tuned. Crypto Switch Placed on Correct Position	
Receiver R1051/URR (AN/UCC-1)	5/15/2015	Frequency Drift	Messages Garbled	Adjustment	
Crypto KG-14 (AN/UCC-1C)	5/16/1450	Crypto Out of Synchronization	Messages Garbled	Adjustment	
Receiver R1051.KG-14 Crypto (AN/UCC-1C)	5/16/1600	Frequency Drift/ Crypto Out of Synchronization	Messages Garbled	Adjustment	
Receiver R1051/KG-14 Crypto (AN/UCC-1C)	5/16/2100	Frequency Drift/ Crypto Out of Synchronization	Messages Garbled	Adjustment	
Receiver R1051 (AN/UCC-1)	5/16/2135	Defective Frequency Shift Band on Receiver	Unable to Receive Messages	Receiver Removed From UCC-1 System	13
Receiver R1051/KW-26 Crypto (AN/UCC-1)	5/17/1430	Frequency Drift/ Crypto Out of Synchronization	Messages Garbled	Adjustment	
AN/UCC-1C System	5/17/2040	Poor Frequency Propagation	Messages Garbled	None	14
Crypto KG-14 (AN/UCC-1C)	5/17/2220	Crypto Out of Synchronization	Messages	Adjustment	
Crypto KG-14 (AN/UCC-1C)	5/18/1330	Crypto Out of Synchronization	Messages Garbled	Adjustment	
Receiver R1051 (AN/UCC-1C)	5/18/1420	Frequency Drift	Messages Garbled	Adjustment To Receiver	

TABLE B-1 (continued)

Equipment Identification	Date/Time of Incident	Cause of Incident	Type of Incident	Corrective Action Taken	Remarks
Crypto KG-14, KW-26 (AN/UCC-1C)	5/18/1622	Crypto Out of Synchronization	Messages Garbled	Adjustment	15
R1051 (AN/UCC-1C)	5/18/1640	Frequency Drift	Messages Garbled	Adjustment To Receiver	
Crypto KG-14, KW-26 (AN/UCC-1C)	5/18/1652	Crypto Out of Synchronization	Unable to Receive Messages	Adjustment	15
Crypto KG-14, KW-26 (AN/UCC-1C)	5/18/1735	Crypto Out of Synchronization	Unable to Receive Messages	Adjustment	15
Receiver R1051/KG-14 (AN/UCC-1C)	5/19/1430	Frequency Drift/ Crypto Out of Synchronization	Messages Garbled	Adjustment	
Crypto/ KG-14, KW-26 (AN/UCC-1/1C)	5/19/1530	Crypto Out of Synchronization	Unable to Receive Messages	Adjustment	15
WRT2 Transmitter (AN/UCC-1)	5/19/1635	Power to Transmitter Off	Unable to Transmit Messages	Power Restored	
Crypto/ KG-14, KW-26 (AN/UCC-1/1C)	5/19/2045	Crypto Out of Synchronization	Unable to Receive Messages	Adjustment	15
Receiver R1051 (AN/UCC-1)	5/22/1715	Frequency Drift	Messages Garbled	Adjustment	
Receiver R1051/KG14 Crypto (AN/UCC-1C)	5/22/1740	Frequency Drift/ Crypto Out of Synchronization	Messages Garbled	Adjustment	
AN/UCC-1C System	5/22/1800	Unknown	Unable to Receive Messages	None	16
Receiver R1051/ KG-14 Crypto (AN/UCC-1C)	5/22/2150	Frequency Drift/ Crypto Out of Synchronization	Messages Garbled	Adjustment	17

TABLE B-1 (continued)

Equipment Identification	Date/Time of Incident	Cause of Incident	Type of Incident	Corrective Action Taken	Remarks
AN/UCC-1C System	5/23/1900	Unknown	Unable to Receive Messages	None	16
Receiver R1051 (AN/UCC-1C)	5/23/1930	Frequency Drift Bad Propagation Condition	Messages Garbled	Adjustment	17
Crypto KW-26 (AN/UCC-1)	5/24/1620	Crypto Out of Synchronization	Messages Garbled	Adjustment	
Receiver R1051 (AN/UCC-1)	5/24/2315	Frequency Drift	Messages Garbled	Adjustment	
Receiver R1051 (AN/UCC-1C)	5/25/1505	Frequency Drift Bad Propagation Condition	Messages Garbled	Adjustment	17
Crypto/KG-14, KW-26 (AN/UCC-1/1C)	5/25/1825	Crypto Out of Synchronization	Unable to Receive Messages	Adjustment	15
Receiver R1051 (AN/UCC-1C)	5/31/2245	Frequency Drift	Messages Garbled	Adjustment	
AN/UCC-1C System	6/1/0110	Unknown	Messages Garbled	Receiver Replaced Frequency Changed	
Receiver R1051/ (AN/UCC-1)	6/1/1435	Frequency	Messages Garbled	Adjustment	18
AN/UCC-1C Converter CV-1920(P) UCC-1C(V)	7/6/1830	Distortion at Loop Current Output	Messages Garbled	Adjustment	19
Crypto/KG-14, KW-26 (AN/UCC-1/1C)	7/7/2200	Crypto Out of Synchronization	Messages	Adjustment	20
Receiver AN/SRR-19A (AN/UCC-1C)	7/7/2340	Poor Frequency Propagation Condition	Messages Garbled	Receiver Replaced, Frequency Setting Changed	21

TABLE B-1 (continued)					
Equipment Identification	Date/Time of Incident	Cause of Incident	Type of Incident	Corrective Action Taken	Remarks
Receiver R-1051 (AN/UCC-1C)	7/9/1555	Frequency Drift	Messages Garbled	Adjustment	22
Crypto KG-14 (AN/UCC-1C)	7/9/2240	Crypto Out of Synchronization	Messages Garbled	Adjustment	
AN/SRR-19A (AN/UCC-1C)	7/9/0100	Failure of Receiver	Messages Garbled	Receiver Replaced	
AN/SRR-19A (AN/UCC-1C)	7/11/1530	Frequency Drift	Messages Garbled	Adjustment	
WRT Transmitter (AN/UCC-1)	7/11/1530	Failure of Transmitter	Unable to Transmit Messages	Transmitter Replaced	
Receiver R1051 (AN/UCC-1C)	7/12/1610	Unknown	Garbled Messages	Receiver Removed From System	23
Receiver R1051 (AN/UCC-1)	7/13/1725	Frequency Drift	Garbled Messages	Adjustment	22
Receiver AN/SRR-19A (AN/UCC-1)	7/2/1510	Poor Frequency Propagation Condition	Garbled Messages	Receiver Replaced	
AN/UCC-1	8/2/1710	Unknown	Garbled Messages	None	
Receiver R1051 (AN/UCC-1C)	8/2/1710	Frequency Drift	Garbled Messages	Adjustment	32
CV-1522(P)/ UCC-1 Converter	8/3/0225	Excessive Distortion at Loop Current Output	Messages Garbled	Adjustment*	
Crypto/ KG-14 KW-26 (AN/UCC-1/1C)	8/3/0310	Crypto Out of Synchronization	Unable to Receive Messages	Adjustment	
R1051 Receiver (AN/UCC-1C)	8/3/1850	Frequency Drift/Poor Frequency Reception	Unable to Receive Messages	Adjustment	24

TABLE B-1 (continued)

Equipment Identification	Date/Time of Incident	Cause of Incident	Type of Incident	Corrective Action Taken	Remarks
AN/UCC-1C/1 Systems	8/4/0215	Poor Frequency Reception	Unable to Receive Messages	None	25
Crypto KW-26/R1051 Receiver (AN/UCC-1C)	8/4/1350	Poor Frequency Reception	Crypto Gives Alarm Unable to Receive Messages	Adjustment	
AN/UCC-1	8/14/1520	Unknown	Unable to Receive Messages	None	26
Receiver R1051 (AN/UCC-1)	8/5/1535	Frequency Drift	Messages Garbled	Adjustment	
Receiver R1051 (AN/UCC-1)	8/6/1350	Frequency Drift	Messages Garbled	Adjustment	
Receiver R1051/KW-26 Crypto (AN/UCC-1C)	8/7/0830	Problem of Keying at the Transmit Station	Unable to Receive Messages Crypto Gives Alarm	Adjustment	27
AN/UCC-1	8/7/1240	Unknown	Unable to Receive Messages	None	
Receiver R1051 (AN/UCC-1)	8/8/1815	Poor Frequency Reception	Messages Garbled	None	28
Receiver R1051 (AN/UCC-1)	8/9/1145	Poor Frequency Reception	Messages Garbled	Adjustment	
Crypto KW-26/R1051 Receiver (AN/UCC-1)	8/9/1145	At Transmit Station	Unable to Receive Messages Crypto Gives Alarm	Adjustment	29
Receiver R1051 (AN/UCC-1)	8/9/1145	Poor Frequency Reception	Messages Garbled	Adjustment	

TABLE B-1 (continued)

Equipment Identification	Date/Time of Incident	Cause of Incident	Type of Incident	Corrective Action Taken	Remarks
Receiver R1051 (AN/UCC-1C)	8/10/1430	Frequency Drift	Messages Garbled	Adjustment	
Receiver R1051 (AN/UCC-1C)	8/10/1715	Receiver Out of Tune	Messages Garbled/ Messages Received on Wrong Channels	Adjustment/ Communi- cation Transfer From UCC-1C to UCC-1	30
Crypto KW-26 R1051 Receiver (AN/UCC-1)	8/11/1140	Bad Keying From Transmit Station	Unable to Receive Messages Crypto Gives Alarm	Adjustment	31
<p>REMARKS:</p> <p>¹Information on crypto malfunctions could not be obtained because of security reasons.</p> <p>²Guns firing.</p> <p>³Not due to receiver; poor propagation conditions.</p> <p>⁴Messages garbled due to poor propagation for 35 min. No corrective action taken.</p> <p>⁵Messages garbled due to poor propagation. No corrective action taken.</p> <p>⁶Messages garbled for 15 minutes.</p> <p>⁷Messages garbled for 10 minutes.</p> <p>⁸Poor propagation and frequency drift causing crypto to go out of synchronization.</p> <p>⁹Frequency and receiver changed.</p> <p>¹⁰Not due to any equipment aboard ship. Problem was at the transmitting station.</p> <p>¹¹Problem at the transmitting station.</p> <p>¹²Not due to receiver; poor propagation conditions.</p> <p>¹³Defective receiver was removed from the system. System was operational with only one receiver. Defective receiver was repaired upon arrival at port by shipyard personnel.</p> <p>¹⁴Not due to receiver; poor propagation conditions.</p>					

TABLE B-1 (continued)

- 15 Crypto out of synchronization because of power interruption.
- 16 Transmitting station off the air.
- 17 Bad frequency propagation conditions.
- 18 Poor frequency propagation at high-frequency setting; high-frequency receiver replaced by low-key receiver.
- 19 Incident Report No. 1.
- 20 Crypto out of synchronization because of gun fire.
- 21 Poor frequency propagation condition at low-frequency setting; low-frequency setting; low-frequency receiver was replaced by high-frequency receiver.
- 22 Receiver unable to tune properly.
- 23 System was operating with two receivers (frequency/space diversity). Removal of one receiver corrected the malfunction.
- 24 Poor frequency reception; ship approximately 1000 miles from transmitting station.
- 25 Communication with San Diego via UCC-1C discontinued; ship approximately 1200 miles from transmitting station.
- 26 Loss of communication.
- 27 Receiver adjusted but did not clear the problem. Problem at transmit station.
- 28 Poor frequency reception because of a tropical thunder storm.
- 29 Keying problem at transmitting station.
- 30 Receiver out of tune by exactly two channels. Messages were sent by transmitting station on channels 3 & 4, ship was receiving on channels 5 & 6.
- 31 Receiver adjusted but did not clear the problem.
- 32 See incident report No. 2.

<p align="center">TABLE B-2</p> <p align="center">SUMMARY OF EVENTS OCCURRING DURING SURVEILLANCE</p> <p align="center">PERIOD ABOARD USS CAVALIER</p>					
Equipment Identification	Date/Time of Incident	Cause of Incident	Type of Incident	Corrective Action Taken	Remarks
Receiver R1051 (AN/UCC-1C)	6/27/1615	Receivers Out of Adjustment		Adjusted Receivers	1
Crypto KWR-37 (AN/UCC-1C)	6/27/2125	Crypto Out of Synchronization	Messages Garbled	Adjusted Crypto & R-1A, R-3A, & R-7A	
Receiver R1051 KWR-37 Crypto (AN/UCC-1C)	7/9/2110	Receiver Out Crypto Out of Synchronization		Repaired by ET's	
Receiver AN/SRR-19 (AN/UCC-1C)	7/24/0210	Lost Broadcast on Receiver	Messages Garbled	Returned to Different Frequency	
Crypto KWR-37 (AN/UCC-1C)	7/24/0210	Crypto Out of Synchronization		Recycled Crypto	
Crypto KWR-37 (AN/UCC-1C)		Out of Synchronization		Adjusted Crypto	
Crypto KWR-37 (AN/UCC-1C)	7/27/0013	Out of Synchronization		Recycled Crypto	
AN/UCC-1C System	8/15/0300	Undetermined	Messages Garbled	---	2
Receiver AN/SRR-19 (AN-UCC-1C)	8/16/1730	Transmission Off the Air	Messages Garbled/Unable to Receive Messages	Change Frequency Reception (Receiver Adjustment)	3
AN/UCC-1C System	8/17/0500	Unknown	Unable to Receive Messages	--	4
R-1051 Receiver (AN/UCC-1C)	8/17/1900	Unexperienced Personnel Tuning The Receiver	Unable to Receive Messages	Adjustment to Receiver	

TABLE B-2 (continued)

Equipment Identification	Date/Time of Incident	Cause of Incident	Type of Incident	Corrective Action Taken	Remarks
R1051 Receiver (AN/UCC-1C)	9/1/2030	Frequency Drift	Unable to Receive Messages	Adjustment to Receiver	
AN/UCC-1C System	9/2/0130	Unknown	Unable to Receive Messages	None	
AN/UCC-1C System	9/6/1100	Unknown	Messages Garbled	None	
AN/UCC-1C System	9/6/1630	Unknown	Unable to Receive Messages	None	
AN/UCC-1C System	9/6/1927	Unknown	Unable to Receive Messages	None	
Crypto KWR-37 (AN/UCC-1C)	9/7/1850	Crypto Out of Synchronization	Messages Garbled	Adjustment	5
AN/UCC-1C System	9/8/0130	Unknown	Unable to Receive Messages	None	3
REMARKS:					
¹ Crypto gave alarm.					
² Different frequencies were selected to correct the problem. Broadcast was regained at same frequency setting at which incident occurred.					
³ Transmitting station off the air at set frequency.					
⁴ Problem at transmitting station.					
⁵ Crypto out of synchronization because of bad keying from transmitting station.					

APPENDIX C
SURVEILLANCE PROCEDURES

APPENDIX C
SURVEILLANCE PROCEDURES

1. Observer Objectives

The objectives of the ARINC Research Observer are as follows:

- A. Conduct shipboard surveillance by maintaining appropriate records for establishing the reliability, maintainability and cost effectiveness of the AN/UCC-1C and of conventional telegraph terminals.
- B. Collect all AN/UCC-1/A, B or C parts replaced during the shipboard surveillance period.
- C. Collect information on the effect that other equipments have on the operation of the AN/UCC-1A, B or C and, if time permits, additional information on reliability and maintainability data of equipments that interface with the telegraph terminal.
- D. Collect information on environmental and operational conditions that may affect equipment reliability and maintainability.

In performing the above, the emphasis will be on observing the AN/UCC terminal equipments. Data collection on interfacing equipments will be of secondary importance or as time permits.

2. Functional Procedures

In the performance of his duties the observer must rely upon cooperation of shipboard personnel. The equipment being evaluated will be operational 24 hours a day, 7 days per week. Since it will be impractical for the observer to be present this entire time, he must rely on information provided by shipboard personnel on maintenance actions taken in his absence.

In order to accomplish his objectives the observer will correlate data gathered from ships' personnel with his own observed data and transfer this data to the following reports:

- 1) Initial Report
- 2) Daily Log
- 3) Weekly Activities Report
- 4) Incident Report
- 5) Work Sheet

A description of each of these reports follows:

A. Initial Report

Prior to beginning the evaluation the observer will assign assembly code numbers to all AN/UCC and interfacing equipments, and terminal subassembly code numbers to all AN/UCC-1/A, B or C components. A description of these codes follows:

- (1) Assembly Code Number -- Alfa-numeric code assigned by the observer to identify the particular major assembly unit of the major equipment such as AN/UCC-1C, radio transmitter, etc. This code will differentiate between similar major equipments other than teletypewriters.
- (2) Terminal Subassembly Code Number -- Alfa-numeric code assigned by the observer to the components of the AN/UCC-1/A, B, or C equipments. This code will differentiate between different subassemblies (alfa- see table 1) of the UCC-1/A, B or C equipments and between similar subassemblies (numeric- see Figure 1). It is imperative that each subassembly maintain the same alfa-numeric number for the duration of the evaluation.

The observer will attach embossed tags containing these code numbers to all AN/UCC and interfacing equipments. A list will be made of the assigned assembly and terminal subassembly code numbers and the information will be tabulated in the following manner and forwarded to ARINC Research, Annapolis, during the first week of the evaluation.

SY/SUBASSY DE NO.	NAME OF EQUIPMENT	PART NO. (FSN, EIC, OR MANUFACTURER PART NO.)	SERIAL NO.	NAME OF MAN- UFACTURER (1)	* LOCATION IN SHIP	** D/T EVAL. BEGAN
----------------------	----------------------	--------------------------------------------------------	---------------	-------------------------------	--------------------------	--------------------------

- (1) Note: The manufacturer of the AN/UCC equipments are as follows:

<u>Major Equipment</u>	<u>Manufacturer</u>
AN/UCC-1	Stelma
AN/UCC-1A	American Science
AN/UCC-1B	Metro-Tel
AN/UCC-1C	M-H

- * Physical location in Ship -- Draw up on a work sheet a sketch of various compartments(not necessarily to scale), indicating the relationships of major equipments and specifying their code numbers.

** Date/Time each unit evaluation began (starting point assigned by the observer)

B. DAILY LOG

In order to observe the daily events and conditions that affect the operation of the AN/UCC and related equipments a daily log will be maintained. Entries will be made on a daily basis and will record the time of events and occurrences such as the following:

- 1) The location of the ship (in port or at sea)
- 2) Activities of the ship (participating in maneuvers, gunnery practice, refueling, etc.)
- 3) Environmental conditions (weather conditions and effects on transmitter and receivers, conditions of the sea)
- 4) Maintenance actions performed on related equipments but not effecting the operation of the AN/UCC equipments
- 5) Installation of additional equipments and/or removal of equipments from evaluation
- 6) Change of personnel
- 7) All other observed happenings that the observer feels may be of importance

Copies of the daily log will be forwarded to ARINC Research, Annapolis, on a weekly basis.

C. WEEKLY ACTIVITIES REPORT:

The observer will submit a weekly activities report summarizing significant events and conditions that occurred during the period of the week preceding the date of report. The report will contain a summary of the daily log entries and an analysis of the effects of events that were not apparent when the daily entries were made. The report will also give the status of incomplete incident reports.

D. INCIDENT REPORT

The incident report will be used for the systematic tabulation of information on maintenance actions performed on the AN/UCC and interfacing equipments. AN/UCC/A, B or C equipments will take precedence, and an incident report is to be submitted on each AN/UCC evaluation unit for each maintenance action initiated during the period of the evaluation. A maintenance action will constitute those actions necessary for retaining AN/UCC-1/A, B or C equipments in or restoring them to a normal operational condition. (Performing its intended function). Work performed on interfacing equipments for malfunctions which affect the performance of the AN/UCC equipments are included in these actions.

The reports should be forwarded to ARINC Research, Annapolis, as soon as they are completed or within one week of the occurrence whether complete or not.

E. WORK SHEET

Work sheets will be used by the observer to record general information, draw sketches and diagrams and to continue comments from the incident reports.

GENERAL INFORMATION

The following outline will be used as a guideline or base to work from while compiling information during evaluation of the AN/UCC-1 equipments. It is imperative that all subjects listed be considered for comment. However, the outline is not intended to be restrictive in any way and by no means should comments be limited only to items listed below.

1. Specific Equipment Information
 - a. Physical location (diagrams, sketches)(Initial Report)
 - b. Correlate equipment serial numbers with assigned evaluation numbers (Initial Report)
 - c. Operating hours prior to evaluation (AN/UCC units)
 - d. Daily equipment operating schedule
 - e. Associated government furnished equipment (GFE) (radio transmitters and receivers, patch panels, crypto equipment, etc., -- diagrams and sketches) (Initial report)
 - f. Adequacy of GFE
 - g. Percentage of maintenance performed at equipment, in repair shop, by shore activities (estimate)
 - h. Power supply - Initial report
 - i. Equipment history and major modifications
2. Equipment Installation and Installation Design (AN/UCC)
 - a. Is equipment design adequate? (Can equipment perform intended function?)
 - b. Wiring and cabling
 - c. Unsafe conditions
 - d. Installation problems
 - e. Suggested improvements for future installations or retrofitting existing installation
3. Equipment Design
 - a. Latches and fasteners (require only a few turns for release; require special tools; or are captive)
 - b. Access (internal and external access adequate for both visual and manipulative tasks)

- c. Packaging (mechanical disassembly required for internal access to components and parts)
 - d. Units -- parts, (plug-in nature; mechanically held; soldered)
 - e. Visual displays (visual information on equipment operation is sufficiently given within one display area; two display areas; more than two areas must be consulted to obtain sufficient information about equipment operation)
 - f. Fault and operation indicators (information provided clearly for rapid action; not clearly presented; repairs operator interpretation)
 - g. Test points (availability, identification)
 - h. Labeling (parts labeled with full identifying information, labeling clearly visible)
 - i. Adjustments (adjustment or realignment necessary to place equipment back in operation)
 - j. Testing (defective part or component can be determined without removal from ckt, requires removal)
4. Equipment Environmental Conditions
- a. Temperature
 - b. Ventilation
 - c. Space (accessibility for operation and maintenance)
 - d. Lighting
 - e. Cooling system
 - f. Unusual conditions (high seas, firing, rocket launching, etc.)
5. Test and Repair Shop Facilities
- a. Physical location with respect to operating equipment area and stock or supply room. (Initial report)
 - b. Working space
 - c. Adequate benches and stools
 - d. Lighting
 - e. Ventilation
 - f. Sufficient power sources
 - g. Hazardous working conditions
6. Test Equipment and Tools
- a. External test equipment (identification and number of pieces of external test equipment required)

- b. Availability (insufficient, or substitute equipment used)
 - c. Operating condition (operating and in calibration)
 - d. Preparation (time required to set-up)
 - e. Capabilities (gives all information needed to perform proper maintenance)
 - f. Test equipment manuals available
 - g. Handling (weight)
 - h. Presentations (easily read)
 - i. Tools (necessary tools immediately available, in good condition, substitute tools used, insufficient)
 - j. Special pieces of test equipment and tools needed
7. Technical Data (Manuals, Instructions, Plans, Schematics)
- a. Availability (necessary manuals and instructions immediately available)
 - b. Clarity (facts and procedures presented in clear and concise manner)
 - c. Accuracy (up-to-date, errors, omissions)
 - d. Completeness (required signal characteristics and/or tolerances for all test points are stated)
 - e. Schematics and circuit diagrams (availability, clarity, accuracy, completeness)
8. Supply
- a. Accessibility (spare parts immediately available-- 5 minutes, some time expended in obtaining -- 30 minutes, excessive delay, not available)
 - b. Auxiliary materials (cleaning fluids, solder, wire, etc., immediately on hand)
 - c. Parts identification (obtained quickly through use of parts lists, cross references, etc., some delay, considerable delay)
 - d. Supply forms (time required in completing)
 - e. Comparison of shipboard stores inventory to APL
9. Preventive Maintenance
- a. Planned policy and schedule (Submit samples of PMR cards)
 - b. Observed procedures

- c. Observed times PM performed
- d. Length of time required to perform PM
- 10. Organizational Procedures
 - a. Operations
 - b. Maintenance
 - c. Extra duties
 - d. Liberty and leave policies
 - e. Turnover rate
- 11. Manning
 - a. Number of personnel available for duty
 - b. Number of personnel assigned
 - c. Work schedules
 - d. Rating
 - e. Adequacy
 - f. Personnel histories of maintenance personnel (training, experience, knowledge, rating)
- 12. Training
 - a. OJT
 - b. Classroom
- 13. Forms Completed by Personnel
 - a. Daily Log
 - b. Maintenance worksheets (MDCS or other)
 - c. Supply
- 14. Problem Areas
 - a. Difficult maintenance tasks
 - b. High failure rate items
 - c. Critical adjustments required frequently
 - d. Unusual circumstances
 - e. Working conditions
 - f. Attitudes of technicians
 - g. Suggestions

DEFINITION OF TERMS CONTAINED IN ARINC RESEARCH
INCIDENT REPORT ON THE AN/UCC-1/AN/UCC-1C EVALUATION PROGRAM

PAGE 1 OF -- Insert total number of pages being submitted with this particular report form, and number each of the attached pages.

REPORT NO. -- Chronological numbering of reports beginning with #1. Under certain conditions the completion of the maintenance action may be delayed. The maximum length of time a report should be held in abeyance pending additional information is one week. If, after this time, all of the required information is not available the observer should perform the following: 1) bring the report up to date, 2) note in what respect the report is incomplete and 3) note that a follow-up report will be submitted.

If a report is forwarded by the observer to ARINC Research, Annapolis, before all entries are completed, additional report form(s) should be forwarded when the remaining information becomes available. The follow-up report forms will contain supplemental information and need repeat only pertinent information (such as contained in the form heading and blocks one and two) and changes in information contained in the original report. Follow-up reports should be labeled with the original number followed by the subletters "A", "B", etc. depending on the number of additional reports required.

Example -- A keyer fails and is immediately replaced in the cabinet by a spare keyer of the same frequency. The malfunctioned keyer is placed on the bench, but is not immediately repaired. After one week (or sooner if it is obvious to the observer that no further action will be taken in the immediate future) the observer forwards the first report and explanation to ARINC Research, Annapolis.

During the second week the keyer is analyzed and a defective resistor is to be replaced. However, the defective resistor is not available in the ships stockroom and a supply delay is experienced. The observer forwards a second report describing in detail the action taken during the second week. The report is labeled with

the original number followed by the subscript "A". (i.e. -- #1A). During the third week the resistor is obtained and maintenance is completed. The observer submits a third report containing the final information. This report is labeled with the original number followed by the subscript "B". (i.e. -- #1B)

REPORT DATE -- Date the report is forwarded to ARINC Research, Annapolis, regardless of whether or not it is complete.

1. EQUIPMENT IDENTIFICATION -- Parts A, B and C of this section identify the equipment type and the major assembly and subassembly of the failed equipment receiving the attention of the report.

- A. MAJOR ASSY -- The model or identification number of the major equipment receiving the attention of the maintenance action and/or containing the failed component. Example -- UCC-1, UCC-1A, UCC-1B, UCC-1C, and model numbers for radio transmitters and receivers, transmit and receive radio antennas, wiring and cabling, multiplexer-demultiplexer for UCC-1C equipment, patch panels, DC loop power supply, cryptographic equipment or teletypewriter equipment;
- B. ASSY CODE NO.--Alpha-numeric code assigned by the observer to identify the particular major assembly unit of the assembly identified in A above. This code will differentiate between similar major equipments other than teletypewriters (see Figure 1). The observer will forward an initial report identifying the name, manufacturer, part number and serial number of each piece of equipment and its associated assembly code number.
- C. TERM SUBASSY CODE -- Alpha-numeric code assigned by the observer to the components of the UCC-1/A, B or C equipments. This code will differentiate between different sub-assemblies (alfa- see table 1) of the UCC-1/A, B or C equipments and between similar sub-assemblies (numeric- see Figure 1). The observer will forward an initial report associating the serial number of individual cabinet, keyer, converter, attenuator, multiplexer-demultiplexer and test set with its assigned alfa-numeric subassembly code number. It is imperative that each subassembly maintain the same alfa-numeric number for the duration of the evaluation.

TABLE 1

The Alpha code for UCC-1/A, B or C subassemblies should be as follows:

<u>Code</u>	
CY	Elect equip cabinet
KY	Freq shift keyer
KY(F)	Keyer chassis assy, front
KY(R)	Keyer chassis assy, rear
CV	Freq shift converter
CV(F)	Converter chassis assy, front
CV(R)	Converter chassis assy, rear
C	Control attenuator
C(F)	Control-attenuator chassis, front
C(R)	Control-attenuator chassis, rear
TS	Test set
TD	Multiplexer-demultiplexer

NOTE: If units and assemblies in addition to those listed above are included in the evaluation, the observer will identify them with his own coding and include this coding in his initial report (see item 1B) or in an addendum to the initial report when necessary.

2. TYPE OF REPORT -- Circle one to indicate whether corrective maintenance (CM), preventive maintenance (PM) or other maintenance was performed. Other maintenance is interpreted as maintenance on equipments such as air conditioners which may effect the communication systems operations.

3. PARTS REPLACED/REPAIRED -- List all components and/or parts replaced or repaired (except teletypewriters).

- A. REF DESIG -- Should be taken from the technical manual
B. NAME -- of the equipment being repaired whenever possible. The reference designator and name of all parts repaired and/or replaced should be listed. If a malfunctioned part is replaced with a part of different design or value¹, this should be noted in block #7, "MAINT ACTION".

S/A CODE -- (UCC-1/A, B or C equipments only) If a complete subassembly such as a keyer or converter is replaced or repaired give the subassembly alfa-numeric code.

RPLMT/RPR -- Check the appropriate column to indicate whether the part or subassembly was a replacement or was repaired. If a malfunctioned part is replaced with a part of different design or value this should be noted in block #7, "MAINT ACTION".

PRI/SEC -- Check the appropriate column to indicate whether the failed part was the primary cause of failure or a secondary failure resulting from a previously failed part or condition. An explanation should be included in block #6, "DISCRIPTION OF MALFUNCTION."

ANALYSIS -- Check "Yes" or "NO" to indicate whether or not the part is being forwarded to ARINC Research, Annapolis, for further analysis. All parts on UCC-1 A, B or C equipments that are removed should be forwarded for failure analysis.

UNIT COST -- Give the unit cost of each part and/or subassembly listed. This cost will be obtainable from the ships technical supply section.

4. SYMPTOMS: FIRST NOTED - MON ____ DAY ____ TIME ____ -- Insert the month, day and time (Greenwich mean time) the symptoms were first noticed and describe the anomalous operation of the equipment that led to the discovery of the malfunctioned part.
(Example -- low meter reading, high meter reading, noise, vibrations, overheating, intermittent operation, inoperative, teletypewriter message garbling, etc.)

5. NOTED CONDITIONS: (RELATED ACTIVITIES) -- Indicate conditions or related activities at or near the time of failure that could have effected equipment operation. Examples of some conditions to be noted are:

- A. Auxillary equipment failures
 - 1) Air conditioning system
 - 2) Power supply
- B. Humidity
- C. Excessive heat or cold
- D. General maintenance
 - 1) Cleaning
 - 2) Scrubbing decks
 - 3) Welding
 - 4) Painting
 - 5) Polishing
 - 6) Chipping paint from decks (including adjacent and overhead compartments)
- E. Heavy seas or storm conditions
- F. Geographical location
- G. Ship activities
 - 1) Gunnery practice
 - 2) Missile launching
 - 3) Violent maneuvers
 - 4) Entering or leaving a communications area
 - 5) Preparation for inspection
- H. Equipment relocation
- I. Operator or maintenance technician availability

Even though the observer may not consider the above conditions to be of importance, this information will be invaluable during the final analysis in determining statistically whether or not a relationship between the failure modes and the observed conditions did exist.

6. DESCRIP OF MALF -- Give a complete and detailed description of the malfunction. State the cause of the malfunction and its effect on other components and equipments. Use the work sheet to draw diagrams and schematics. Identify by name and/or reference and mechanical condition of all failed parts. Circle either "YES" or "NO" to indicate whether or not a diagram or schematic is attached.

7. MAINT ACTION TAKEN -- In addition to an explanation of all parts repaired and/or replaced, give a detailed explanation of all other corrective and preventive maintenance actions. List all adjustments such as bias control, level control, trigger control and diversity balance control adjustments. Identify by reference designator and name each part or module replacement when the replacement is different from the original part identified in block 3.

8. MAINT TIMES -- Times required for all actions necessary for retaining an item in or restoring it to a specified condition. Since all maintenance times will not be continuous, but will be interrupted occasionally by coffee breaks, lunches, etc., several columns are included to record the date/time the maintenance action started and stopped and to record the reason for the interruption.

The date/time will be a six digit number. The first two digits will indicate the date, while the last four digits will indicate the "ZULU" time. (Example -- March 24, 2 P.M. Z will be indicated as 241400Z) The reason for interruption should be explained as briefly as possible. The observer can develop his own coding if the situation so warrants. Examples -- CB - Coffee Break, SD - Ships duties, IB - incidental break, OD- off duty for the day, MB- meal break.

- A. FAULT LOCATION -- That element of Maintenance Time during which testing and analysis is performed on an item to isolate a failure.
- B. ACTIVE REPAIR -- Active repair time includes fault correction time which is defined as that element of Maintenance Time during which a failure is corrected by (1) repairing in place (2) removing, repairing, and replacing; or (3) removing and replacing with a like serviceable item. In addition to fault correction, active repair time includes the time required to gain access to, disassemble, clean, lubricate, assemble, check-out, and adjust and calibrate the failed equipment.

Note: In the case of an item being removed and replaced with a like serviceable item, even though the item is replaced by an item with a different terminal subassembly code number, both the removal and replacement times will be included in the active repair time. In addition, the active repair time will include the time required to repair or replace the individual components of the removed item.

C. SUPPLY DELAY -- That element of Delay Time during which a needed item is being obtained from other than the designated organizational stockrooms.

Note: The administrative delay time is not tabulated on this report form but will be calculated at a later date by ARINC Research, Annapolis, using the formula.

Adm Delay Time = Total down time - (fault location time + active repair time + supply delay time)

9. A. TECH RATING -- Give the technical rating of each technician that works on the equipment during the maintenance action:

B. EMT -- Estimated maintenance time (in percentage)

Estimated percentage of the total maintenance time (clock hours) that each technician contributed to completing the maintenance action. Example -- Total maintenance time (clock time) - 100 mins. Tech A (RM3) worked on the repair the full 100 mins. Techn B (RM1) assisted A for 20 mins. and Tech C (chief Petty Officer) assisted for 10 mins. EMT's will be tabulated as follows:

Tech	EMT
RM3	100%
RM1	20%
Chief	10%

10. TEST EQUIP USED -- List all test equipment utilized during maintenance action.

11. TECH MANUALS USED -- Circle either "YES" or "NO" to indicate whether or not technical manuals were referred to during the maintenance action.

12. DEGRADATION TIME -- The date/time that the UCC-1/A, B or C equipment is degraded because of a malfunction. This time begins when the symptom is first noted and ends when the malfunction is corrected and the failed item is back in operation or when the failed item is replaced by a like serviceable item.

BEST AVAILABLE COPY

NAVSHIPS 0967-046-9010

AN/UCC-1C(V)
General Information




Figure 1-1. Telegraph Terminal AN/UCC-1C(V) Relationship of Units

- NOTES:
- VOLTAGE REQUIREMENTS:
115V OR 220V $\pm 10\%$, 14, 30 OR 40 CFS $\pm 5\%$
POWER REQUIREMENTS:
TELETYPEWRITER: 100 WATTS
CONVERTER FREQUENCY SHIFTER CV-1920/P3/UCC-1C(V): 5.3 WATTS
CONTROL ATTENUATOR C-4654/UCC-1C(V): 5 WATTS
MULTIPLEXER-DIMAPLEXER TD-460/UCC-1C(V): 20 WATTS (GFM)
TELETYPEWRITER: 100 WATTS
TELETYPEWRITER: 100 WATTS
POWER FACTOR: 1
 - CABLES 1W2, 1W5 ARE SUPPLIED.

APPENDIX D
INCIDENT REPORTS

BEST AVAILABLE COPY

Report No. 1
Report Date: July 24, 1967

AN/UCC-1C EVALUATION PROGRAM
INCIDENT REPORT - W.O. 553-01

Page 1 of 1

1. Equipment Identification:		3. Parts Replaced/Repaired				Analysis		Unit			
A. Major Assy.	AN/UCC-1C(V)	A. Ref. Desig.	B. Name	S/A Code	RPL	HPR	FRI	SEC	Yes	No	Cost
B. Assy. Code No.	CV-1920(P)UCC-1C(V)										
C. Term Subassy. Code	CV-17										

2. Type of Report: ☒ PM Other

4. Symptoms: First noted -- Mon 7 Day 6 Time 1830Z
Printing of messages was garbled on Channel # 1

AN/UCC-1C System

5. Noted Conditions: (Related Activities)

6. Descrip. of Malfunction: (Cause and Effect - Elect & Mech Cond of Parts - Names & Nos. of other Effected Assy's)

Sketch: Yes ☒ No

Converter CV-17 loop current output has a distortion between 25% to 45%

7. Maint Action Taken: (Explanation of Repairs/Replmts)

- "Delay" setting adjusted to center
- Bias setting adjusted until the distortion was minimum and channel # 1 was being printed satisfactorily

8. Maint Times		D/T Start	D/T Stop	Reason	D/T Start	D/T Stop	Reason	D/T Start	D/T Stop	Reason
A. Fault Location:		6/1830	6/1855							
B. Active Repair:		6/1855	6/1915							
C. Supply Delay:		----								

9. A. Tech Rating		B. EMT	10. Test Equip Used		11. Tech Manuals Used:		12. Degradation Time:	
ETR 2		45 min.	Telegraph Distortion Analyzer Model		Yes <input checked="" type="radio"/> No		Date/Time	
			TDA - 2NR				Assembly: Start Stop	
			(Stelma Inc.)				Subassembly: Start Stop	

BEST AVAILABLE COPY

Page 1 of 1

AN/UCC-1C EVALUATION PROGRAM
INCIDENT REPORT - W.O. 553-01

Report No. 2
Report Date: Aug. 7, 1967

1. Equipment Identification: A. Major Assy. <u>AN/UCC-1(V)</u> B. Assy. Code No. <u>CV-1522(P)/UCC-1(V)</u> C. Term Subassy. Code <u>CV-09</u> D. Type of Report: <u>CM FM Other</u>				3. Parts Replaced/Repaired <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th>A. Ref. Desig.</th> <th>B. Name</th> <th>S/A Code</th> <th>RPL</th> <th>RPR</th> <th>PRI</th> <th>SEC</th> <th colspan="2">Analysis</th> <th>Unit Cost</th> </tr> <tr> <th></th> <th></th> <th></th> <th></th> <th></th> <th></th> <th></th> <th>Yes</th> <th>No</th> <th></th> </tr> </thead> <tbody> <tr><td> </td><td> </td><td> </td><td> </td><td> </td><td> </td><td> </td><td> </td><td> </td><td> </td></tr> <tr><td> </td><td> </td><td> </td><td> </td><td> </td><td> </td><td> </td><td> </td><td> </td><td> </td></tr> <tr><td> </td><td> </td><td> </td><td> </td><td> </td><td> </td><td> </td><td> </td><td> </td><td> </td></tr> <tr><td> </td><td> </td><td> </td><td> </td><td> </td><td> </td><td> </td><td> </td><td> </td><td> </td></tr> </tbody> </table>				A. Ref. Desig.	B. Name	S/A Code	RPL	RPR	PRI	SEC	Analysis		Unit Cost								Yes	No																																									
A. Ref. Desig.	B. Name	S/A Code	RPL	RPR	PRI	SEC	Analysis		Unit Cost																																																										
							Yes	No																																																											
2. Symptoms: First noted -- Mon <u>8</u> Day <u>3</u> Time <u>0225</u> <u>Channel #3</u> Printing of messages garbled.				5. Noted Conditions: (Related Activities) 																																																															
6. Descrip. of Malf: (Cause and Effect - Elect & Mech Cond of Parts - Names & Nos. of Other Effectuated Assy's) Sketch: Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Converter CV-9 loop current output has a distortion of 45% 																																																																			
7. Maint Action Taken: (Explanation of Repairs/Replmts) 1. Delay setting adjusted to center 2. Bias setting adjusted until the distortion was minimum 																																																																			
<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th>8. Maint Times</th> <th>D/T Start</th> <th>D/T Stop</th> <th>Reason</th> <th>D/T Start</th> <th>D/T Stop</th> <th>Reason</th> <th>D/T Start</th> <th>D/T Stop</th> <th>Reason</th> </tr> </thead> <tbody> <tr> <td>A. Fault Location:</td> <td>03/0245</td> <td>03/0415</td> <td>Off Dut.</td> <td> </td> <td> </td> <td> </td> <td> </td> <td> </td> <td> </td> </tr> <tr> <td>B. Active Repair:</td> <td>03/1500</td> <td>03/1530</td> <td> </td> <td> </td> <td> </td> <td> </td> <td> </td> <td> </td> <td> </td> </tr> <tr> <td>C. Supply Delay:</td> <td>03/1530</td> <td>03/1545</td> <td> </td> <td> </td> <td> </td> <td> </td> <td> </td> <td> </td> <td> </td> </tr> </tbody> </table>										8. Maint Times	D/T Start	D/T Stop	Reason	D/T Start	D/T Stop	Reason	D/T Start	D/T Stop	Reason	A. Fault Location:	03/0245	03/0415	Off Dut.							B. Active Repair:	03/1500	03/1530								C. Supply Delay:	03/1530	03/1545																									
8. Maint Times	D/T Start	D/T Stop	Reason	D/T Start	D/T Stop	Reason	D/T Start	D/T Stop	Reason																																																										
A. Fault Location:	03/0245	03/0415	Off Dut.																																																																
B. Active Repair:	03/1500	03/1530																																																																	
C. Supply Delay:	03/1530	03/1545																																																																	
9. A. Tech Rating ETR 2 <u>2</u> hrs. <u>15</u> min.				10. Test Equip Used Telegraph distortion - Analyzer Model TDA-2NB (Stelma Inc.)			11. Tech Manuals Used: Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>			12. Degradation Time: Assembly: Start <u> </u> Stop <u> </u> SubAssembly: Start <u> </u> Stop <u> </u>																																																									

AD-A054 693


ARINC RESEARCH CORP ANNAPOLIS MD
COST-EFFECTIVENESS COMPARISON OF SHIPBOARD TELEGRAPH TERMINAL E--ETC(U)
NOV 67 M Y RAWASIA, E B BELL, C W DUKE
553-01-1-849

F/G 17/2
N00024-67-C-1182
NL

UNCLASSIFIED

2 OF 2
ADA
054693





NATIONAL BUREAU OF STANDARDS
MICROCOPY RESOLUTION TEST CHART

APPENDIX E
MDCS COMPUTER OUTPUT

NDCS GENERAL DATA RETRIEVAL

NOCS 11 FORMAT

[illegible]

BEST AVAILABLE COPY

UGC-1 & UGC-1C TERMINAL EQUIPMENT MALFUNCTION AND PARTS PROCUREMENT DATA

MDCS GENERAL DATA RETRIEVAL																			DATE PREPARED 20 SEPT 67				PAGE
																			LABOR CC HULL NO.				
																			UNPR CC HULL NO.				
																			SERIAL NOJN				
																			REFER. SYM				
																			QUANT				
																			MNRS				
																			CID/APL/AEL				
																			A UNIT				
																			MAL D				
																			ATSM				
																			RAAN				
																			AWC FSN				
																			WC CG				
																			EIC				
																			DATE AVAIL				
																			MCJ MCN				
																			DATE AVAIL				
																			EIC				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				
																			F237000				

MDCS GENERAL DATA RETRIEVAL

WDCS11-4-06304
PERIOD COVERED 01 APR 66 THRU 30 JUN 67

ET PARTS	DT	ADMIN	SAN	MCN	DATE	AVAIL	ETC	WC	AWC	RAAN	MAL	D	A UNIT	MNHR	SERIAL	NOUN	QUANT	LABOR	CC	HULL	NO.
		SC	UNIT	SAN	MCN	DATE	AVAIL	CG	FSN		ATSM		CID/APL/AEL	REFER.	SYM			UNPR	CC	HULL	NO.
		EA		5439	61026	F23					450	G	C	01			1	\$.00	K0	AGMR	0001
		EA		5440	61026	F23					450	G	C	01			1	\$.00	K0	AGMR	0001
		EA		5440	61026	F23					450	G	C	01			1	\$.00	K0	AGMR	0001
		EA		5441	61026	F23					450	G	C	01			1	\$.00	K0	AGMR	0001
				5800	61128	F237011					450	G	C	01	.5	497			80	AGMR	0001
				5808	61128	F237011					450	G	C	01	.5	508			80	AGMR	0001
				5809	61128	F237011					450	G	C	01	.5	463			80	AGMR	0001
				5911	61128	F237011					450	G	C	01	.5	424			80	AGMR	0001
				5812	61128	F237011					450	G	C	01	.5	667			80	AGMR	0001
				5813	61128	F237011					450	G	C	01	.5	519			80	AGMR	0001
				5814	61128	F237011					450	G	C	01	.5	425			80	AGMR	0001
		EA		5800	61128	F23Q14	CONVERTER						62764786			1		\$11.60	K0	AGMR	0001
		EA		5808	61128	F23Q14	CONVERTER						62764786			1		\$11.60	K0	AGMR	0001
		EA		5809	61128	F23Q14	CONVERTER						62764786			1		\$11.60	K0	AGMR	0001
		EA		5811	61128	F23Q14	CONVERTER						62764786			1		\$11.60	K0	AGMR	0001
		EA		5812	61128	F23Q14	CONVERTER						62764786			1		\$11.60	K0	AGMR	0001
		EA		5813	61128	F23Q14	CONVERTER						62764786			1		\$11.60	K0	AGMR	0001
		EA		5814	61128	F23Q14	CONVERTER						62764786			1		\$11.60	K0	AGMR	0001
				5856	61130	F237012					450	C	C	01	.5	466			80	AGMR	0001
				5857	61130	F237012					450	C	C	01	.5	527			80	AGMR	0001
				5858	61130	F237012					450	C	C	01	.5	499			80	AGMR	0001
		EA		5858	61130	F23Q14	TRANSISTOR						62764786			1		\$5.20	K0	AGMR	0001
		EA		5856	61130	F23Q14	TRANSISTOR						62764786			1		\$5.20	K0	AGMR	0001
		EA		5857	61130	F23Q14	TRANSISTOR						62764786			1		\$5.20	K0	AGMR	0001
				6647	70224	F237012					450	C	C	01	.2	482			80	AGMR	0001
				6765	70307	F237012					450	D	C	01	.1	482			80	AGMR	0001
				6766	70307	F237012					450	D	C	01	.1	456			80	AGMR	0001
				6766	70307	F237012			59608536093				62764787		ST-201	1		\$5.20	F0	AGMR	0001
		EA		6766	70316	F237012			59608536093				62764787		XSI2TOR	1		\$5.20	F0	AGMR	0001
		EA		6768	70316	F237012			59608536093				62764785		ST201	1		\$9.20	F0	AGMR	0001
		EA		6528	70321	F237010			59202849493				62764992		FUSE	450		\$.05	F0	AGMR	0001
		EA		7097	70417	F237012			59109950218				62764782		CAPACITOR	2		\$4.00	F0	AGMR	0001
		EA		7098	70417	F237012			59052793514				62764782		RESISTOR	2		\$.10	F0	AGMR	0001
		EA		6918	70501	F237012			59618536093				62764996		A14	1		\$9.20	F0	AGMR	0001
		EA		6768	70501	F237012			59618536093				62764785		ST201	1		\$9.20	F0	AGMR	0001
		EA		5291	70502	F237011			58056822954				71966089		TUNEDCKT	1		\$75.00	F0	AGMR	0001

BEST AVAILABLE COPY

MDCS11-4-06304
PERIOD COVERED 01 APR 66 THRU 30 JUN 67

MDCS GENERAL DATA RETRIEVAL

ET DT ADMIN SAN MCN DATE AVAIL EIC MCN DATE AVAIL EIC CG

PARTS SC UNIT SAN MCN DATE AVAIL EIC CG

PAGE 3
DATE PREPARED 20 SEPT 67

LABOR CC HULL NO.
UNPR CC HULL NO.

EA	7404	70515	F237012		450	C	C	01	.1	262		80	ACMR	0001		
	7404	70515	F237012	59608536093	62764991	0-14ST-201	1		\$5.20	F0	ACMR	0001				
	7853	70610	F237014		040	C	C	01	.5	A9		80	ACMR	0001		
	7852	70610	F237014		450	C	C	02	.3	A9		80	ACMR	0001		
	7851	70610	F237014		450	C	C	02	.3	A9		80	ACMR	0001		
	7873	70613	F237012		196	G	C	01	.5	378		80	ACMR	0001		
	7910	70616	F237014		450	C	C	02	.3	A6		80	ACMR	0001		
	7974	70622	F237012		450	G	C	04	.5	425		80	ACMR	0001		
	2069	70524	F237000		000	O	H	01	.2	A135		D1	AGTR	0001		
	2069	70524	F237000		AN/UCC-1C V 3									D2	AGTR	0001
	0180	61013	F237012		255	C	C	01	5.0	181		80	AGTR	0003		
	0534	70509	F237000		233	C	K	05	.3	SYSTEM		D0	AKA	0104		
	4256	70523	F237000		000	O	E	01	.5	A115		80	AD	0026		
	0115	70302	F237012		000	O	J	01	.5	H450		D0	AD	0105		
	0207	70403	E F237015	08809	161	C	T	00		A86 UCC1		80	AD	0105		
EA	0115	70404	F237012	59356655717	62981956	PLUG	1		\$1.80	F0	AD	0105				
EA	0115	70419	F237013	59359955782	58123151	CONNECTOR	1		\$8.60	F0	AD	0105				
	0650	70503	F237012		068	C	J	01	2.0	B448		D0	AD	0105		
	0115	70616	F237012		000	O	P	01	1.0	B450		D0	AD	0105		
	8089	70407	F237000		000	O	G	01	1.0	A26		81	APA	0037		
	8089	70407	F237000		TS-2232-1									82	APA	0037
	8090	70407	F237000		000	O	J	01	.1	A26		D1	APA	0037		
	8090	70407	F237000		UCC-1C-2									D2	APA	0037
	7459	70602	F237000		000	O	G	01	3.0	A26		81	APA	0037		
	7459	70602	F237000		FC3-UCC-1C									82	APA	0037

MDCS GENERAL DATA RETRIEVAL

WDCS11-4-06304
PERIOD COVERED 01 APR 66 THRU 30 JUN 67

ET PARTS	DT	ADMIN	SAN	MCN	DATE	AVAIL	ETC	WC	AWC	RAAN	MAL	D	A UNIT	MNHR	SERIAL	NOUN	QUANT	UNPR	CC	HULL	NO.
		SC	UNIT	SAN	MCN	DATE	AVAIL	ETC	CG	FSN	ATSM		CID/APL/AEL	REFER.	SYM						
					0448	60823	F237012				127	C	E	O1	1.0	A6276			80	APA	0045
					8530	70126	F237000				255	C	F	O1	50.0	C 173			80	APA	0045
		EA			0768	60991	F237011		59359216015				58123197				2	\$1.30	F0	AR	0008
		EA			0768	60991	F237010		59359216022				58123197				2	\$1.30	F0	AR	0008
					3812	60611	F237010				255	C	D	O1	1.0	MUXER UCC-1C			80	CA	0073
					9208	60701	F237012				255	C	C	O1	2.0	CV1522P UCC1V			80	CA	0073
					5328	61201	E F237000		04618		080	C	C	O1	21.0	TS 2232 UCC 1			C0	CA	0073
					5328	61201	E F237000		04618		080	C	C	O1	21.0	TS 2232 UCC1			C0	CA	0073
					7612	70106	F2A3000				161	C	D	O1	.5	MUXUCC-1C			80	CA	0073
					8598	70501	F2A2000				346	C	E	O1	2.0	UCC-1A/B			80	CA	0073
					8666	70504	F2A3000				161	C	D	O1	1.0	UCC1CVMUX			80	CA	0073
					9138	70624	F237012				161	C	D	O1	2.0	CV-1522P			80	CA	0073
					9160	70627	F237012				819	C	D	O1	2.0	CV-1522P			80	CA	0073
					1764	69516	F237012				233	C	C	O1	24.0	D15			80	CA	0148
					2777	60608	F237013				196	C	C	O1	1.0	C6			80	CA	0148
		EA			2777	60608	F237013		59608531065				58123197		CR20		1	\$5.40	F0	CA	0148
		EA			4261	60622	1 F237013		59608531065				62764781		1A2A1CR202		2	\$5.40	F0	CA	0148
		EA			0759	60719	1 F237012		59619683858				62764781		ALCR7D10DE		2	\$7.70	F0	CA	0148
		EA			0873	60801	1 F237015		59359645468				89162001		2P1		8	\$2.00	F0	CA	0148
		EA			0874	60801	1 F237015		59358146598				89162001		2P4		4	\$3.30	F0	CA	0148
		EA			0875	60801	1 F237015		59358791813				89162001		2P5		4	\$4.30	F0	CA	0148
					1346	70117	F237000				450	C	J	O1	10.0	C8			D0	CA	0148
		EA			1372	70125	1 F237012		59608536093				62764782		1A2A1Q14		2	\$11.60	F0	CA	0148
		FA			1373	70125	1 F237012		59608786521				62764782		1A2A1Q9		6	\$7.41	F0	CA	0148
					7341	70328	F237012				161	C	C	O1	.5	C21			80	CA	0148
					7342	70328	F237012				161	C	C	O1	1.0	701			80	CA	0148
		EA			7342	70328	1 F237012		59618786521				62704789		1A2A1Q11		3	\$7.41	F0	CA	0148

MDCS GENERAL DATA RETRIEVAL

MDCS11-4-06304
 PERIOD COVERED 01 APR 66 THRU 30 JUN 67

ET	DT	ADMIN	SAN	MCN	DATE	AVAIL	EIC	WC	AHC	RAAN	MAL	D	A UNIT	CID/APL/AEL	MMHRS	SERIAL	NOUN	QUANT	LABOR CC	HULL	NO.	
PARTS		SC	UNIT	SAN	MCN	DATE	AVAIL	EIC	CG	FSN	ATSH					REFER.	SYM		UNPR	CC	HULL	NO.
				8859	70304	F237012					127	C D OI			.4	250				80	CAG	0001
				8866	70304	F237011					127	C D OI			.4	141				80	CAG	0001
				8869	70304	F237011					127	C D OI			.4	208				80	CAG	0001
				8873	70304	F237011					127	C D OI			.4	56				80	CAG	0001
		EA		8518	70306	F237012		59108501502				62765102			1A1C22			1	\$1.10	F0	CAG	0001
		EA		8518	70306	F237012		59608531065				62765102			A1CR20			1	\$1.10	F0	CAG	0001
		EA		7242	70307	F237012		59352593608							1A2J-1			1	\$5.40	F0	CAG	0001
		EA		8507	70307	F237012		59618531065				62765102			1A1CR20			1	\$1.10	F0	CAG	0001
		EA		8518	70307	F237012		59608786521				62765107			2N40A4			1	\$.31	F0	CAG	0001
		EA		7242	70308	F237012		59350793487				62765108			1XA-1			1	\$3.00	F0	CAG	0001
		EA		9128	70308	F237012		59608786521				62765108			1A1Q7/2N40			2	\$.31	F0	CAG	0001
		EA		8518	70312	F237012		59608453954				62765108			1A1Q11/2N3			1	\$3.90	F0	CAG	0001
				9414	70313	F237012					127	C E OI			.3	C285CV1522				80	CAG	0001
				9415	70313	F237012					127	C E OI			.5	C208CV1522				80	CAG	0001
				9416	70313	F237012					127	C E OI			.5	C370CV1522P				80	CAG	0001
				9417	70313	F237012					127	C E OI			.3	C291CV1522 P				80	CAG	0001
				9419	70313	F237012					127	C E OI			.3	C337CV1522 P				80	CAG	0001
				9420	70313	F237012					242	C C OI			.7	C250CV-1522 P				80	CAG	0001
				9412	70313	F237012					127	C E OI			.3	C304CV1522				80	CAG	0001
				9411	70313	F237012					127	C E OI			.3	C324CV1522				80	CAG	0001
				9413	70313	F237012					127	C E OI			.3	C393CV1522				80	CAG	0001
				9418	70313	F237012					127	C E OI			.3	C258CV1522 P				80	CAG	0001
				8518	70313	F237012					242	C C OI			40.0	C363CV1522				80	CAG	0001
				9128	70313	F237012					242	C C OI			6.0	C231CV1522				80	CAG	0001
				9407	70313	F237012					127	C E OI			.3	C443				80	CAG	0001
				9408	70313	F237012					127	C E OI			.3	C246				80	CAG	0001
				9409	70313	F237012					127	C E OI			.3	C475				80	CAG	0001
				9410	70313	F237012					127	C E OI			.3	C361				80	CAG	0001
		EA		9420	70313	F237012		59202849493				62765108			1A2F1FUSE			1	\$1.10	F0	CAG	0001
		EA		3242	70322	F237012		59352593608				62765108			1-J-1			1	\$5.40	F0	CAG	0001
		EA		9168	70412	F237000		59156909400				62765110			1A2FL-1			1	\$218.00	F0	CAG	0001
		EA		8518	70603	F237012		59608360382				62765102			A1CR21			1	\$3.30	F0	CAG	0001
		EA		6684	60521	F237010		59356655717							CONNECTOR			2	\$3.00	F0	CAG	0002
		EA		5725	60527	F237012		59350606774				58123197			1A2TP3			5	\$.25	F0	CAG	0002
				6725	60623	F237000					000	O J OI			2.0	A144017				D0	CAG	0002

BEST AVAILABLE COPY

MDCS GENERAL DATA RETRIEVAL

MDCS11-4-05304
PERIOD COVERED 01 APR 66 THRU 30 JUN 67

ET	DT	ADMIN	SAN	MCN	DATE	AVAIL	EIC	WC	AWC	RAAN	MAL	D	A UNIT	MNHR	SERIAL	NOUN	LABOR	CC	HULL	NO.
PARTS	SC	UNIT	SAN	MCN	DATE	AVAIL	EIC	CG	FSN		ATSM	CID/APL/AEL	REFER.	SYM	QUANT		UNPR	CC	HULL	NO.
EA				2161	60415		F237012		59605834410		068	C	F	01	1.0	CV1522P/UCC-1		80	CC	0001
EA				2358	60509		F237012		59618536093		000	D	E	01	1.0	CV1522P A10		80	CC	0001
EA				2359	50509		F237012		59618536093		000	D	E	01	3.5	CV1522P D23		80	CC	0001
EA				0854	61122	1	F237010		59617525229		62764781				TRANSISTOR	2	\$1.80	F0	CC	0001
EA				0854	61212	1	F237010		59617525229		62764781				TRANSISTOR	6	\$9.20	F0	CC	0001
EA				0854	61227	1	F237010		59618453954		62764781				TRANSISTOR	10	\$3.32	F0	CC	0001
EA				0854	61227	1	F237010		59618453954		62764781				TRANSISTOR	6	\$2.70	F0	CC	0001
EA				0854	61229	1	F237010		59617525229		62764781				TRANSISTOR	9	\$3.32	F0	CC	0001
EA				0854	61230	1	F237010		59619683858		62764781				CR13010DE	10	\$1.13	F0	CC	0001
EA				0854	61231	1	F237010		59605776084		62981956				CR1010DE	4	\$1.00	F0	CC	0001
EA				0854	70103	1	F237010		59618531065		62981956				CR83010DE	3	\$1.10	F0	CC	0001
EA				6623	70110	1	F237010		59052793500		62764781				R23RESISTO	4	\$1.10	F0	CC	0001
EA				6623	70110	1	F237010		59108195745		62764781				C21CAPACIT	4	\$3.38	F0	CC	0001
EA				6623	70114	1	F237010		59617525229		62764781				2N404TRANS	4	\$3.32	F0	CC	0001
EA				6623	70114	1	F237010		59106443595		62981956				C-21CAPACI	3	\$3.36	F0	CC	0001
EA				6623	70114	1	F237010		59618360382		62764781				IN3022BDIO	5	\$1.20	F0	CC	0001
EA				6623	70117	1	F237010		59610692110		62764781				Q1TRANSIST	8	\$1.20	F0	CC	0001
EA				6623	70117	1	F237010		59600692110		62764781				1A2A1QTRAM	3	\$2.60	F0	CC	0001
EA				6623	70117	1	F237010		59058826380		62764781				1A2A1R41RF	1	\$5.70	F0	CC	0001
EA				6623	70117	1	F237010		59108335912		62764781				1A2A1C-15C	2	\$3.32	F0	CC	0001
EA				6623	70124	1	F237010		59202849493						FUSE1A1A2F	29	\$3.07	F0	CC	0001
EA				0854	70126	1	F237010		59618360382		62764781				CR21010DE	6	\$1.20	F0	CC	0001
EA				6891	70130	1	F237010		59202804045						FUSEHOLDER	10	\$3.05	F0	CC	0001
EA				6891	70206	1	F237010		59202215673						FUSEHOLDER	10	\$3.18	F0	CC	0001
EA				6623	70213	1	F237010		59109950218						1A2A1C-21C	6	\$2.70	F0	CC	0001
EA				6623	70213	1	F237010		59057028070						1A2A1R-31R	6	\$6.50	F0	CC	0001
EA				6623	70217	1	F237010		59619683858						1A2A1CR70I	12	\$3.10	F0	CC	0001
EA				6623	70217	1	F237010		59502258123						1A2A1T3TRA	5	\$9.50	F0	CC	0001
EA				6623	70217	1	F237010		59507194325						1A2A111ND	6	\$8.00	F0	CC	0001

BEST AVAILABLE COPY

PAGE 8

DATE PREPARED 20 SEPT 67

MOCS GENERAL DATA RETRIEVAL

MOCS11-4-G6304
PERIOD COVERED 01 APR 66 THRU 30 JUN 67

ET	DT	ADMIN	SAN	MCN	DATE	AVAIL	ETC	MC	AWC	RAAN	MAL	ATSM	CID/APL/AEL	MMHRS	SERIAL	NOJN	QUANT	LABOR	CC	HULL	ND.
PARTS	SC	UNIT	SAN	MCN	DATE	AVAIL	ETC	CG	FSN						REFER.	SYM		UNPR	CC	HULL	ND.
EA				6623	70217	1	F237010		59108927871						1A2A1C7CAP	8		\$.21	F0	CC	0001
EA				6623	70217	1	F237010		59507994163						1A2A1Y-1TR	4		\$6.90	F0	CC	0001
EA				6623	70220	1	F237010		59502258123						1A2A1T3TRAN	3		\$9.50	F0	CC	0001
EA				6891	70318	1	F237010		59156822947						FILTER	2		\$161.00	F0	CC	0001
				6953	70327		F237011			242	A	C	01		8-0 306				80	CC	0001
				6952	70327		F237012			242	A	C	01		8-0 528				80	CC	0001
				6909	70327		F237000			700	C	C	01		9-9 A-10				80	CC	0001
				6891	70327		F237000			700	C	C	01		9-0 A-10				80	CC	0001
				6879	70327		F237000			700	C	C	01		6-0 P-23				80	CC	0001
EA				6909	70328	1	F237010		59106882822						C-13	4		\$.38	F0	CC	0001
EA				6909	70328	1	F237010		59202849493						FUSE1/RAMP	20		\$.07	F0	CC	0001
EA				6891	70417	1	F237010		59156822946						FILTER	2		\$48.00	F0	CC	0001
EA				6952	70420	1	F237010		59506822861						DISCRIMNAT	1		\$147.00	F0	CC	0001
EA				6953	70420	1	F237010		59351924789						JACKV-1	4		\$.31	F0	CC	0001
EA				6891	70420	1	F237010		59107173635						CAPACITOR	3		\$1.00	F0	CC	0001
EA				6879	70420	1	F237010		59351924789						JACK	4		\$.31	F0	CC	0001
EA				6991	70421	1	F237010		59156822969						FILTER	2		\$72.00	F0	CC	0001
EA				6891	70421	1	F237010		59156909405						FILTERFLY	1		\$209.00	F0	CC	0001
EA				6952	70423	1	F237010		59352593608						JACKV-1	1		\$5.40	F0	CC	0001
EA				6953	70423	1	F237010		59508800427						CHOK	2		\$.81	F0	CC	0001
EA				6891	70423	1	F237010		59108805433						CAPACITOR	4		\$.36	F0	CC	0001
EA				6909	70423	1	F237010		59109950218						C-13	3		\$1.60	F0	CC	0001
EA				6909	70423	1	F237010		59107818983						C-8	4		\$.73	F0	CC	0001
EA				6879	70423	1	F237010		59109950218						CAPACITOR	6		\$1.60	F0	CC	0001
EA				6891	70423	1	F237010		59108927871						CAPACITOR	3		\$.73	F0	CC	0001
EA				6879	70423	1	F237010		59108927600						CAPACITOR	5		\$1.20	F0	CC	0001
EA				6953	70429	1	F237010		59502258123						TRANSFORME	2		\$9.50	F0	CC	0001
EA				6909	70504	2	F237010		58206822870						KEVERIAIAI	1		\$360.00	F0	CC	0001
				6623	70508		F237010			161	C	C	01		6-0 475				80	CC	0001
EA				6953	70510	1	F237010		59618786521						TRANSISTOR	10		\$.35	F0	CC	0001
				5038	60403		F237000			346	C	H	01		-2 026				00	CC	0002
				5040	60403		F237000			346	C	H	01		-2 A3				00	CC	0002
				5041	60403		F237000			346	C	H	01		-2 A4				00	CC	0002
				5039	60403		F237000			346	C	H	01		-2 A2				00	CC	0002

BEST AVAILABLE COPY

MDCS GENERAL DATA RETRIEVAL

MDCS11-4-06304
PERIOD COVERED 01 APR 66 THRU 30 JUN 67

ET	DT	ADMIN	SAN	MCN	DATE	AVAIL	EIC	WC	AWC	RAAN	MAL	D	A	UNIT	MNHR	SERIAL	NOUN	QUANT	LABOR	CC	HULL	NO.
PARTS	SC	UNIT	SAN	MCN	DATE	AVAIL	EIC	CG	FSN	ATSM	CID/APL/AEL	REFER.	SYM						UNPR	CC	HULL	NO.
5321	EA				60425	F237012					161	C	C	01		1.0	167			80	CC	0002
5322	EA				60425	F237012					161	C	C	01		1.0	232			80	CC	0002
5342					60502	F237012					161	C	J	01		1.5	102			00	CC	0002
5321	EA				60504	F237012			59608552537		58123197					0145T205	5		\$1.50	F0	CC	0002
5321	EA				60504	F237012			59608536093		58123197					0125T201	5		\$11.60	F0	CC	0002
5342					60607	F237012					161	C	C	01		1.5	102			00	CC	0002
5342	EA				60609	F237012			59506822980		58123197					STELLMA C5	1		\$75.00	F0	CC	0002
5698	EA				60721	F237011			59051923971		58123197					3301/2W	2		\$.03	F0	CC	0002
5698	EA				60721	F237011			59109950218		58123197					60MFDCAP	1		\$4.00	F0	CC	0002
0098	EA				60728	F237011			59109950218		58123197					C2C360FDCA	2		\$4.00	F0	CC	0002
0059					60802	F237011					428	C	C	01		2.5	A3CHANNEL 4			80	CC	0002
5038					60802	F237000					346	C	C	01		43.0	D26			00	CC	0002
5039					60802	F237000					346	C	D	01		43.5	A2			00	CC	0002
5040					60802	F237000					346	C	D	01		15.5	A3			00	CC	0002
5041					60802	F237000					346	C	D	01		14.0	A4			00	CC	0002
0156	EA				60809	F237000			59618536093		58123197					ST201	4		\$9.20	F0	CC	0002
0469					60910	F237011					068	A	C	01		1.5	AN/UCC-1V			80	CC	0002
0156	EA				60919	F237000			59208453954		58123197					2N329A	3		\$.09	F0	CC	0002
0722					60928	F237011					068	C	C	01		3.0	D26			80	CC	0002
0722	EA				60928	F237011			59109950218		58123197					C13	2		\$4.00	F0	CC	0002
0722	EA				60928	F237011			59052792626		58123197					680 1W	5		\$.10	F0	CC	0002
0757					60930	F237011					068	A	C	01		4.0	D26			80	CC	0002
0757	EA				61003	F237011			59051956761		58123197					R81-R83	5		\$.04	F0	CC	0002
0757	EA				61003	F237011			59052499468		58123197					R183	5		\$.07	F0	CC	0002
0757	EA				61003	F237011			5905292000		58123197					R1	5		\$.60	F0	CC	0002
0156	EA				61006	F237000			59618431009		58123197					2N404A	4		\$.46	F0	CC	0002
1050	EA				61107	F237011			59606829178		58123197					2N404	2		\$.50	F0	CC	0002
5078					70105	F237012					255	A	C	01		2.0	210			80	CC	0002

BEST AVAILABLE COPY

PAGE 11
DATE PREPARED 20 SEPT 67

MOCS GENERAL DATA RETRIEVAL

MOCS11-4-06304
PERIOD COVERED 01 APR 66 THRU 30 JUN 67

FT	DT	ADMIN	SAN	MCN	DATE	AVAIL	EIC	WC	AMC	RAAN	MAL	D	A	UNIT	MNHS	SERIAL	NRJN	LABOR	CC	HULL	NO.
PARTS	SC	UNIT	SAN	MCN	DATE	AVAIL	EIC	CG	FSN		ATSM	CID/APL/AEL	REFER.	SYM	QUANT			UNPR	CC	HULL	NO.
EA				7325	60607	1	F237011		59507805568			71966081				T10UTPUTXF	1	\$35.00	F0	CG	0012
				5630	61121		F237000			255	C	J	01			9.5	4296		D0	CGM	0009
				5630	61212		F237000			255	C	C	01			4.5	4296		D0	CGM	0009
EA				2523	60817		F237012		59507246731			58120154				1A2T1	6	\$15.00	F0	CLG	0003
				8356	70209		F2A1000			000	D	J	01			5.0	AU09		D0	CLG	0003
				8356	70522		F237000			000	D	M	01			2.0	A109		D0	CLG	0003
				9742	60708		F237000			000	D	J	01			.5	A212		D0	CLG	0004
EA				9742	60808	1	F237010		59358271545			61399554				PLUG	4	\$6.00	F0	CLG	0004
EA				9742	60810	1	F237010		59358168643			61399554				PLUG	4	\$5.70	F0	CLG	0004
				1495	60907		F237000			000	D	E	01			1.0	A212		80	CLG	0004
EA				5371	61227	1	F237011		58059216019			62264007				IC-1MICROC	1	\$7.20	F0	CLG	0004
				5371	70127		F237000			068	A	C	01			4.0	738		80	CLG	0004
EA				3200	60501		F237010		59358151541			62982108				PLUGELECT	7	\$2.70	F0	CLG	0305
				3352	60516		F237012			255	C	J	01			3.0	625		D0	CLG	0005
EA				3684	60620		F237000		59358168643			62981956				PLUG	4	\$5.70	F0	CLG	0005
EA				2729	61025		F237011		9623805343200416			71966095				FILTER	1	\$248.75	P0	CLG	0005
				3022	61031		F237010			255	C	C	02			3.0	A71		80	CLG	0305
EA				3022	61101		F237010		59156822966			62264000				FILTER	1	\$50.00	F0	CLG	0005
EA				3022	61101		F237010		59156909398			62264000				FILTER	1	\$128.00	F0	CLG	0005
				3161	61119		F237000			000	D	J	01			.1	AN/UCC-1CV		D1	CLG	0005
				3160	61119		F237000			000	D	J	01			.1	AN/UCC-1CV		D1	CLG	0005
				3160	61119		F237000					FIELDCHANGE01							D2	CLG	0005
				3161	61119		F237000					FIELDCHANGE02							D2	CLG	0005
				2792	70117		F237011			004	C	C	01			1.0	94		D0	CLG	0005
EA				3352	70514		F237012		59156909398			62764788				FILTER	1	\$128.00	F0	CLG	0005

MDCS GENERAL DATA RETRIEVAL

WDCSI1-4-06304
PERIOD COVERED 01 APR 66 THRU 30 JUN 67

ET	DT	ADMIN	SAN	MCN	DATE	AVAIL	EIC	WC	AMC	RAAN	MAL	D	A	UNIT	MNHR	SERIAL	QUANT	LABOR	CC	NO.	
PARTS		SC	UNIT	SAN	MCN	DATE	AVAIL	EIC	CG	FSN	ATSM				REFER.	SYM		UNPR	CC	MULL	NO.
		EA		5435	60406	F237011	F237011	59108826695						71966095	22UF35VDC	1		\$1.20	F0	CLG	0006
		EA		5435	60406	F237011	F237011	59108927871						71966095	15UF20VDC	2		\$.68	F0	CLG	0006
				7698	60505	F237000	F237000				Q01	0	A	01	.2	AN/UCC1V			B0	CLG	0006
				7699	60505	F237000	F237000				Q01	0	A	01	.2	AN/UCC1V			B0	CLG	0006
		EA		8331	70104	F237000	F237000	58206822870							KEYERSURAY	1		\$250.00	F0	CLG	0006
				8331	70111	F237011	F237011				000	0	B	01	.1	AN/UCC1VKEYER			B0	CLG	0006
		EA		7822	70202	F237011	F237011	58059216019							A1A11C1	6		\$7.20	F0	CLG	0006
				6940	70224	F237011	F237011				276	C	C	01	1.5	ANUCC-1C			B0	CLG	0006
		EA		6940	70224	F2A3000	F2A3000	59052791979						71966107	R33	2		\$.12	F0	CLG	0006
		EA		6942	70224	F2A3000	F2A3000	59052549201						71966087	1A1A1R20	2		\$.04	F0	CLG	0006
		EA		9553	70224	F2A3000	F2A3000	58059216019							A1A11C1	10		\$7.20	F0	CLG	0006
		EA		6955	70301	F237012	F237012	58056822972						62764995	1A2A1	1		\$250.00	F0	CLG	0006
		EA		0503	70303	F2A3000	F2A3000	59359216015						62764994	CONNSECT	1		\$1.30	F0	CLG	0006
				0506	70304	F2A3000	F2A3000				008	C	K	01	.5	ANUCC1C			D0	CLG	0006
		EA		0555	70309	F2A3000	F2A3000	59052791979						71966098	R33	1		\$.12	F0	CLG	0006
				9553	70403	F2A3000	F2A3000				255	A	C	05	20.0	AN/UCC-1CSNED			B0	CLG	0006
		EA		1645	70403	F2A3000	F2A3000	59358168643						58123153	CONNECTR	1		\$5.70	F0	CLG	0006
				6942	70405	F2A3000	F2A3000				900	C	C	01	.2	AN/UCC-1CKEYE			B0	CLG	0006
				6955	70405	F237012	F237012				161	C	C	01	1.0	AN/UCC-1			B0	CLG	0006
				0503	70405	F2A3000	F2A3000				000	0	P	01	.5	AN/UCC-1CKEYE			B0	CLG	0006
				0753	70405	F237012	F237012				161	C	J	01	.4	AN/UCC-1CCONV			D0	CLG	0006
				0728	70405	F237011	F237011				161	C	J	01	2.0	AN/UCC-1CKEYE			D0	CLG	0006
				3365	70417	F2A3000	F2A3000				161	C	C	01	9.0	AN/UCC-1CKEYF			B0	CLG	0006
				0506	70418	F2A3000	F2A3000				008	C	C	01	.2	AN URC1C			D0	CLG	0006
		EA		0753	70608	F2A3000	F2A3000	58059257259						58123153	1A2A1CONVC	1		\$50.00	F0	CLG	0006
		EA		0728	70615	F2A3000	F2A3000	58059257257						58123153	CARD	1		\$184.00	F0	CLG	0006
		EA		4314	70322	H	F237000	58153700827						2839405		1		\$.00	F0	CLG	0007

BEST AVAILABLE COPY

MDCS11-4-06304
PERIOD COVERED 01 APR 56 THRU 30 JUN 67

MDCS GENERAL DATA RETRIEVAL

ET DT ADMIN SAN MCN DATE AVAIL EIC MCN DATE AVAIL EIC MCN DATE AVAIL EIC

PARTS SC UNIT SAN MCN DATE AVAIL EIC MCN DATE AVAIL EIC MCN DATE AVAIL EIC

PAGE 13
DATE PREPARED 20 SEPT 67

LABOR CC HULL NO.
UNPR CC HULL NO.

EA	0036	60809	F237012	090	C	J	03	1-2	1543	50.0	1543	ANUCC1	5	00	CLG	0008
EA	0041	61013	F237012	62264	008			TRASISTOR					5	00	CLG <td>0008</td>	0008
	0036	61015	F237012	080	C	C	03	50.0	1543	ANUCC1				00	CLG <td>0008</td>	0008
	8227	70321	F237012	450	C	D	01	1-2	263					80	CLG <td>0008</td>	0008
	8006	70621	F2A3000	000	D	E	32	7.0	UCCICCONVERT					80	CLG <td>0008</td>	0008
	4192	70206	F237012	255	C	C	01	2-5	8245					80	CVA <td>0019</td>	0019
	4201	70207	F237011	161	C	C	01	2-0	C5					80	CVA <td>0019</td>	0019
	4210	60805	F237011	450	C	J	01	5-0	A425					00	CVA <td>0034</td>	0034
	7086	70403	F237015	000	D	E	01	.5	C54					80	CVA <td>0034</td>	0034
	1209	60425	F237011	068	A	J	01	1-0	D47					00	CVA <td>0042</td>	0042
	2657	60706	F237010	360	C	C	01	10-0	02					80	CVA <td>0042</td>	0042
EA	2657	60706	F237010	59357553804				1J8					1	F1	CVA <td>0042</td>	0042
AV	2657	60706	F237010	58206822870				1A1A1					1	F1	CVA <td>0042</td>	0042
	2932	60820	F237012	068	C	C	01	1-0	D3					80	CVA <td>0042</td>	0042
	1209	60820	F237011	068	A	C	01	.5	D3					00	CVA <td>0042</td>	0042
EA	1209	60820	F237011	59507246731				UCC1					1	F0	CVA <td>0042</td>	0042
EA	2932	60820	F237012	59610692110				TRANSISTOR					1	F1	CVA <td>0042</td>	0042
EA	2932	60820	F237012	59618343194				TRANSISTOR					1	F1	CVA <td>0042</td>	0042
	2943	60824	F237012	068	C	C	01	2-0	D3					80	CVA <td>0042</td>	0042
EA	2943	60824	F237012	59610692110				CUI522PUCC1	TRANSISTOR				1	F0	CVA <td>0042</td>	0042
	6863	60902	F237012	068	C	J	01	3-0	C58					00	CVA <td>0042</td>	0042
	7197	61104	F237012	068	C	C	01	2-0	C47					80	CVA <td>0042</td>	0042
EA	7197	61104	F237012	59618166237				CUI522PUCC1	A102				1	F0	CVA <td>0042</td>	0042
EA	7197	61104	F237012	59610692110				CUI522PUCC1	A101				1	F0	CVA <td>0042</td>	0042
	7210	61107	F237012	068	C	C	01	2-0	D3					80	CVA <td>0042</td>	0042

APR 66 THRU 30 JUN 67

MDCS GENERAL DATA RETRIEVAL

QUANT	UNION
-------	-------

PAGE 14
DATE PREPARED 20 SEPT 67

BEST AVAILABLE COPY

ET PARTS	DT	ADMIN SC UNIT SAN	MCN	DATE DATE AVAIL	ETC	WC CG	AWC FSN	RAAY	MAL ATSM	D	A UNIT CID/APL/AEL	MMHRS REFER.	SERIAL SYM	NOUN QUANT	LABOR UNPR	CC	HULL NO.
EA			7210	61107	F237012		59618536093			CV1522P	1A014			1	\$9.20	F0	CVA 0042
			0188	70526	F237011				450	C D 01	1.5 D2					B0	CVA 0042
			6863	70529	F237012				068	C C 01	6.0 C58					D0	CVA 0042
			6863	70529	F237012		59618166237				1A2A02			1	\$1.50	F1	CVA 0042
EA			8005	70503	F237000				750	E J 02	UCC 1					D0	CVA 0059
			2614	60425	F237011				462	C D 01	-2 B75					B0	CVA 0060
			2615	60425	F237011				462	C D 01	-2 B65					B0	CVA 0060
			2618	60425	F237011				462	C D 01	-2 B26					B0	CVA 0060
			2616	60425	F237011				462	C D 01	-2 B69					B0	CVA 0060
			1465	60615	F237010				099	C D 01	30.0 C4					B0	CVA 0060
			7194	61010	F237000				068	C D 01	18.0 C4					B0	CVA 0060
			2394	70106	F237010				255	E C 01	2.0 B11					B0	CVA 0060
EA			2394	70106	F237010		59205772264			62764781	HOLDER			4	\$1.20	F0	CVA 0060
			2646	70410	F237000				255	C J 01	4.0 B20					D0	CVA 0060
			5583	70424	F237012				000	D E 01	1.5 358					R0	CVA 0060
			5695	70426	F237012				000	D E 01	10.0 358					B0	CVA 0060
			0127	70510	F237011				068	C D 01	1.0 C4					B0	CVA 0060
			0413	70612	F237000				099	K K 01	1.0 A458					D0	CVA 0060
			0412	70612	F237000				099	K K 01	1.0 A400					D0	CVA 0060
			0414	70612	F237000				099	K K 01	1.0 A122					D0	CVA 0060
			0415	70612	F237000				099	K K 01	1.0 A126					D1	CVA 0060
			0415	70612	F237000				ANUCCICV 2							D2	CVA 0060
			7290	70628	F237000				255	C J 01	1.5 A2014					D0	CVA 0060
			2867	60801	F237010				472	C C 01	2.0 ANUCCIC11V1					B0	CVA 0062
EA			2867	50801	F23F1									1	\$1.10	K0	CVA 0062
EA			7901	60911	F237000		59059511424				1A1A1R7			1	\$1.50	F0	CVA 0062

MDCS11-4-06304
PERIOD COVERED 01 APR 56 THRU 30 JUN 67

MDCS GENERAL DATA RETRIEVAL

PAGE 15
DATE PREPARED 20 SEPT 67

ET	DT	ADMIN	SAN	MCN	DATE	AVAIL	EIC	WC	AWC	RAAN	MAL	D	A	UNIT	MMHRS	SERIAL	NOIN	QUANT	LABOR	CC	HULL	NO.
PARTS	SC	UNIT	SAN	MCN	DATE	AVAIL	EIC	CG	FSN	ATSM	CID/APL/AEL	REFER.	SYM						UNPR	CC	HULL	NO.
				0296	61112		F237000			054	C	J	O1		3.0	42				D0	CVA	0062
				0278	60602		F237012			127	A	E	O1		1.0	A76				R0	CVA	0064
				0279	60602		F237012			127	A	E	O1		.5	A98				R0	CVA	0064
				0277	60602		F237012			127	A	E	O1		.5	A97				H0	CVA	0064
				0984	60614		F237012			255	A	J	O1		.5	462				D0	CVA	0064
				1360	60614		F237012			255	A	J	O1		.5	449				D0	CVA	0064
				1359	60614		F237012			255	A	J	O1		.5	350				D0	CVA	0064
EA				1360	60626		F237012		59608536093								1		\$9.20	F0	CVA	0064
				0274	60704		F237012			255	A	J	O1		.5	A430				F0	CVA	0064
EA				0273	60704		F237012		59608453954								1		\$3.90	F0	CVA	0064
EA				0749	60708		F237012		59608453954								1		\$3.90	F0	CVA	0064
EA				0749	60708		F237012		59051963583								5		\$6.60	F0	CVA	0064
EA				0984	60814		F237012		59608536093								1		\$9.20	F0	CVA	0064
				0373	60919		F237012			255	A	C	O1		.2	A413				D0	CVA	0064
				0274	60919		F237012			255	A	C	O1		.2	A430				D0	CVA	0064
				9280	60923		F237000			255	C	C	O1		1.0	A410				B0	CVA	0064
				0749	61029		F237012			255	H	C	O1		.2	A421				D0	CVA	0064
				0984	61107		F237012			255	A	C	O2		2.0	462				D0	CVA	0064
				1360	61107		F237012			255	A	C	O1		1.0	449				D0	CVA	0064
				7789	70403		F237012			196	D	C	O2		.5	A434				B0	CVA	0064
EA				7799	70403		F237012		59618536093								2		\$9.20	F0	CVA	0064
				7797	70404		F237012			242	C	C	O1		3.0	A430				B0	CVA	0064
EA				7797	70404		F237012		59058826380								1		\$5.70	F0	CVA	0064
				8593	70407		F237012			255	C	J	O1		2.0	449				D0	CVA	0064
EA				8593	70407		F237012		59618536093								1		\$1.90	F0	CVA	0064
				8597	70410		F237012			255	C	C	O1		.5	A429				R0	CVA	0064
EA				8597	70410		F237012		59050685919								1		\$2.00	F0	CVA	0064

BEST AVAILABLE COPY

BEST AVAILABLE COPY

MDCS GENERAL DATA RETRIEVAL

ET	DT	ADMIN	SAN	MCN	DATE	AVAIL	EIC	WC	MC	RAAN	MAL	D	A	UNIT	MNHR	SERIAL	NOVN	QUANT	LABOR	CC	HULL	NO.
PARTS	SC	UNIT	SAN	MCN	DATE	AVAIL	EIC	CG	FSN	ATSM	CID/APL/AEL	REFER.	SYM						UNPR	CC	HULL	NO.
FT				8593	70511	F237012				255	C	C	O1		.5	449						
FT				2906	70518	F237012			61451841253									800	\$1.15	F0	CVA	0064
				2906	70518	F237012			61451841253									800	\$1.15	F0	CVA	0064
EA				3932	70523	F237012				068	C	J	O1		2.0	A419		1	\$1.04	F0	CVA	0064
				3932	70523	F237012			59051908889													
EA				7611	70527	F237012				255	C	C	O1		.2	A412		1	\$1.04	F0	CVA	0064
				7611	70527	F237012			59051908889													
EA				7670	70601	F237012				255	C	C	O1		2.0	A430		1	\$1.04	F0	CVA	0064
				7665	70601	F237012				255	C	C	O1		1.0	A425						
EA				7665	70601	F237012			59618536093									1	\$1.90	F0	CVA	0064
				7677	70602	F237012				161	C	J	O1		.5	A425						
				7824	70617	F237012				160	G	C	O1		3.5	A422						
				1384	70119	F237012				068	C	J	O1		.5	A197						
				5938	70627	F237000				099	C	E	O1		.2	D-9						
				1017	70327	F237000				161	C	C	O1		1.0	B42						
				7009	70503	F237000				068	C	C	O1		2.5	936						
EA				7009	70503	F237000			59306822970									1	\$2.50	F0	CVS	0012
				7258	70516	F237000				000	O	E	O4		1.0	737						
				7258	70516	F237000				000	O	E	O4		1.0	737						
				7344	70519	F237000				127	C	E	O4		1.0	732						
				7344	70519	F237000				127	C	E	O4		1.0	732						
EA				7812	70616	F237000			59507194325									1	\$8.00	F0	CVS	0012
EA				7812	70616	F237000			59507194325									1	\$8.00	F0	CVS	0012
EA				7812	70616	F237000			59619683858									10	\$1.13	F0	CVS	0012
EA				7812	70616	F237000			59619683858									10	\$1.13	F0	CVS	0012
EA				7812	70617	F237000			59618786521									10	\$1.31	F0	CVS	0012
EA				7812	70617	F237000			59618453954									2	\$3.90	F0	CVS	0012
EA				7812	70617	F237000			59618953954									2	\$3.90	F0	CVS	0012

BEST AVAILABLE COPY

MDCS11-4-06304																				MDCS GENERAL DATA RETRIEVAL										DATE PREPARED 20 SEPT 67										PAGE 17																																							
PERIOD COVERED 01 APR 66 THRU 30 JUN 67																																																																															
ET		DT		ADMIN		SAN		MCN		DATE		AVAIL		EIC		WC		AWC		RAAN		MAL		D		A		UNIT		MHRS		SERIAL		NOUN		QUANT		LABOR		CC		HULL		NO.																																			
PARTS		SC		UNIT		SAN		MCN		DATE		AVAIL		EIC		CG		FSN		ATSM		CID/APL/AEL		REFER.		SYM																																																					
EA		7834		70617		F237000		59107173635												161		C		C		O1		26.0		D31						1		\$10.50		F0		CVS		0012																																			
EA		7834		70618		F237000		59610876047												161		C		C		O1		26.0		D31						1		\$2.25		F0		CVS		0012																																			
		7834		70619		F237000														161		C		C		O1		26.0		D31								80		CVS		0012																																					
		7834		70619		F237000														161		C		C		O1		26.0		D31								80		CVS		0012																																					
		7856		70619		F237000														161		C		C		O1		.5		D31								80		CVS		0012																																					
EA		7834		70619		F237000		59108927871																												\$6.68		F0		CVS		0012																																					
EA		7834		70619		F237000		59610876047																												\$2.25		F0		CVS		0012																																					
		7812		70621		F237000														161		C		C		O1		30.0		D31								80		CVS		0012																																					
		7950		70625		F237000														161		C		C		O1		6.0		731								80		CVS		0012																																					
EA		8753		60929		F237000		59608084741																												\$1.60		F0		CVS		0015																																					
		5973		70328		F237000														346		C		E		O1		6.5		D17UCC1V								80		CVS		0020																																					
		5974		70328		F237012														255		C		C		O2		1.5		D19UCC1V								80		CVS		0020																																					
		2124		70225		F243000														161		C		K		O1		20.0		ANUCC-1C								D0		D0		0449																																					
		2124		70310		E F237012		04637												161		C		T		O1												C0		D0		0449																																					
		2124		70318		F237012														161		C		M		O1		2.5		AN/UCC-1C								D0		D0		0449																																					
		3486		70323		F237012														068		C		C		O1		22.0		UCC1C								80		D0		0449																																					
		3487		70404		F237012														000		O		B		O1		1.7		ANUCC-1C								80		D0		0449																																					
EA		6595		70314		F237010		59359216015												58123153																\$1.30		F0		D0		0681																																					
EA		6595		70402		F237010		59359216022												58123153																\$1.30		F0		D0		0681																																					
		2962		70512		F237013														070		G		C		O1		.1		500								80		D0		0682																																					
EA		2962		70525		F237013		59205772264												61399554																\$1.10		F0		D0		0682																																					
		6423		61209		A F237000														000		O		K		O1		.2		AN-UCC-1								D1		D0		0701																																					
		6423		61209		A F237000																																		D2		D0		0701																																			
EA		6073		70317		F237010		59159200494												62981956																\$21.90		F0		D0		0717																																					
		3770		70119		F243000														000		O		K		O1		.5		A34								D1		D0		0718																																					
		3769		70119		F243000														000		O		K		O1		.5		A34								D1		D0		0718																																					
		3770		70119		F243000																																D2		D0		0718																																					

FC 2

BEST AVAILABLE COPY

NDSCS11-4-06304
PERIOD COVERED 01 APR 66 THRU 30 JUN 67

MDCS GENERAL DATA RETRIEVAL

ET DT ADMIN SAN MCN DATE AVAIL EIC MCN DATE AVAIL EIC
PARTS SC UNIT SAN MCN DATE AVAIL EIC

MDCS11-4-06304
PERIOD COVERED 01 APR 66 THRU 30 JUN 67

PAGE 19
DATE PREPARED 20 SEPT 67

ET	DT	ADMIN	SAN	MCN	DATE	AVAIL	EIC	WC	AMC	RAAN	MAL	D	A	UNIT	MNHR	SERIAL	NO.	LABOR	CC	HULL	NO.
PARTS	SC	UNIT	SAN	MCN	DATE	AVAIL	EIC	CG	FSN		ATSM	CID/APL	REFER.	SYN	QUANT			UNPR	CC	HULL	NO.
				2757	70309	F237000					458	G	D	01	2.0	A91			80	DD	0746
				2756	70309	F237000					255	C	C	03	1.0	A91			80	DD	0746
				0650	70108	F237012					346	C	C	01	.3	ANUCC1V			80	DD	0752
EA				0650	70108	F237012			59051711999			58120102			RESISTOR	8		\$.04	F0	DD	0752
				0703	70118	F237012					161	C	K	01	4.0	ANUCC1			DD	DD	0752
EA				0754	70201	F237000			59617291059						TRANSISTOR	2		\$.83	F0	DD	0752
EA				0703	70221	F237012			59608786521						2N404	2		\$.35	F0	DD	0752
				0703	70223	F237012					161	C	C	01	998.0	ANUCC1			80	DD	0752
				0703	70223	F237012					161	C	C	01	8.0	ANUCC1			DD	DD	0752
				2919	60405	F237000					255	C	D	01	1.0	A109			80	DD	0758
				4408	61121	F237000					021	C	J	01	4.0	A52			DD	DD	0758
EA				4408	70320	1	F237000		58059216020			58120230			2A11C1	8		\$9.00	F0	DD	0758
EA				4408	70324	1	F237000		58059216019			58120230			1A2A11C1	4		\$7.20	F0	DD	0758
EA				4408	70405	1	F237000		59619149034			58120230			1A2A1Q6	3		\$5.00	F0	DD	0758
				4408	70503	F237000					021	C	C	01	2.5	A52			DD	DD	0758
EA				7934	61031	F237000			59619149034			62264000			262417	10		\$5.00	F0	DD	0759
				3739	70119	F237000					000	O	J	01	1.0	A487			DD	DD	0763
				3739	70127	F237000					000	O	M	01	1.5	A487			DD	DD	0763
FT				3739	70210	1	F237000		61455537823			58123197			COAX	500		\$.23	F0	DD	0763
EA				3739	70219	1	F237000		59358146598						CONNECTOR	3		\$3.30	F0	DD	0763
EA				3739	70301	1	F237000		59358168643						CONNECTOR	2		\$5.70	F0	DD	0763
EA				3739	70301	1	F237000		59358151541						CONNECTOR	2		\$2.70	F0	DD	0763
EA				3739	70317	1	F237000		59358510221			58123197			CONNECTOR	2		\$3.00	F0	DD	0763
EA				3739	70410	1	F237000		61459132063			58123197			CABLE	100		\$.25	F0	DD	0763
EA				3739	70411	1	F237000		59358168643			58123197			CONNECTOR	3		\$5.70	F0	DD	0763

BEST AVAILABLE COPY

PAGE 20
DATE PREPARED 20 SEPT 67

MDCS GENERAL DATA RETRIEVAL

MDCS11-4-06304
PERIOD COVERED 01 APR 66 THRU 30 JUN 67

ET	DT	ADMIN	SAN	MCN	DATE	AVAIL	ETC	WC	AMC	RAAN	MAL	D	A	UNIT	MNHR	SERIAL	NOUN	QUANT	LABOR	CC	HULL	NO.
PARTS		SC	UNIT	SAN	MCN	DATE	AVAIL	ETC	CG	FSN	ATSH					REFER.	SYM		UNPR	CC	HULL	NO.
				7512	70512	F237000					127	D	E	01	8.0	A-21				80	DD	0776
				7512	70512	F237000					127	D	E	01	8.0	A-21				80	DD	0776
		FT		0300	70624	F237010			61455426910			58123153			ACPOWCABLE		50		\$1.16	F0	DD	0784
				0208	60907	E F237015			04643		117	A	O	00	21.0	TELETYPE	PETEST			80	DD	0785
				0208	60908	E F237015			04643		117	A	D	01	6.0	TELETYPE	PETEST			C0	DD	0785
				2565	70326	F237010					255	C	C	01	.5					80	DD	0787
				2898	70414	F237012					900	C	J	03	4.0	NONE				DD	DD	0787
				2969	70417	F237000					161	C	C	01	.1					80	DD	0787
		EA		2614	70424	F237015			59205772264			92232000			SF1		6		\$1.10	F0	DD	0787
				2042	70428	F237000					099	C	D	16	1.5	AN/UCC-1C				80	DD	0787
				2898	70510	F237012					900	C	C	03	.5	NONE				DD	DD	0787
		EA		2618	70511	F237010			59619149034			58123151			2N3439		4		\$5.00	F0	DD	0787
		EA		2115	70516	F237000			59202849493			58123153			FUSE		5		\$0.05	F0	DD	0787
				2283	70606	F237000					161	C	C	01	1.5	A-193				80	DD	0787
		EA		7129	70520	F237000			59352577208			62795101			CONN		1		\$5.40	F0	DD	0790
		EA		7129	70520	F237000			59356655717			62795101			CONN		1		\$4.60	F0	DD	0790
		EA		7129	70525	F237000			59351924789			62765101			JACK		1		\$4.43	F0	DD	0790
				6952	61117	F237012					127	C	H	01	12.0	A6533AN/UCC1				DD	DD	0795
		EA		2685	60412	F237000			59352592019			58123196			CONNECTOR		2		\$0.81	F0	DD	0825
		EA		1960	60425	F237000			59358151541			58123196			CONNECTOR		1		\$2.70	F0	DD	0825
		EA		1960	60518	F237000			59358151541			58123196			CONNECTOR		3		\$2.70	F0	DD	0825
				1960	60603	F237000					000	O	M	01	99.9	A59				DD	DD	0825
		EA		1960	60603	F237000			59357211081			58123196			CONNECTOR		2		\$3.00	F0	DD	0825
		EA		1960	60603	F237000			59357553809			58123196			CONNECTOR		2		\$3.60	F0	DD	0825
		EA		1960	60603	F237000			59358146598			58123196			CONNECTOR		1		\$3.30	F0	DD	0825
		EA		1960	60603	F237000			59358817775			58123196			CONNECTOR		4		\$2.40	F0	DD	0825

MODCS GENERAL DATA RETRIEVAL

MDCS11-4-06304
PERIOD COVERED 01 APR 66 THRU 30 JUN 67

ET	DT	ADMIN	SAN	MCN	DATE	AVAIL	EIC	WC	ANC	RAAN	MAL	D	A UNIT	MNHRS	SERIAL	NOUN	QUANT	LABDR	CC	HULL	NO.
PARTS		SC	UNIT	SAN	MCN	DATE	AVAIL	EIC	CG	FSN	ATSM	CID/APL/AEL			REFER.	SYM		UNPR	CC	HULL	NO.
				7112	70411	F2A2000					346	C	E	01	24.0	ANUCCIA			80	DDR	0874
				0408	60730	F237012					161	C	C	01	4.5	A-14			80	DF	1041
				6429	60811	F237010					000	O	R	01	.3	A13			80	DE	1045
				4285	70104	F237000					000	O	B	01	.1	A17			80	DEG	0001
				8507	60404	F237012					900	C	C	01	.5	ANUCCIV			80	DLG	0009
				8570	60404	F237012					196	C	C	01	.5	ANUCCIV			80	DLG	0009
EA				8507	60409	F237012			59605776085						CR5		4	\$4.45	F0	DLG	0009
				5286	60612	F237000					099	C	K	02	.5	ANUCCI SY			D0	DLG	0009
EA				6118	70215	F237012			59052793516						RESISTOR		9	\$4.04	F0	DLG	0009
				6118	70319	F237000					099	G	C	02	30.0	A173 A174			80	DLG	0009
				5286	70321	F237000					099	C	T	02		ANUCCI			D0	DLG	0009
EA				6118	70403	F237012			59618536093					62264002	TRANSISTOR		6	\$1.90	F0	DLG	0009
				6895	70105	F237000					093	K	C	01	.3	1209			80	DLG	0012
EA				6895	70109	F237000			59052792296					92600251	RESISTOR		7	\$4.13	F0	DLG	0012
				6934	70111	F237000					068	G	J	01	.5	1214			D0	DLG	0012
EA				6934	70126	F237000			59052792296					92600251	RESISTOR		5	\$4.13	F0	DLG	0012
EA				2962	70201	F237010			59358151541					58123150	CONNECTOR		6	\$2.70	F0	DLG	0012
EA				2962	70202	F237000			59350896309						CABLECLAMP		3	\$1.00	F0	DLG	0012
EA				2962	70207	F237010			59358168643						CONNECTOR		3	\$5.70	F0	DLG	0012
EA				2962	70209	F237013			59202966842						4AMPFUSES		20	\$4.21	F0	DLG	0012
EA				2962	70209	F237013			59207224894						6AMPFUSES		10	\$4.15	F0	DLG	0012
EA				2962	70209	F237013			59202850810						5AMP FUSES		25	\$4.17	F0	DLG	0012
				6934	70223	F237000					068	G	C	01	4.0	1214			D0	DLG	0012
				4187	60415	F237010					000	O	J	01	2.0	A249			00	DLG	0024
				4187	60505	F237010					000	O	M	01	40.0	A249			D0	DLG	0024

BEST AVAILABLE COPY

MDCS11-4-06304
 PERIOD COVERED 01 APR 66 THRU 30 JUN 67
 ET DT ADMIN SAN MCN DATE AVAIL EIC WC AWC RAAN MAL D A UNIT MMHRS SERIAL NOUN
 PARTS SC UNIT SAN MCN DATE AVAIL EIC CG FSN ATSM CID/APL/AEL REFER. SYM QUANT
 MDCS GENERAL DATA RETRIEVAL
 DATE PREPARED 20 SEPT 67
 LABOR CC HULL NO.
 UNPR CC HULL NO.

EA	4187	60505	F237010	59358151541					J4	2	\$2.30	F0	DLG	0024
EA	4187	60505	F237010	59358146598					J1	1	\$3.30	F0	DLG	0024
EA	4187	60505	F237010	59357553804					J8	2	\$3.60	F0	DLG	0024
EA	4819	70317	F2A3000	59617526081			58123153		1A2A1Q6	6	\$-.89	F0	DLG	0024
	4819	70318	F2A3000						2.5 ULC NRI			B0	DLG	0024
	5394	70531	F2A3000				080 C C 05		1.0 A-249			D1	DLG	0024
	5394	70531	F2A3000				000 O H 01					D2	DLG	0024
							FC-3							
EA	3428	60425	F237000	59351924758			58123196		PJ-C478	10	\$-.61	F0	DLG	0026
	3428	60426	F237000				000 O C 01		2.0 A2 AN-UCC-1			D0	DLG	0026
	0902	60925 A	F237000				099 E K 01		.5 A82			D0	DLG	0028
	0902	70315	F237000				099 E C 01		20.0 A82			D0	DLG	0028
EA	4091	70228	F237013	59352593608			62765101		JACK	1	\$5.40	F0	LPD	0005
	4107	70304	F237012				458 C E 03		9.0 ANUCCIV			B0	LPD	0005
EA	4280	70419	F237013	59352593608			62765101		JACK	1	\$5.40	F0	LPD	0005
EA	4279	70419	F237013	59350793487			62765101		1XA1	1	\$3.00	F0	LPD	0005
EA	4280	70607	F237013	58158876504			61600033		INSULATOR	1	\$1.92	F0	LPD	0005
	2009	70406	F237000				161 C J 01		.5 A28			D0	LPD	0006
	2055	70428	F237000				099 K P 01		.2 A28ANUCCICV			B0	LPD	0006
EA	2015	70518	F2A3000	59550603278			85912101		CRYSTAL	1	\$17.00	F0	LPD	0006
	2216	70611	F237000				161 C C 01		1.0 A28			B0	LPD	0006
	5512	70525	F237012				450 D C 01		2.5 ANGCCIV1274			B0	LPD	0002
	5559	70608	F237012				127 G C 01		11.5 ANUCC10001274			B0	LPD	0002
	5489	60920	F237000				000 O M 01		36.0 A101			D0	LPD	0003
	5489	61106	F237000				000 O M 01		90.0 A101			D0	LPD	0003
	8734	61204	F237015				000 O H 01		.1 8244			D1	LPD	0003

BEST AVAILABLE COPY

MDCS11-4-06304
PERIOD COVERED 01 APR 66 THRU 30 JUN 67

ET DT ADMIN SAN MCN DATE AVAIL EIC MC AWC RAAN MAL D A UNIT MNHRS SERIAL NOUN
PARTS SC UNIT SAN MCN DATE AVAIL EIC CG FSN ATSM CID/APL/AEL REFER. SYM QUANT

MDCS GENERAL DATA RETRIEVAL

PAGE 24
DATE PREPARED 20 SEPT 67

ET	DT	ADMIN	SAN	MCN	DATE AVAIL	EIC	MC	AWC	RAAN	MAL	D	A UNIT	MNHRS	SERIAL	NOUN	LABOR UNPR	CC	HULL NO.
8735	61204				F237013				000	O	H	O1	.1	B244		D1	LPH	0003
8734	61204				F237015											D2	LPH	0003
8735	61204				F237013											D2	LPH	0003
8734	70214				F237015				000	O	G	O1	.2	B244		D1	LPH	0003
8735	70214				F237013				000	O	G	O1	.5	B244		D1	LPH	0003
8734	70214				F237015											D2	LPH	0003
8735	70214				F237013											D2	LPH	0003
0963	70614				F237012				346	C	K	O1	5.0	A-39		D0	LPH	0003
0963	70623				F237012				346	C	E	O1	24.0	A-39		B0	LPH	0003
0963	70623				F237012				346	C	E	O1	4.0	A-39		D0	LPH	0003
2456	70610				F237012				068	A	D	O1	1.5	A63		B0	LPH	0010
3421	70520				F237000				346	C	D	O1	3.0	A119		D0	LSD	0017
1462	70527				F237000				000	O	H	O2	.2	AN UCC	ICV	D1	LSMR	0525
1462	70527				F237000											D2	LSMR	0525

FC AN/UCC-ICV-

APPENDIX F
COMPUTER PRINTOUT OF STATISTICAL TESTS

BEST AVAILABLE COPY

ANALYSIS OF RELIABILITY DATA THE AN/UCC-1 NETWORK SYSTEM ABOARD THE USS TOPEKA

NON PARAMETRIC RELIABILITY FUNCTION

INTERVAL	NO. AT START	NO. FAIL	NO. TERM.	REL. AT END OF INT.
0.00 --	60	9	0	0.852459
0.50 --	51	2	1	0.819672
1.00 --	48	4	0	0.752760
2.00 --	44	3	1	0.702576
3.00 --	40	2	0	0.668304
4.00 --	38	2	2	0.634032
5.00 --	34	5	2	0.543456
7.50 --	27	1	2	0.524047
10.00 --	24	0	3	0.524047
15.00 --	21	3	0	0.452586
20.00 --	18	11	0	0.190563
25.00 --	7	3	0	0.119102
30.00 --	4	1	0	0.095282
40.00 --	3	1	0	0.071461
50.00 --	2	0	1	0.071461
75.00 --	1	1	0	0.035731

BEST AVAILABLE COPY

TEST HYPOTHESIS-DATA EXPONENTIAL

MTBSO IS 17.54

TIME	EFFECTIVE SAMPLE SIZE	ALLOWED DEVIATION	NON-PAR. FCN.	THEOR. FCN.
0.50	60	0.1381	0.852459	0.971899
1.00	51	0.1498	0.819672	0.944587
2.00	48	0.1544	0.752760	0.892245
3.00	44	0.1613	0.702576	0.842804
4.00	40	0.1692	0.668304	0.796102
5.00	38	0.1736	0.634032	0.751988
7.50	34	0.1835	0.543456	0.652103
10.00	27	0.2059	0.524047	0.565486
15.00	24	0.2184	0.524047	0.425238
20.00	21	0.2335	0.452586	0.319774
25.00	18	0.2522	0.190563	0.240466
30.00	7	0.4044	0.119102	0.180828
40.00	4	0.5350	0.095282	0.102256
50.00	3	0.6178	0.071461	0.057824
75.00	2	0.7566	0.071461	0.013905
200.00	1	1.0700	0.035731	0.000011

CANNOT
REJECT HYPOTHESIS AT 20% SIGNIFICANCE

BEST AVAILABLE COPY

ANALYSIS OF RELIABILITY DATA						
THE AN/UCC-1C NETWORK SYSTEM ABOARD THE USS CAVALIER						
NON PARAMETRIC RELIABILITY FUNCTION						
INTERVAL	NO. AT START	NO. FAIL	NO. TERM.	REL. AT END OF INT.		
0.00 --	0.50	22	1	0	0.956522	
0.50 --	1.00	21	0	0	0.956522	
1.00 --	2.00	21	0	0	0.956522	
2.00 --	3.00	21	1	0	0.913043	
3.00 --	4.00	20	1	0	0.869565	
4.00 --	5.00	19	2	0	0.782609	
5.00 --	7.50	17	1	0	0.739130	
7.50 --	10.00	16	0	1	0.739130	
10.00 --	15.00	15	2	0	0.646739	
15.00 --	20.00	13	1	2	0.600543	
20.00 --	25.00	10	2	1	0.491353	
25.00 --	30.00	7	2	0	0.368515	
30.00 --	40.00	5	1	0	0.307096	
40.00 --	50.00	4	1	2	0.245677	
50.00 --	75.00	1	1	0	0.122839	

BEST AVAILABLE COPY

TEST HYPOTHESIS-DATA EXPONENTIAL

MTBSO IS 29.83

TIME	EFFECTIVE SAMPLE SIZE	ALLOWED DEVIATION	NON-PAR. FCN.	THEOR. FCN.
0.50	21	0.2281	0.956522	0.983377
1.00	21	0.2335	0.956522	0.967030
2.00	21	0.2335	0.956522	0.935148
3.00	21	0.2335	0.913043	0.904316
4.00	20	0.2393	0.869565	0.874501
5.00	19	0.2455	0.782609	0.845669
7.50	17	0.2595	0.739130	0.777680
10.00	16	0.2675	0.739130	0.715156
15.00	15	0.2763	0.646739	0.604785
20.00	13	0.2968	0.600543	0.511448
25.00	10	0.3384	0.491353	0.432516
30.00	7	0.4044	0.368515	0.365765
40.00	5	0.4785	0.307096	0.261579
50.00	4	0.5350	0.245677	0.187070
75.00	1	1.0700	0.122839	0.080911

CANNOT
REJECT HYPOTHESIS AT 20% SIGNIFICANCE

BEST AVAILABLE COPY

ANALYSIS OF RELIABILITY DATA
THE AN/UCC-1C NETWORK SYSTEM ABOARD THE USS TOPEKA

NON PARAMETRIC RELIABILITY FUNCTION

INTERVAL	NO. AT START	NO. FAIL	NO. TERM.	REL. AT END OF INT.
0.00 --	54	4	0	0.927273
0.50 --	50	5	1	0.836364
1.00 --	44	5	1	0.743435
2.00 --	38	3	2	0.686248
3.00 --	33	1	0	0.666064
4.00 --	32	2	1	0.625697
5.00 --	29	4	1	0.542271
7.50 --	24	3	1	0.477198
10.00 --	20	2	0	0.431751
15.00 --	18	1	0	0.409027
20.00 --	17	6	2	0.272685
25.00 --	9	4	0	0.163611
30.00 --	5	1	1	0.136342
40.00 --	3	1	0	0.102257
50.00 --	2	1	1	0.068171

BEST AVAILABLE COPY

TEST HYPOTHESIS-DATA EXPONENTIAL

MTBSO IS 15.95

TIME	EFFECTIVE SAMPLE SIZE	ALLOWED DEVIATION	NON-PAR. FCN.	THEOR. FCN.
0.50	54	0.1456	0.927273	0.969134
1.00	50	0.1513	0.836364	0.939221
2.00	44	0.1613	0.743435	0.882135
3.00	38	0.1736	0.686248	0.828520
4.00	33	0.1863	0.666064	0.778163
5.00	32	0.1892	0.625697	0.730866
7.50	29	0.1987	0.542271	0.624823
10.00	24	0.2184	0.477198	0.534165
15.00	20	0.2393	0.431751	0.390403
20.00	18	0.2522	0.409027	0.285333
25.00	17	0.2595	0.272685	0.208540
30.00	9	0.3567	0.163611	0.152415
40.00	5	0.4785	0.136342	0.081415
50.00	3	0.6178	0.102257	0.043489
75.00	2	0.7566	0.068171	0.009069

CANNOT
REJECT HYPOTHESIS AT 20% SIGNIFICANCE

APPENDIX G
INSTALLATION COST DATA



LONG BEACH NAVAL SHIPYARD
LONG BEACH 2, CALIFORNIA

IN REPLY REFER TO:

14 July 1967

ARINC Research Corporation
2551 Riva Road
Annapolis, Maryland 21401

ATTN: Mr. W. C. Duke

Gentlemen:

During a recent visit to this shipyard by Mr. Ralph All and Mr. Mohammed Yahya Rawasia, cost effectiveness evaluation of UCC-1(V) and UCC-1C(V) teletype terminal equipment was discussed with our Mr. William Schneider. The installation of UCC-1 aboard the USS CAVALIER was selected as a typical installation for costs as shown in enclosure (1).

In accordance with agreement with your Mr. All, data requested by your letter of June 8 was provided by Code 234 and is forwarded as enclosures (1) and (2). If Code 234 can be of any additional assistance do not hesitate to let them know.

E. L. Martin
E. L. MARTIN

Encl:

- (1) Installation Costs
- (2) Associated Drawings (2 copies)

1. Labor Costs

a. Civilian Personnel

Shop test AN/UCC-1 Equip & prepare for installation	24 M/H	
Fabricate & install fdn aboard ship	38 M/H	
or		
Fabricate mounting kits & install in 19" cabinet		
Shipboard installation of AN/UCC-1 Equip	81 M/H	
Install cable, connect, cold wire check and final tests, check-out of installation (includes Quality Assurance services)		
Total labor costs @ 8.50 hour	143 M/H	\$ 1,216

b. Contractor engineer services Not Used

c. MOTU Services Not Used

Primary function of MOTU is to
provide Technical Services to
Forces Afloat when requested for
ship not assigned availability at
a Naval Shipyard

2. Material Costs

Material used for equipment preparation and bonding (plugs - misc elex mat - bond mat)	\$ 116
Material used for equipment installation (cable - mtg hardware- insulation - rubber matting)	100
Material for foundations or mounting kit	30
	—
Total material	\$ 246

3. Transportation by commercial carriers from storage area to ship None

4. Other costs (Ship structure mods) None

Enclosure (1)